



Service Bulletin

Bulletin No.: PIT6439

Date: September, 2025

PRELIMINARY INFORMATION

Subject: Turn Signal Over Cancel

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox EV	2025-2026		All	All	All	All

Involved Region or Country	United States, Canada, Mexico, Middle East, Israel, Palestine, Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West), Japan
Condition	Customer may comment that their turn signal is over cancelling. May be consistent or intermittent condition.
Cause	Issue may be due to faulty turn signal switch.

Correction

First, perform TSB 24-NA-176 and if re-programming the BCM does not resolve the concern, remove steering wheel column shroud and check for any loose or broken components. If no issues are found, then proceed to replace the turn signal switch.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation.

Labor Operation	Description	Labor Time
7442380	Turn Signal Switch Replacement	Use Published Time

Version	1
Modified	09/30/2025 Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.