

ATTENTION: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers & Parts Managers

Service Campaign Notification

October 3, 2025

Replace TIREFIT Bottle in Trunk

Campaign #

Description

2025090001

25P5898016

Campaign Details

Total Population	5,734	Model(s)/ Platform(s)	C-Class, CLA, CLE, E-Class, GLA, GLB, and GLC (206, 118, 236, 214, 247, and 254 platform)
Model Year(s)	2025		
Issue	Mercedes-Benz AG, the manufacturer of Mercedes-Benz vehicles, has determined that on certain subject vehicles, the TIREFIT sealant bottle may not meet specifications. The possibility exists that the sealant bottle may leak or may have been removed from the vehicle.		
Remedy	MBUSA will conduct a service campaign. An authorized Mercedes-Benz dealer will replace or install the TIREFIT bottle in the trunk.		
Launch Date	Affected VINs will be flagged as "OPEN" in VMI on Friday, October 3, 2025.		
Warranty Claim Notice	Please note the campaign will close after the warranty claim has been submitted. This change can take at least one-day to reflect in NetStar VMI.		

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Care Center at 1-800-FOR-MERCEDES.



Service Campaign Bulletin



Mercedes-Benz

October 2025

TO: ALL MERCEDES-BENZ CENTERS

CAMPAIGN NO.	2025090001
CAMPAIGN DESC.	25P5898016
SUBJECT	Replace TIREFIT Bottle in Trunk
MODEL(S)	C-Class, CLA, CLE, E-Class, GLA/GLB, and GLC (206, 118, 236, 214, 247, and 254 platform)
MODEL YEAR(S)	2025
CAMPAIGN POPULATION	5,734

Campaign Technical Instructions

Prior to performing this Campaign:

Check the Vehicle Master Inquiry (VMI) to verify this campaign applies to the specific vehicle.

Always check for other open campaigns and perform them accordingly!

Review the entire campaign bulletin first, and perform the procedures exactly as described.

Order No. P-SC-2025090001

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Primary Parts Information

Qty.	Part Name	Part Number
As required (1)	Tire sealant bottle including hose (Models: 118, 177, 243, 247)	A 000 583 75 05 28
As required (1)	Tire sealant bottle including hose (Models: 206, 214, 236, 254)	A 000 583 76 05 28

i Small parts such as screws, lock nuts, sealing rings, cable ties, fluids, sealant, etc. are not listed in the parts list. The required small parts are taken into account in the budgeting.

Work Procedure

- Remove TIREFIT tire sealant bottle from vehicle.
 - i** For basic data, see **AP40.10-P-4054R**.
- Clean contaminated surfaces and objects so they are free of residue.
 - i** Replace any components that cannot be cleaned.
 - i** Capture pictures of components that cannot be cleaned and submit with warranty claim.
- Insert new TIREFIT tire sealant bottle in vehicle holder.

Warranty Information

i **Note:** The following allowable labor operation should be used when submitting a warranty claim for this repair:

Damage Code	Operation Number	Description	Labor Time (hrs.)
58 980 16	11-0010	Replace TIREFIT tire sealant bottle	0.1
	11-0011	Perform cleaning in trunk (after check) Includes: Replace components as needed	ZM

i **Note:** Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.