

UPDATE DELIVERY STOP: STOP320007 – M 1000 R and XR Steering Damper Analysis

Updated 9/11/25

We are pleased to inform you that the delivery stop for the M 1000 R and M 1000 XR STOP320007 has been officially lifted.

The delivery stop was issued as a precaution following a single field case with a failed steering damper. To exclude a possible systematic root cause, intensive analyses and tests were performed and concluded successfully. It has been confirmed that the field incident was a singular occurrence. Therefore, the stop has been lifted today without any technical measure.

Thank you for your patience and cooperation during the analysis process.

Updated 8-26-2025

BMW announced a delivery stop STOP320007 For M 1000 R and M 1000 XR models, new and pre-owned, in dealer inventory.

BMW is conducting an analysis of the steering damper quality to safeguard quality.

Until further information is gathered, vehicles marked with delivery stop STOP320007 cannot be delivered to customers.

Note: Vehicles previously retailed are not subject to this delivery stop but may have STOP320007 show up in WVI and AIR.

The investigation into the root cause and affected units is ongoing. We expect to have more information early in September and will communicate more details as soon as these become available.