



SSM 54284 2025 F-150 - Tremor/Raptor - Auxiliary/Upfitter Switches No Longer Equipped With Rubber Tips

Some 2025 F-150 Tremor and Raptor vehicles may be equipped with auxiliary/upfitter switches that do not have rubber tips. Switches no longer equipped with rubber tips is an appearance only change and has no impact on function or performance. Repair or replacement for auxiliary/upfitter switches no longer equipped with rubber tips should not be performed and is not warrantable.