



Thor Motor Coach Technical Service Bulletin

TSB #	TSB 25-06		
Description/Title:	Tire PSI Typographical error on Fed Tag		
Affected Product Line(s):	Certain MY 2026 Omni & Magnitude		
Service Campaign # :	RC000334		
Codes:	Inspect with Repair: TMCTS10125W	Document Date:	10/14/2025
Time Allowed:	Inspect with Repair: 0.1	Document Revision:	A

Issue:


There is a typographical error on the Federal ID Tag with regards to the PSI of the rear tires.

Part(s) Required:

New Federal ID Tag (“tag”) provided with Owner notification letter.

Instructions:

1. Locate the existing tag. It can be found in the driver’s cockpit threshold. **Sample tag:**





2. Make sure the existing tag is free of dirt, debris, or any other substance that might interfere with the adhesive on the new tag.
3. Apply the new tag over the existing tag.