



Service Bulletin

Bulletin No.: PIT6440

Date: October, 2025

PRELIMINARY INFORMATION

Subject: Vehicle Returns To Transport Mode After An Ignition Cycle

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
ALL	ALL	2020 – 2026		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Vehicle Returns To Transport Mode After An Ignition Cycle.
Cause	Engineering is currently investigating the reported concern.

Correction

For unsold vehicles, no action is required. Once vehicle is delivered and OnStar® Blue Button call is completed, device registration will resolve the issue.

For customer owned vehicles, press the OnStar® Blue Button and ask advisor to complete unit configuration.

Version	1
Modified	10/03/2025 Created on.

