

[📎 25-01-050H-1 - Walk-in Switch Inspection & Replacement \(Campaign TEC\)\\_\(posted 10.23.25\).pdf](#)

## **Hyundai Motor America (HMA) has re-launched Service Campaign TEC – Walk-in Switch Inspection & Replacement!**

### **Revision (reflected on TSB 25-01-050H-1):**

- To revise the service procedure with a new inspection method.

### **A. Affected Vehicles (Certain):**

- 2026MY IONIQ 9 (ME1A EV) produced from 03/03/2025 – 06/24/2025

- VIN Identification: Use the 'Vehicle Information' screen in WebDCS under the 'Campaign Not Performed' section to determine campaign applicability.

### **B. Campaign Description:**

Certain IONIQ 9 (ME1A EV) vehicles may have walk-in switches that are not fully secured. **Technical Service Bulletin (TSB) 25-01-050H-1** provides instructions to inspect and, if necessary, replace the walk-in switch.

### **C. Campaign Document(s):**

**1) [Technical Service Bulletin \(TSB\) 25-01-050H-1; Supersedes TSB 25-01-050H](#)**

- Available on [Hyundaidealer.com](http://Hyundaidealer.com) > Service > HMA Tech Info > Campaign

### **D. Parts Ordering/Information:**

1. If applicable, order the part if the vehicle fails the inspection.
  - a) Ordering of a part can be completed through the normal WebDCS ordering.
  - b) Verify the correct part number for the affected vehicle by referencing the parts catalog.

### **E. Action Required:**

- 1) Confirm VIN eligibility for campaign via WebDCS.
- 2) **Follow TSB 25-01-050H-1** for service procedure & order necessary part for the vehicle if the inspection does not pass.
- 3) **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Warranty Campaign Team  
Hyundai Motor America