

Technical Service Bulletin (TSB)
Security Gateway Module (SGW) Software Update

REFERENCE:	TSB: 08-327-25 REV. B GROUP: 08 - Electrical	Date:	October 21, 2025	REVISION:	08-327-25 REV. A
VEHICLES AFFECTED:	2025 (D2) RAM 3500 Pickup			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North and South America markets.	
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: <ul style="list-style-type: none"> • SGW module is not responding to diagnostics and showing offline. • If message for FOTA appears, then a manual flash is required for SGW update. • Diagnostic Trouble Code (DTC) U3033 - 00 Control module security certificate Missing/Invalid is active or stored and cannot clear. This DTC will not turn on the Malfunction Indicator Light (MIL). 				
CAUSE:	SGW Software Flash				

This bulletin supersedes Technical Service Bulletin (TSB) 08-327-25 REV. A, date of issue October 18, 2025, which should be removed from your files. All revisions not highlighted with **asterisks**** include a TSB number correction.**

NOTE: This service action is canceled. In the event the customer reports an applicable symptom/condition, please follow published service information to diagnose and repair.

POLICY:

Information Only.