



# Service Bulletin


Bulletin No.: PIC6625

Date: October, 2025

## PRELIMINARY INFORMATION

**Subject: Interior View Camera - Currently Not Turned On**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CELESTIQ	2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Condition</b>	<p>Some clients may comment about the B350B Interior View Camera (located in the roof console) being inoperative.</p>  <p style="text-align: right;">7010707</p> <p>Some technicians may find the shielded coax cable going to the B350B Interior View Camera disconnected from the backside of the A11 Radio. Some technicians may further find the cable has been intentionally taped off.</p>



7011541

<b>Cause</b>	The Interior View Camera feature is not currently enabled and therefore intentionally disconnected for safety and security.
--------------	---

**Correction**

In the meantime, please advise the customer they may continue to drive the vehicle.

The current concern may be a potential customer dissatisfier, but it is not a Safety Issue and does not create a substantial loss of use or value.

The PI will be updated or replaced with a TSB should the feature be enabled for MY25 vehicles in the future, The bulletin will be issued to direct any required hardware updates, camera reconnection, and associated software updates.

<b>Version</b>	1
<b>Modified</b>	10/20/2025 Created on.

