



SIB 61 10 25

SERVICE ACTION: Software Update R 1300 RT-P  
2025-10-31

## MODEL

Model	Model Description
KA3	R 1300 RT-P

The vehicles affected have been marked with campaign number **0061710000** in AIR.

In order to determine if a specific motorcycle is affected by this campaign, it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

## SITUATION

Center stands assist does not function on vehicles with center stand and standard chassis (meaning without option 22B – Dynamic chassis Adaption), due to a faulty coding.

Note: the center stand can still be operated manually.

The affected motorcycles have been placed under the delivery stop **STOP610029** associated with campaign number 0061710000, which will be lifted upon completion of this technical campaign.

For vehicles that have not yet been delivered, the service action must be completed before vehicle handover. If the service action cannot be completed due to a parts, software, or special tool shortage, the service action then must be performed during the next possible workshop visit when parts, software, or special tools become available. In such instances where work cannot be performed, it is essential to inform the customer of the situation.


In all instances in which the vehicles have already been handed over to customers, the Technical Campaign must be carried out at the next workshop visit.

## PROCEDURE

The software version of the motorcycle must be updated.

ISTA Version 4.56.2X or newer must be used and should be released in the coming weeks.

Motorcycle must be programmed to I-Level X001-25-11-500 or newer via repair instruction “61 00 510 – Programming Vehicle Control Units”.



## CLAIM INFORMATION

Please submit claims via the normal claim process using the information below:

### Defect code

00 61 71 00 00	Update Software
----------------	-----------------

### Labor Operation

00 60 426	Technical campaign standard 3	5 FRU
+00 60 926	Technical campaign standard 3	4 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 00 60 426 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

NOTE: If multiple campaigns pertain to a software update, the software update shall be claimable only once, as the motorcycle will already have been brought to the requisite software level applicable to any subsequent campaigns necessitating the same software version.

## QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Powered by [Froala Editor](#)

### Supporting Materials

[picture\\_as\\_pdf 61 10 25 - SA Software Update R 1300 RT-P.pdf](#)

