



Service Bulletin

Bulletin No.: PIT6447

Date: October, 2025

PRELIMINARY INFORMATION

Subject: Forward Collision System Unavailable DTC U0140 B1A05

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Tahoe PPV	2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	9C1
Condition	When taking the vehicle out of transportation mode a dealer may find a "Forward Collision System Unavailable" message along with one or both active DTCs: U0140 Front View Camera – Windshield - Lost Communication with Body Control Module B1A05 Front View Camera – Windshield - Missing Calibration
Cause	Software

Correction

Using TLC/SPS2 reprogram the B174W Front View Camera - Windshield.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810835	Front View Camera Reprogramming with SPS	Use the published labor time

Version	1
Modified	10/30/2025 Created on

