



# Service Bulletin

Bulletin No.: PIC6615A

Date: October, 2025

## PRELIMINARY INFORMATION

**Subject:** Mirror Puddle Lamps Inoperative

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT5	2025		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	DMB, DWR, or DXR
<b>Condition</b>	A customer may comment that the Mirror Puddle Lamps are inoperative.
<b>Cause</b>	Body Control Module calibrations.

### Correction

Reprogram the Body Control Module.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Time

<b>Version</b>	2
<b>Modified</b>	07/30/2025 - Created on 10/23/2025 - Updated the cause, correction and warranty sections.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.