



Service Bulletin

Bulletin No.: PIP6090

Date: October, 2025

PRELIMINARY INFORMATION

Subject: 6.6 L5P DTC P0381

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500	2024-2025		All	All	6.6 L5P	All
Chevrolet	Silverado 3500	2024-2025		All	All	6.6 L5P	All
GMC	Sierra 2500	2024-2025		All	All	6.6 L5P	All
GMC	Sierra 3500	2024-2025		All	All	6.6 L5P	All

Involved Region or Country	North America. Israel, Palestine, Middle East
Condition	A customer may comment of a Check Engine Light (CEL) illuminated. When checking for DTCs a P0381 will be set in the ECM.
Cause	Engineering is currently investigating this issue.

Correction

Clear the DTC using the scan tool and return the vehicle to the customer.

If the DTC resets and the customer returns, refer to Service Information (SI).

Engineering is currently investigating this issue. In the meantime, the customer may continue to drive the vehicle. The PI will be updated or replaced with TSB once a determination has been made

Version	1
Modified	10/30/2025 - Created on.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.