



Countries: CANADA, UNITED STATES Document ID: IK0400173
 Availability: ISIS, NotSIR Revision: 0
 Major System: BRAKES Created: 9/30/2025
 Current Language: English Last Modified: 10/9/2025
 Other Languages: NONE Author: Eric Waller
 Viewed: 51

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 1	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: Hill Hold Assist FSC 25203 Supporting Article

Applies To: Electric MV Hill Hold Assist

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

Initial article release 10/2/2025

DESCRIPTION

This document will guide the user through the Hill Hold Assist Vin list to replace the Bendix blank ECUs

SYMPTOMS

DTC/Light	Description
N/A	N/A

SPECIAL TOOLS / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A	N/A	N/A	N/A

SERVICE PARTS INFORMATION

Kit Description	Part Number	Qty. Required	Notes
N/A	N/A	N/A	N/A
N/A	N/A	N/A	N/A

DIAGNOSTIC STEPS

N/A

REPAIR STEPS

1. Refer to the VIN list below to verify if the ABS ECU needs to be replaced.
2. Use control + F on your keyboard, then search the last 8 of your VIN to see if the ABS ECU needs to be replaced.

VIN list for Hill Hold Assist ABS ECU Swap

--

3HAFFE2N7ML424326
3HAFFE2N0ML424331
3HAFFE2N2NL424333
3HAFFE2N3NL433185
3HAFFE2L4NL553723
3HAFFE2L1NL553775
3HAFFE2L5NL553777
3HAFFE2L2NL553848
3HAFFE2N1PL004064
3HAFFE2L5PL281427
3HAFFE2L7PL450542
3HAFFE2N3PL515629
3HAFFE2NXPL649179
3HAFFE2N1PL649183
3HAFFE2N3PL649184
3HAFFE2N5PL649185
3HAFFE2N6PL743589
3HAFFE2L3PL787340
3HAFFE2N6RL203792
3HAFFE2N5RL252949
3HAFFE2N9RL730399
3HAFFE2N0SL153459
3HAFFE2NXSL375846
3HAFFE2N3SL744126
3HAFFE2N5NL159049
3HAFFE2N1NL433170
3HAFFE2N5NL433172
3HAFFE2N7NL433173
3HAFFE2N0PL528726
3HAFFE2N7PL021015
3HAFFE2L4PL040085
3HAFFE2NXPL263152
3HAFFE2N7PL791361
3HAFFE2N0PL791363
3HAFFE2N1PL507478
3HAFFE2N2PL512107
3HAFFE2L5PL668155
3HAFFE2N7PL791358
3HAFFE2N5PL608281
3HAFFE2N3PL791356
3HAFFE2NXPL281148
3HAFFE2NXPL746463
3HAFFE2L3PL669790
3HAFFE2N1PL373474
3HAFFE2N9RL605208

3HAFFE2N4PL512108
 3HAFFE2N5PL791360
 3HAFFE2L1PL140175
 3HAFFE2L9PL669793
 3HAFFE2N6PL512109
 3HAFFE2N0RL412588
 3HAFFE2L7PL202694
 3HAFFE2N1PL161416
 3HAFFE2L7RL643728
 3HAFFE2L2PL520125
 3HAFFE2N9PL161633
 3HAFFE2N2RL605213
 3HAFFE2N2RL512112
 3HAFFE2N7RL875845
 3HAFFE2NXRL788313
 3HAFFE2N1PL746464
 3HAFFE2N7RL605207
 3HAFFE2L8PL792758
 3HAFFE2N8RL015758
 3HAFFE2NXRL512116
 3HAFFE2L0RL692382
 3HAFFE2L2RL692433
 3HAFFE2L3RL692439
 3HAFFE2N2PL489878
 3HAFFE2N7RL605210
 3HAFFE2N0RL605209
 3HAFFE2L6RL479419
 3HAFFE2L2RL479420
 3HAFFE2LXPL138571
 3HAFFE2N7RL519024
 3HAFFE2N8RL788309
 3HAFFE2N1RL788314
 3HAFFE2N0PL161634
 3HAFFE2N7PL489875
 3HAFFE2N9PL489876
 3HAFFE2N3PL865729
 3HAFFE2N8SL792429
 3HAFFE2N1SL788304
 3HAFFE2N6SL792431
 3HAFFE2N0RL792418
 3HAFFE2N3PL489873
 3HAFFE2N0RL512111
 3HAFFE2N1SL262688
 3HAFFE2N7RL607474
 3HAFFE2N6RL788308
 3HAFFE2N3RL164188
 3HAFFE2L5RL632579
 3HAFFE2N9SL699550
 3HAFFE2N1SL470456
 3HAFFE2L6PL194426
 3HAFFE2L6PL128278

3. IF needed replace the ABS ECU per FSC instructions 25203.

WARRANTY INFORMATION

Repair	SRT	Hrs
N/A	N/A	N/A

ADMINISTRATIVE PROCEDURE

Expense is to be charged to Warranty. Claims are to be submitted in the normal manner, making reference to Proactive Field Change Number.

It is important that the coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Policy Manual, Section 10.

As with all claim submissions, items acquired locally must be submitted in the Other Charges tab. The cost of any bulk items (such as a bag of cable tie straps, roll of wire, barrel of oil, or tube of silicone) should be prorated for the cost of the individual pieces / amount used during each repair.

Sales Policy repairs have a 10% markup on parts


To ensure this important improvement is made in a timely manner, all claims for this Proactive Field Change Number must be submitted within 12 months from the release of this document or within the normal warranty period for the vehicle, if after 12 months from the release date

	GROUP	NOUN	C	WARR.	TP	PAD
GROUP Enter number G--						
NOUN Leave blank						
C (CAUSE) Enter either 1, 2, 3. (see below)						
1. Inspected (No repair required).						
2. Inspected and repaired.						
3. Defective part from parts stock.						
WARRANTY (Warranty Code) Enter 40.						
TYPE PART Enter P for type part causing failure.						
PAD Enter 100						

If a feedback case is required, please select feedback type as 600/MRC/FSC and case type as feedback. This will ensure the case file goes to the correct correspondents

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed:	50
Helpful:	1
Not Helpful:	0

No Feedback Found