

# TSBs 54-375 FTL and 54-100 WST

## Removing Odometer Pause Wiring Modifications

## TSB-54-375-FTL

---

Creation Date: 2025-08-20

---

### Engine or Vehicle Affected:

- ▶ Business Class M2-Plus
  - ▶ 108SD Plus/114SD Plus
- 

This is an informational bulletin only. The described condition is a product improvement and is not warrantable.

### Described Condition

For vehicles with Common Powertrain Controller (CPC5) software installed prior to January 9, 2024, hardware and software modifications were necessary to allow vehicle speed and mileage sensors to be ignored during split shaft Power Takeoff (PTO) operations. This bulletin applies to Freightliner and Western Star vehicles equipped with Detroit® engines and the CEEA+ architecture.