

# Wiring/Airing Routing and Clipping

## Problem Description

- Many customer/dealer complaints for poor routing of airlines and wire harnesses causing rubs and premature failures/breakdowns.

## Affected Models

- All



## Root Cause

- Plants not following guidelines in K09-S0000-018 & K09-S0003-009 WIs

## Containment

- TBD

## Containment Date

- TBD

## Countermeasure

- TBD

## Countermeasure Date

- TBD

## Important Notes

- These complaints are consistent with plants not following routing and clipping guidelines.