



<b>Subject:</b> <b>TRUNK LID UNLOCKING OPERATION CHANGE AFTER DYNAMIC STABILITY CONTROL (DSC) REPLACEMENT</b>	<b>Service Alert No.: SA-048/25</b>
	<b>Last Issued : 10/14/2025</b>

## BULLETIN NOTES

### APPLICABLE MODEL(S)/VINS

2024-2025 MX-5 vehicles with Advanced Keyless Entry System with VINs lower than JM1 ND\*\*\*\* \*\* 654801 (Produced before Feb. 28, 2025)


## DESCRIPTION

To improved customer experience, an operational modification has been made to unlock the trunk lid after Dynamic Stability Control (DSC) replacement. Be sure to explain the following unlock operational modification to affected customers.

### Trunk Lid Unlocking Operational Modification:

- After the engine is turned off and the vehicle remains inactive for more than 5 minutes (sleep mode), it was necessary to operate the electric trunk lid opener switch **twice** to unlock the trunk lid.
- After replacing the Dynamic Stability Control (DSC) with a newly modified part, the trunk lid is unlocked with a **single** operation, as described in the owner's manual.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



**Using the electric trunk opener (with the remote release button):**

- Trunk lid can also be opened while the key is being carried.
- Press the electric trunk lid opener and raise the trunk lid when the latch releases.

**Using the electric trunk opener (without the remote release button):**

- Unlock the doors and trunk lid, then press the electric trunk lid opener and raise it when the latch releases.

**DSC Replacement and Trunk Lid Opener Switch Operation:**

	Switch Operation in Sleep Mode	Switch Operation <b>NOT</b> in Sleep Mode
Before DSC replacement	Twice	Once
After DSC replacement	Once	Once

**NOTE:** If not already completed, be sure to perform the related campaign (Recall 7425E) according to the instructions on MGSS:

Recall 7425E: 7425E - EMISSION AND NON-COMPLIANCE RECALL - 2024-2025 MX-5 - TRACTION/STABILITY LIGHT MAY FAIL TO ILLUMINATE.

Part Name	Part Number (Before Modification)	Part Number (After Modification)
Dynamic Stability Control (DSC)	N452-43-7A0C	N452-43-7A0D or later
	N4Y0-43-7A0D or later	N4Y0-43-7A0C
	NH6V-43-7A0A or later	NH6V-43-7A0

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

NHY0-43-7A0A or later

NHY0-43-7A0

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.