

REFERENCE:	TSB: 08-360-25 GROUP: 08 - Electrical	Date:	October 29, 2025	REVISION:	—
VEHICLES AFFECTED:	2025 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or after September 01, 2025 (MDH 0901XX) and on and before September 22, 2025 (MDH 0922XX) .			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America markets.	
CUSTOMER SYMPTOM:	Customers may experience the following: <ul style="list-style-type: none"> • Headlamps are aimed too low. 				
CAUSE:	Incorrectly calibrated headlamps				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-227, date of issue October 29, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves performing the headlamp alignment procedure.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-34-9C	Headlamp Alignment - Aim/Adjust (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZY	Service Action	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Perform the headlamp alignment procedure. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 08 - Electrical / 8L - Lamps and Lighting / Lamps/ Lighting - Exterior / Standard Procedure.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.