

## GPOP - Issue Review System

**Part Number:** 68633947A\$, 68639445A\$, 68663479A\$

**Part Description:** MODULE, Telematics

**Issue Description:** DTC B1E21 is triggered when the TBM Backup Battery is discharged, inactive, or drained. This can happen during the lifetime of the vehicle. TBM should not be replaced for B1E21, since there is no fault on TBM. TBM battery is replaceable. Part number of the back-up battery inside TBM is 68597650AA.