

Document Information

Location: Transmission, Steering Wheel

Topic: Shift paddle related DTCs

Condition: Intermittent

Diagnostic Trouble Codes: P08162F-24, P08162F-A4

Measure

If you are presented with a McLaren Arura with a transmission warning message or functional concern with DTCs for shift paddles pre-cog signal erratic have been stored and the paddle adjustment is believed to be at fault **DO NOT** adjust the paddles. Please raise a Technical Request for instruction on how to proceed.

Parts Information

N/A

Repair Time

N/A

Attachments

N/A

KA Update Information

Initial release - 22/10/2025