

WSN5 Workshop Campaign – Rework damper element screw connection

WSN5 Workshop Campaign - Rework damper element screw connection

ID Number	WSN5
Model(s)	911 GT3 (992) 911 GT3 RS (992) 911 S/T (992)
Model Year(s)	2024 - 2025
Number of Affected VINs	7
VIN List	Attached
Issue Description	The damper elements of the catalytic converter brackets may not have been screwed down correctly on the affected vehicles. This leads to increased vibrations and forces on the exhaust manifold, which can cause cracks and consequently significant noise in the area of the exhaust system over the vehicle's service life. For this reason, the screw connection of the damper elements must be reworked.
What Porsche Centers Should Do	During the next workshop visit, please arrange for this action to be carried out on the affected vehicles (Solution available as of 10/27/2025)
TI	WSN5
Part Status	Status 1 - Order as needed

Required parts

PAF910423	Oval head 6-lobe bolt M6 x 16	5 pieces
-----------	-------------------------------	----------

Warranty processing

Validity:

This workshop campaign will be carried out up to 06/11/2030 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WSN5 66 000
Repair Code	1
Labor time	31 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Attachments

1. [WSN5 Workshop Campaign VIN List for Field Managers V3 10.27.2025 HT.xlsx](#)