

# WSR4 Workshop campaign with individual claiming - Retrofitting charge air cooler support sleeve

---

## WSR4 Workshop campaign with individual claiming - Retrofitting charge air cooler support sleeve

ID Number	WRS4
Model(s)	911 (992)
Model Years	2026
Number of Affected VINs	6
VIN List	Attached
Issue Overview	Due to an error in the production process, the support sleeve on the charge air cooler was not installed. This can cause rattling noises in the rear of the vehicle.
What Porsche Centers Should Do	The support sleeve on the charge air cooler must be retrofitted. Please ensure that the measure is carried out immediately. <b>(Solution available as of 10/27/2025)</b>
TI	Attached
Part Status	Status 1 - Order as needed

---

### Attachments

- [1. WSR4 Workshop Campaign VIN List for Field Managers 10.27.2025 HT.xlsx](#)