

WSR9 Stop Delivery - Checking position of front three-point seat belts and reworking if necessary

WSR9 Stop Delivery - Checking position of front three-point seat belts and reworking if necessary

Remedy Immediately available - see TI attached below

Vehicle Blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Registration and Stop Delivery, immediately.

The vehicles may only be driven for loading and unloading purposes in the transport chain.

A further use is not permitted. Test drives are to be omitted.

ID Number	WSR9
Model(s)	911 Cabriolet (992)
Model Year(s)	2026
Number of Affected VINs	11
VIN List	Attached
Issue Overview	Due to an error in the production process, there is a possibility that the three-point seat belts of the front seat system may not have been installed according to the specifications on the affected vehicles. If this is the case, the comfort function may be impaired.

WSR9 Stop Delivery - Checking position of front three-point seat belts and reworking if necessary

What Porsche Centers Should Do

For this reason, the routing of the three-point seat belts must be checked before delivery to the customer and corrected depending on the test result.

(At the time of posting, 10/30/2025, solution is immediately available)

TI

Attached

Part Status

Status 0 - No parts needed

Attachments

1. [WSR9 Stop Delivery_Check Instruction.pptx](#)
2. [WSR9 Stop Delivery VIN list for Field Managers 10.30.2025 V3 HT.xlsx](#)