

Vehicle-specific service

Topic	91 PSS MMI Entertainment: sound output pauses automatically after starting vehicle
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Audi
Transaction No.	2076904/3
Level	EH
Status	Released for publishing
Release date	Oct 7, 2025

Vehicle data

PPE/PPC vehicles excluding A6 ice

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
FU*	2025	A		*	*	*
GF*	2025	A		*	*	*
GH*	2025	A		*	*	*
GU*	2025	A		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
WA1	*	GF	*	S	*	000001	999999		
WA1	*	GU	*	S	*	000001	999999		
WAU	*	GH	*	S	*	000001	999999		
WAU	*	FU	*	S	*	000001	999999		

Documents

Document name
master.xml

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (Updated SW release date)
1	06/23/2025	Initial publication

This bulletin applies to 2025 PPE/PPC vehicles Q6 e-tron, A6 e-tron, A5 (FU), and Q5 (GU).

Customer Statement:

Radio or media playback pauses automatically after starting vehicle.

Workshop Findings:

The last selected media source is connected upon starting the vehicle but is paused automatically. Playback can be continued by pressing play.

Technical Background

Software issue.

Production Solution

Not applicable.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2025 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Playback can be manually restarted by pressing the play button in the MMI radio menu.

Warranty

Replacing parts or attempting repairs will not fix the concern. Unjustified work/ replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2076904**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2025 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of

Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.