

Condition

Applicable Vehicles						
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To	PR Number (s)
ID.4	2023	All	All	All	All	V6K

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2074689/2	10/13/2025	91-24-07	Revision to use campaign 919A as a prerequisite to allow for usage of the available replacement part.
2074689/1	7/25/2024	91-24-07	Original publication

- The parts catalog (ETKA) refers to this technical bulletin.
- A direct replacement for the Information Electronics Control Module 1 **-J794-** (ICAS3) part number 10A.035.842.Q (SW 1712) from original production ID.S 3.5 is not available.

CAUTION

This technical bulletin is applicable only to support replacement using the available service part when replacement is justified according to a proper technical diagnosis, which is outside the scope of this technical bulletin.

Technical Background

Completion of campaign 919A allows usage of the available replacement part 10A.035.842.M (SW 1741) with a subsequent update to 10A.035.842.N (SW 1751) to achieve compatibility of the replacement part within ID.S 3.5.11 or 3.5.12 after campaign 919A is completed.

Production Solution

Not applicable.

Service

1. Check whether campaign **919A** has already been completed (all criteria closed).
 - If no, continue with step 2.
 - If yes, continue to step 3.
2. Perform campaign **919A** to complete the update to ID.S 3.5.12 using ODIS.
 - Confirm the version in the infotainment display: 10A.035.842.N (SW 1751)



CAUTION

The compound software update according to campaign 919A must be completed before proceeding!

3. Perform technical bulletin **2076669/* (91-25-02)**.
4. End of procedure.

Warranty

Information only.



NOTICE

No parts or labor are to be claimed according to this technical bulletin. The referenced procedures are to be claimed according to campaign 919A (if necessary) and/or technical bulletin 2076669.

Required Parts and Tools

No special parts required.

No special tools required.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2025 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.