



Service Bulletin

Bulletin No.: PIT6338B

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Lane Keep Assist Inoperative or Cannot Program FVCM

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado ZR2	2024		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	MAH / MBC, UHY, ZR2 - UKI / UKW / ULV
Condition	Lane Keep Assist system inoperative. Can turn on and off but there is no dynamic function.
Cause	Engineering is investigating this concern, please do not replace parts for this issue.

Correction

In the meantime, please advise the customer they may continue to drive the vehicle.

The current concern may be a potential customer dissatisfier, but it is not a Safety Issue and does not create a substantial loss of use or value.

The PI will be updated or replaced with a TSB once a determination has been made.

If programming of front view camera module is attempted, a programming error will occur.

This will require Techline support to resolve. Do not replace the front view camera module.

Additional SI Keywords

departure warning

Version	2
Modified	Created on 2/14/2025 Archived 7/28/25 replaced by TSB 25-NA-205 Re-instated on 8/20/2025

