

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



FOREST RIVER ID: 210-2005
INTERNATIONAL RECALL: 25507/25V414

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

- o Integrity
- o Safety
- o Quality
- o Customer Service

November 2025

This Notice applies to your vehicle VIN listed above.

Pursuant to USC49CFR §577.13 – Notification to Dealerships and Distributors – Paragraph B

“It is a violation of Federal Law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied. Substantial civil penalties apply to violations of this law.”

–Forest River motorized and towable products are contained in this section–

Forest River is alerting you to an International Recall 25507/25V414 involving 2024-2026 Entourage Class C Motorhome Recreational Vehicles. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

Residual brake fluid may be present in the brake pressure switch/fuse harness, which was not detected during the completion of the original recall remedy under Safety Recall 23V-282 (23511).

RISK TO MOTOR VEHICLE SAFETY:

Brake fluid in the harness can corrode the wire and fuse, adding more resistance which may increase the risk of fire.

DEALERS: WHAT SHOULD YOU DO?

Vehicles will have a new brake pressure switch/fuse harness installed that contains an anti-capillary wire that will block fluid from wicking up the copper. The repair will be performed free of charge and take approximately 1.5 hours to complete. Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River
Office of Corporate Compliance

IMPORTANT SAFETY RECALL 25507**SEPTEMBER 2025****NHTSA RECALL NO. 25V414****THIS NOTICE APPLIES TO YOUR VEHICLE IDENTIFIED
ON THE ENCLOSED CARD.**

Dear International customer,

This notice is sent to you in accordance with the National
Traffic and Motor Vehicle Safety Act.International Motors, LLC* has decided that a defect which
relates to motor vehicle safety exists in certain 2019 thru
2025 International® CV™ Series trucks built 1/11/2018 thru
9/9/2024, with feature codes 0004198, 0004240 (Brake
system, hydraulic with Hydromax brake booster).**REASON FOR THIS RECALL**Residual brake fluid may be present in the brake pressure
switch/fuse harness, which was not detected during the
completion of the original recall remedy under Safety Recall
23V-282 (23511).**RISK TO MOTOR VEHICLE SAFETY**Brake fluid in the harness can corrode the wire and fuse,
adding more resistance which may increase the risk of fire.**DEFECT REMEDY**Vehicles will have a new brake pressure switch/fuse harness
installed that contains an anti-capillary wire that will block
fluid from wicking up the copper.The repair will be performed free of charge and take
approximately 1.5 hours to complete.**ACTIONS YOU SHOULD TAKE****Until the remedy can be performed, vehicle owners are
advised to park their vehicles outdoors.**If you own this vehicle, please schedule an appointment with
any Authorized repair center to have your vehicle repaired at
no cost to you. You can find your nearest dealer by using
the dealer locator at<https://www.internationaltrucks.com/dealer-locator> or by
calling 1-800-448-7825 or find the nearest Love's center at
<https://www.loves.com>. Love's and Speedco locations in
Texas and Louisiana cannot perform warranty services.If you have already paid for repairs prior to this notice that
corrected this defect, you may be eligible for reimbursement
of certain repair expenses if they occurred 1/11/2018 thru
9/30/2025. Present your original repair paperwork and
proof of payment to any International® dealer and youreligibility will be reviewed. You may also submit a claim using
the enclosed Request for Reimbursement card.If you are the lessor of this vehicle, please forward a copy of
this notice to the lessee within ten days to comply with
federal regulations.If you do not own this vehicle, please fill out and return mail
the enclosed card so that you will not be contacted again
about this recall.**IF YOU NEED FURTHER ASSISTANCE**If you believe that International Motors, LLC has failed to
remedy the defect without charge or within a reasonable
time, please follow the procedure described in the Owner
Assistance Guide section in your Owner's Manual or call toll
free 1-800-448-7825.You may also submit a complaint to the Administrator,
National Highway Traffic Safety Administration, 1200 New
Jersey Ave, SE, Washington, DC 20590; or call the toll-free
Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-
275-9171); or go to <http://www.safercar.gov>.International Motors, LLC requests your prompt attention
and patience regarding the correction of this defect and
apologizes for any inconvenience this may cause you.

Customer Notification

Corporate Compliance
Po Box 30
MIDDLEBURY, INDIANA 46540-9218



FOREST RIVER ID: 210-2005
INTERNATIONAL RECALL: 25507/25V414

- o *Integrity*
- o *Safety*
- o *Quality*
- o *Customer Service*

<<OWNER NAME/DEALERNAME>>
<<ADDRESS>>
<<CITY>>, <<ST>> <<ZIP-XXX>>

November 2025

This Notice applies to your vehicle VIN listed above.

Dear Forest River Customer:

Forest River is alerting you to an International Recall 25507/25V414 involving certain 2024-2026 Entourage Class C Motorhome Recreational Vehicles. Please see the information below which describes the issue and provides you with details on the steps you should take to have your vehicle repaired.

WHAT IS THE ISSUE?

Residual brake fluid may be present in the brake pressure switch/fuse harness, which was not detected during the completion of the original recall remedy under Safety Recall 23V-282 (23511).

RISK TO MOTOR VEHICLE SAFETY:

Brake fluid in the harness can corrode the wire and fuse, adding more resistance which may increase the risk of fire.

OWNERS: WHAT SHOULD YOU DO?

Vehicles will have a new brake pressure switch/fuse harness installed that contains an anti-capillary wire that will block fluid from wicking up the copper. The repair will be performed free of charge and take approximately 1.5 hours to complete. Please review and follow the notice that accompanies this letter.

Sincerely,

Forest River
Office of Corporate Compliance