



Service Bulletin

Bulletin No.: PIT6454

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Flutter or Rattle Noise Heard While Driving

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox EV	2024-	2026	All	All	All	All

Involved Region or Country	United States, Canada, Mexico, Middle East, Israel, Palestine, Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Uruguay (West), Japan
Condition	Some customers may notice a flutter or rattle noise heard from below the vehicle while driving.
Cause	The retaining clip fasteners securing the underbody shielding may be coming loose.

Correction

Engineering is reviewing the concern, but in the meantime install new retaining clips where needed to re-secure the underbody shielding.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
1481718*	Underbody Retaining Clip Installation	0.3 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	11/20/2025 Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2025 General Motors. All Rights Reserved.