



SUBARU SERVICE

**TECHTIPS NEWSLETTER LOCATOR INDEX
UPDATED THROUGH SEPTEMBER 2025**

This list is most efficient when searched using CTRL+F

TABLE OF CONTENTS

Click title below to jump to section

[**01 - General Information**](#)

[**02 - Engine**](#)

[**03 - Drive Train-Transaxle**](#)

[**04 - Steering**](#)

[**05 - Suspension-Wheels & Tires**](#)

[**06 - Brakes**](#)

[**07 - Electrical**](#)

[**08 - Instrument & Controls**](#)

[**09 - Cooling, Fuel, & Exhaust System**](#)

[**10 - Heating Ventilation & A/C Systems**](#)

[**11 - Emission Systems**](#)

[**12 - Body, Glass, & Upholstery**](#)

[**13 - Paint**](#)

[**14 - Special Tools**](#)

[**15 - Accessories**](#)

[**16 - Automatic Transmission**](#)

[**17 - SRS Air Bag**](#)

[**18 - Service Manual Corrections**](#)

[**19 - Special Edition**](#)

[**20 - EV \(Electric Vehicle\)**](#)

01-General Information

| | |
|---|-------|
| Legacy Knocking Noise, Rear of Vehicle When Driven Over Bumps..... | 07/91 |
| Justy Fuel Injection System Service Manual Supplement Section 2-7..... | 08/91 |
| In-transit Spark Plug Fouling Protection | 09/91 |
| Kats Wax Transit Coating Remover Precautions | 10/91 |
| Lemon Law Responsibilities..... | 11/91 |
| PDI Coolant Check - All Models..... | 11/91 |
| Parts Related Inquiries | 02/92 |
| Legacy and Loyale Normal Operating Characteristics | 04/92 |
| All SPI Models Throttle Body Gasket Replacement..... | 05/92 |
| Towing a Front Wheel Drive 5-Speed Legacy..... | 06/92 |
| Location of Engine, Transmission, and Production Date Information | 11/92 |
| Ordering “D” Check Manuals..... | 02/93 |
| Odometer Labels..... | 02/93 |
| Impreza Side Guard Moldings..... | 03/93 |
| Impreza Key Codes | 05/93 |
| Impreza Side Moldings..... | 05/93 |
| 1993MY SVX Model Code PKB “LSL” | 06/93 |
| All Models with PDI Connector for Storage | 06/93 |
| Diagnostic Trouble Codes | 07/93 |
| Flat Towing Subaru Vehicles | 08/93 |
| All Models Lock Cylinder Key Coding..... | 09/93 |
| Warranty Full History Inspection | 09/93 |
| Towing | 10/93 |
| Legacy Front Washer Nozzle Clogged..... | 10/93 |
| All Models with All Wheel Drive Systems, Use of the Space Saver Spare Tire or T-Spare Tire..... | 11/93 |
| All Models Equipped with Knock Sensors | 11/93 |
| Tool Ordering Procedures | 12/93 |
| October Update Revision - Poor Radio Reception AM or FM | 12/93 |
| 1993MY Legacy and Impreza ECU Operation with Select Monitor | 01/94 |
| Diagnosis of Noises Over the Phone..... | 02/94 |
| Justy Diagnostics..... | 03/94 |
| Recall Campaign Announcement – WZG-55 | 05/94 |
| Replacement of Ignition Relays..... | 05/94 |
| Repair Information..... | 05/94 |
| Requests to Return Parts for Inspection..... | 05/94 |
| Use of Trouble Code Diagnostic Trees in Service Manuals | 05/94 |
| 1994MY Impreza Equipment Changes..... | 06/94 |
| Legacy, Impreza, and SVX Service Manual Supplements | 06/94 |
| Select Monitor Cartridge-‘95MY Impreza | 10/94 |
| 1995MY Legacy Outback Wheel Cover Specifications..... | 11/94 |
| 1995MY Legacy Service Manual..... | 12/94 |
| 1995MY Impreza Select Monitor Update | 12/94 |
| Parts Questions..... | 01/95 |
| Legacy Service Manual Supplement | 01/95 |
| Oil Leaks..... | 01/95 |
| Obtaining Service Bulletins | 03/95 |
| Diagnosing Noises Over the Phone | 03/95 |
| Helpline Diagnostic Information | 05/95 |
| Physically Damaged Warranty Returned Parts | 05/95 |
| Kats Wax Removal Tips | 06/95 |

01-General Information

| | |
|--|-------|
| Thinking, the Service Manual, and the use of Diagnostic Flow Charts..... | 06/95 |
| Vehicle Model Year..... | 09/95 |
| 1996MY Subaru Legacy Select Monitor Cartridge | 10/95 |
| Select Monitor Information Update | 11/95 |
| Cooler Weather and Drivability..... | 11/95 |
| Technical Assistance and the CDS 800 Phone Line | 12/95 |
| Part Numbers for Electrical Condition Reports and Quality Monitoring Reports | 12/95 |
| Training Test Answers | 01/96 |
| Monroney Label Mismatches..... | 01/96 |
| Technical Helpline Updates/Service Bulletins..... | 02/96 |
| Impreza Key Code Location | 02/96 |
| 1995MY & 1996MY Power Antenna Operation | 02/96 |
| Service Bulletin Volume 17/Unlisted Bulletins | 04/96 |
| Air Conditioning Reminder | 05/96 |
| Technical Service Helpline Efficiency..... | 05/96 |
| 1996MY Subaru Legacy VIN Change..... | 06/96 |
| Location of Engine, Transmission and Production Date Information | 06/96 |
| Interactive Helpline Updates | 07/96 |
| 1997MY Subaru Legacy-Retrieval of OBD-II Codes without '97 Select Monitor Cartridge..... | 08/96 |
| Additional 1996MY Subaru Legacy VIN Change Information | 09/96 |
| “But, Its New.....” | 09/96 |
| 1997MY Legacy - Information for You..... | 09/96 |
| Returning Your Calls..... | 10/96 |
| Cooler Weather and Driveability..... | 11/96 |
| Towing Vehicles behind Motor Home..... | 02/97 |
| Frozen Wiper Blades | 02/97 |
| Technical Helpline Updates/Service Bulletins..... | 03/97 |
| State I/M 240 Emission Testing and Subaru AWD Vehicles..... | 04/97 |
| New Quality Monitoring Report (QMR) Form | 05/97 |
| 1998 Subaru Forester Facts | 07/97 |
| New Subaru Select Monitor | 07/97 |
| 1997MY Subaru Legacy Service Manual Supplement Volume 7 | 08/97 |
| 1998MY Subaru Forester | 09/97 |
| 1998MY Subaru Key Codes | 09/97 |
| 1998MY Forester Flat Towing..... | 10/97 |
| Customer Particulars..... | 10/97 |
| Subaru Forester PDI Connectors | 11/97 |
| Holiday Schedule For 1998 | 01/98 |
| Marking Messages “Urgent” on the Helpline Answering Machine | 01/98 |
| Parts Collection Cancellation | 01/98 |
| Technical Helpline Update Changes | 02/98 |
| New Name.....Same Dedicated Service | 02/98 |
| Technical Support Line Changes | 02/98 |
| 30th Anniversary/WRC Emblems..... | 03/98 |
| 1998MY Forester Key Blanks | 03/98 |
| State Emission Testing | 07/98 |
| Subaru AWD Vehicles Are Exempt from Two Wheel Dynamometer Emission Testing | 07/98 |
| Subaru Technical Support Line and Independent Repair Shops | 07/98 |
| 1999MY... What’s New..... | 08/98 |
| We Need to Know | 08/98 |
| The Support Line and Parts Questions..... | 08/98 |
| Cooler Weather and Drivability..... | 10/98 |

01-General Information

| | |
|---|----------|
| We Get Letters | 01/99 |
| Magnetic Tip Screwdriver Caution | 01/99 |
| Interior Trim Tool..... | 01/99 |
| Other Protection Ideas | 01/99 |
| Dash Noise | 01/99 |
| Technical Service Support Efficiency..... | 02/99 |
| Location of Data Information for Engine, Trans., and Production Date..... | 03/99 |
| Quality Monitoring Reports (QMRs) and You | 03/99 |
| We Get Letters – Continued..... | 04/99 |
| Parts Replacement..... | 04/99 |
| Reference Materials | 05/99 |
| Back to Basics – One More Time..... | 05/99 |
| Support Line Case Numbers..... | 07/99 |
| 2000MY Key Blanks | 07/99 |
| Y2K Subaru Legacy..... | 08/99 |
| Support Line Answering Machine | 10/99 |
| New Area Code | 11/99 |
| Vehicle Servicing | 4/00 |
| Subaru Warranty Coverage Changes for 2001MY | 05/00 |
| 2001MY Forester Owner’s Manual Correction | 07/00 |
| Suggested Measuring Device | 07/00 |
| Service Bulletin 12-68-00..... | 08/00 |
| Quality Monitoring Reports | 08/00 |
| Required Fluid Use for Warranty Repairs..... | 08/00 |
| Cooler Weather and Drivability..... | 10/00 |
| Impreza 2.5RS Modifications | 11/00 |
| Quality Advice Forms for 2001 H6 Outback..... | 11/00 |
| Expanded Support Line Hours | 01/01 |
| Parts Collection Center – Additional Location | 01/01 |
| AYES Program Participation..... | 02/01 |
| Towing Vehicles behind Motor Homes..... | 02/01 |
| Service Publications New 1-800 Number | 02/01 |
| Bulk Fluid Usage | 02/01 |
| Ordering Technician Patches | 03/01 |
| Answering Machine Reminder | 03/01 |
| Key Codes – A Reminder | 05/01 |
| 2002MY Impreza Sedan Valet Key Function | 09/01 |
| Service Manual Applicability | 11/01 |
| Special Edition: 2003 Forester Accessory Installation | 07/02 |
| Contacting the Technical Support Line..... | 09-10/02 |
| Information Requests | 09-10/02 |
| 2003 Baja Owners Manual Supplement..... | 03/03 |
| www.Subarunet.com Reminder | 03/03 |
| Faded or Ghosted Fluke Original 80 Series Display..... | 04/03 |
| Modifications to Vehicles | 07/03 |
| Electronic QMR | 07/03 |
| SOA Publication MSA5B0403A..... | 08/03 |
| Clamp-on Racks and Wind Noise..... | 01/04 |
| Calling the Technical Support Line..... | 03/04 |
| Service Manual Correction Labels..... | 05/04 |
| 2005MY Legacy/Outback: Updated PDI Check Items and Notes | 07/04 |
| Product Improvements..... | 08/04 |

01-General Information

| | |
|---|-------|
| Subarunet and Service Technicians..... | 10/04 |
| Updated Reprogramming Information | 11/04 |
| Cold Weather and Drivability..... | 11/04 |
| Enhanced EQMR..... | 11/04 |
| Premium Ownership Delivery..... | 12/04 |
| Technical Service Bulletins: A Recent List | 03/05 |
| Technical Service Bulletins: A Recent List | 04/05 |
| Tips from the Techs..... | 04/05 |
| Technical Service Bulletins/Programs..... | 05/05 |
| Technical Service Bulletins, TechTIPS, and Other Publications..... | 06/05 |
| 2006MY Mechanism and Function Service Manual | 06/05 |
| Recently Published Service Bulletins..... | 06/05 |
| Latest Service Bulletins Released..... | 07/05 |
| STi – Towing Behind Motor Homes..... | 07/05 |
| Latest Service Bulletins Released..... | 08/05 |
| Subaru Warranty Wizard Update | 09/05 |
| TechLine Pre-Call Worksheets..... | 09/05 |
| Latest Service Bulletins Released..... | 09/05 |
| Latest Service Bulletins Released..... | 10/05 |
| In Case You Forgot..... | 10/05 |
| Contacting the Technical Support Line..... | 11/05 |
| Come On Guys..... | 11/05 |
| Latest Service Bulletins Released..... | 11/05 |
| 2006MY Impreza Indicator Lights | 11/05 |
| Technical HelpLine Efficiency..... | 11/05 |
| Latest Service Bulletins Released..... | 12/05 |
| Calling the TechLine...."Can You Hear Me Now?" | 12/05 |
| Latest Service Bulletins Released..... | 01/06 |
| Latest Service Bulletins Released..... | 03/06 |
| FYI – Replacement of the Neutral Switch on a 6MT Vehicle..... | 03/06 |
| Service Information Availability on STIS..... | 06/06 |
| Techline Closing | 06/06 |
| Techline Pre-Call Worksheets | 06/06 |
| Immobilizer Codes & the Techline | 06/06 |
| Vehicle Repair Escalation Process..... | 06/06 |
| Calling the Techline.... Can You Hear Me Now??? | 07/06 |
| 2007 Subaru B9 Tribeca Introduction TRB | 08/06 |
| Quickie "FYI" TIPS | 08/06 |
| Latest SOA Service Documents Released..... | 08/06 |
| Latest SOA Service Documents Released..... | 09/06 |
| Subaru Chemical Information..... | 10/06 |
| Cold Weather- Here We Go Again!..... | 10/06 |
| Latest SOA Service Documents Released..... | 10/06 |
| Rear Differential Oil | 11/06 |
| Quick Tip: "No Start" Complaint | 11/06 |
| Power Steering Fluid Usage..... | 11/06 |
| New Tech TIPS Editor: Don Bangs..... | 12/06 |
| Quick TIP: Nox Rust | 12/06 |
| Clarification of the "Valet Key" and "Master Key" Immobilizer Type..... | 12/06 |
| Automatic Transmission Fluid for All 5EAT and 4EAT Transmissions | 12/06 |
| New Techline Representative | 01/07 |
| A "Back To Basics" Reminder..... | 01/07 |

01-General Information

| | |
|---|----------|
| Quick TIPS: Important Items to Note | 02/07 |
| From The “Clarifications Department” | 03/07 |
| Quick TIP – Forester Spare Tire Cover..... | 03/07 |
| Techline Survey Results | 04/07 |
| Gear Oil Specification Differences | 06/07 |
| 2007 U.S. National Technician Competition..... | 07/07 |
| Latest Service Bulletins Released..... | 07/07 |
| SSM III, Reprogramming & You..... | 08/07 |
| New 2008 M/Y Service Manuals on STIS | 11&12/07 |
| U.S National and World Technician Troubleshooting Competitions | 12/07 |
| H-6 Engine Smoke from Exhaust on Start-Up..... | 08/08 |
| Sending SSM-III Files..... | 08/08 |
| Oil Filter Wrenches | 12/08 |
| Calling the Techline: A Reminder about Cell Phones | 12/08 |
| Cold Weather Reminders | 12/08 |
| Incentive Program for Technician TIPS Suggestions | 01/09 |
| 2009 M/Y Forester & Impreza Protective Wheel Film | 01/09 |
| 2010 M/Y Legacy / Outback Preliminary Information | 05/09 |
| Use of Synthetic / Semi-Synthetic Engine Oils | 05/09 |
| 2008-09 M/Y Impreza, Dim Headlights and / or Erratic Outside Temperature Display | 06/09 |
| Help Us to Help You | 07/09 |
| 2010 M/Y Legacy & Outback Reporting Requirements | 07/09 |
| Subarunet & Subaru “SMART” System Login Information | 09/09 |
| Cell Phones, Air Tools & the Techline..... | 09/09 |
| SSMIII Error Codes..... | 11/09 |
| EQMR Authorization Requests... A Reminder | 01/10 |
| First Annual Subaru / ASE Master Automotive Technician of the Year | 02/10 |
| Techline Case Follow-Up and Call-In Tips | 04/10 |
| EQMR’s and Photos | 05/10 |
| Subaru / ASE Master Automobile Technician of the Year – 2010..... | 09/10 |
| 2nd Annual Subaru / ASE Master Automobile Technician of the Year Awards Announced | 10/10 |
| New 2011 MY Forester Quality Reporting Information..... | 11/10 |
| 2011 Factory-Fill Synthetic Oil and Maintenance Information..... | 11/10 |
| Does Your Service Department Have A “What’s New” Bulletin Board? | 02/11 |
| Troubleshooting Guides - A Reminder | 04/11 |
| “D-Check” Connector Locations | 05/11 |
| Revised Service Bulletins..... | 06/11 |
| Calling the Techline – Questions You Should Be Ready For | 07/11 |
| Use of Silicone Spray Precautions..... | 07/11 |
| 2012 Impreza PDI Fuse Procedure..... | 09/11 |
| Is This Clip Important? | 10/11 |
| Change to Oil Fill Cap of FB Engine..... | 11/11 |
| 2012 M/Y Oil Change Interval Information | 11/11 |
| Turning Off Blinking “Check Engine” light on 2012 MY Vehicles | 12/11 |
| Valve Clearance Checking Procedures, A Reminder | 01/12 |
| Yes, Another Sales Record Year for Subaru | 02/12 |
| Techline Case Follow-Up..... | 02/12 |
| Special Automatic Transmission Fluid for the New BRZ..... | 05/12 |
| Calibration Identification Numbers..... | 05/12 |
| Techline Staffing changes | 06/12 |
| 2013 BRZ PDI Procedure Information | 06/12 |
| 2013 Legacy, Outback and BRZ Launch-Your Help Is Needed | 07/12 |

01-General Information

| | |
|--|-------|
| Techline Staffing Changes | 09/12 |
| Subaru ASE Master Tech Of The Year 2012..... | 11/12 |
| Addition To PDI Procedure For Impreza And Crosstrek..... | 12/12 |
| Additional Tie Down Plug for 12-13 Impreza Models | 01/13 |
| Thanks to You..... | 02/13 |
| QMR Of The Month | 02/13 |
| QMR Of The Month Winner..... | 03/13 |
| New Model Launch Activities..... | 03/13 |
| Information You Should Always Have When Calling Tech Line..... | 04/13 |
| QMR Of The Month Winner..... | 04/13 |
| QMR Of The Month Winner..... | 05/13 |
| Recommended Materials Update | 05/13 |
| QMR Of The Month Winner..... | 06/13 |
| Authorization Requests | 06/13 |
| 2013 National Technician Competition..... | 08/13 |
| QMR of the Month..... | 08/13 |
| Quality Monitoring Reports | 08/13 |
| QMR of the Month..... | 09/13 |
| Subaru-ASE Master Auto Technician of the year..... | 09/13 |
| Towing Subaru Vehicles-Revisited | 09/13 |
| QMR of the Month..... | 10/13 |
| New Tech line Fax Number and Pre-Call Worksheets | 10/13 |
| Friday November 29th 2013-Tech line open..... | 10/13 |
| Clarification on Towing | 10/13 |
| QMR of the Month..... | 11/13 |
| Don't Forget to check the basics when diagnosing Drivability Complaints..... | 11/13 |
| Troubleshooting Guides on STIS-Reminder..... | 11/13 |
| BUI replacement and Key's..... | 11/13 |
| QMR of the Month..... | 12/13 |
| Fourth Bi-Annual Subaru international tech competition awards | 12/13 |
| Subaru/ASE Master Tech of the Year..... | 12/13 |
| 2014 XV-Crosstrek Hybrid Launch-Your Help Is needed | 12/13 |
| New Tech line hours of operation..... | 12/13 |
| QMR of the Month..... | 01/14 |
| 14Crosstrek Hybrid Launch Reminder | 01/14 |
| QMR of the Month..... | 02/14 |
| Authorization Request (AR) for Paint and Glass over 500..... | 02/14 |
| 2014 Hybrid Launch-Your Help is Needed | 02/14 |
| QMR of the Month..... | 03/14 |
| Tech line new hours of Operation..... | 03/14 |
| 2015 WRX and WRX STI Launch-Your help is Needed | 03/14 |
| QMR of the Month..... | 04/14 |
| New Tech line Pre-Call Worksheets | 04/14 |
| Tech line Case Follow up-Revisited | 04/14 |
| Authorization Request Pictures..... | 04/14 |
| QMR of the Month..... | 05/14 |
| Tech line case follow up-Revisited..... | 05/14 |
| QMR of the Month..... | 06/14 |
| 15MY Legacy and Outback Transit Fuse Information | 06/14 |
| QMR of the Month..... | 07/14 |
| 2015 Legacy and Outback Launch Team Activity-Your Help is Needed..... | 07/14 |
| New Subaru Oil Change Reference Cards..... | 07/14 |

01-General Information

| | |
|---|-------|
| 2015 Legacy and Outback Fujitsu 10 Audio and Audio/Navigation Systems | 07/14 |
| QMR of the Month..... | 08/14 |
| Change to Spare Tire Retaining Bolt..... | 08/14 |
| QMR of the Month..... | 09/14 |
| Locating Flash write Reprogramming Files for 2015 WRX Models..... | 09/14 |
| Calling the Tech line for Assistance | 09/14 |
| QMR of the Month..... | 10/14 |
| 5th Annual Subaru Technician Competition..... | 10/14 |
| QMR of the Month..... | 11/14 |
| Interior Rear View Mirror Separation..... | 11/14 |
| QMR of the Month..... | 12/14 |
| Subaru of America’s ASE Master Tech of the Year..... | 12/14 |
| QMR of the Month | 01/15 |
| Escalation Process What, Why, and How | 01/15 |
| QMR Reporting, Do’s and Don’ts..... | 01/15 |
| No Crank Condition on Push-Button Start-Equipped Model’s..... | 01/15 |
| Techline Case Follow Up..... | 01/15 |
| QMR of the Month..... | 02/15 |
| Reminder: Sending Saved Freeze Frame (FFD) and SSM Data Files..... | 02/15 |
| New Product Announcement (SOA868V9175) Silicone Gasket Remover..... | 02/15 |
| Exciting Update to the “QMR of the Month” Award Program..... | 02/15 |
| QMR of the Month..... | 03/15 |
| Techline Phone System “Courtesy Call Back Feature” | 03/15 |
| QMR of the Month..... | 04/15 |
| QMR of the Month Award Presentation | 04/15 |
| Calling the Tech line Revisited..... | 04/15 |
| QMR of the Month..... | 05/15 |
| New Required Detail Fields Established for Claims Submission | 05/15 |
| Explanation of New Required Fields in Quality Monitoring Report (QMR)..... | 05/15 |
| QMR of the Month Award Presentation | 05/15 |
| QMR of the Month..... | 06/15 |
| Authorization Requests/Better Pictures Requested | 06/15 |
| Combination Meter and BIU shipments to SOA | 06/15 |
| QMR of the Month..... | 07/15 |
| QMR of the Month Award Presentation | 07/15 |
| Subaru Oil Consumption..... | 07/15 |
| QMR of the Month..... | 08/15 |
| Technician Submission of the Month | 08/15 |
| EyeSight Charts..... | 08/15 |
| 2016 Forester Service Manual-The next Generation..... | 08/15 |
| QMR of the Month..... | 09/15 |
| QMR of the Month Award Presentation | 09/15 |
| CPO procedure for turbocharged Subaru vehicles..... | 09/15 |
| Understanding DTC’s and how to proceed properly with repairs..... | 09/15 |
| QMR of the Month..... | 10/15 |
| QMR of the Month Award Presentation | 10/15 |
| Remanufactured Transmission Replacements | 10/15 |
| 2015 Technician ASCENT Program-Important Enhancements..... | 10/15 |
| QMR of the Month..... | 11/15 |
| QMR of the Month Award Presentation | 11/15 |
| QMR of the Month..... | 12/15 |
| QMR of the Month Award Presentation | 12/15 |

01-General Information

| | |
|--|-------|
| Subaru World Technician Competition..... | 12/15 |
| Subaru Technical Training-Gaming Survey..... | 12/15 |
| QMR of the Month..... | 01/16 |
| QMR of the Month Award Presentation | 01/16 |
| Pre-cut Keys..... | 01/16 |
| 2016 Technical Training Curriculum Planning Workshops | 01/16 |
| Fujitsu (F-10) Map Information..... | 01/16 |
| Towing Subaru Vehicles | 01/16 |
| The New and Improved QMR of the Month Program | 01/16 |
| QMR of the Month..... | 02/16 |
| QMR of the Month Award Presentation | 02/16 |
| QMR of the Month..... | 03/16 |
| QMR of the Month Award Presentation | 03/16 |
| QMR of the Month..... | 04/16 |
| QMR of the Month Award Presentation | 04/16 |
| Subaru-U Announcement | 04/16 |
| Saving and Printing Freeze Frame Data..... | 04/16 |
| Changes to Subaru-Net Links..... | 04/16 |
| QMR of the Month..... | 05/16 |
| QMR of the Month Award Presentation | 05/16 |
| American National Technician Competition | 05/16 |
| Subaru-U..... | 05/16 |
| Stickers on the Windshield..... | 05/16 |
| QMR of the Month..... | 06/16 |
| QMR of the Month Award Presentation | 06/16 |
| Subaru-U..... | 06/16 |
| New STIS User's..... | 12/16 |
| Subaru-U..... | 01/17 |
| QMR of the Month..... | 01/17 |
| QMR of the Month Award Presentation | 01/17 |
| Subaru-U..... | 02/17 |
| QMR of the Month..... | 02/17 |
| QMR of the Month Award Presentation | 02/17 |
| Update to STIS..... | 02/17 |
| QMR of the Month..... | 03/17 |
| Subaru-U..... | 03/17 |
| QMR of the Month..... | 04/17 |
| QMR of the Month Award Presentation | 04/17 |
| Subaru-U..... | 04/17 |
| Locating Tech Tips | 04/17 |
| CPO Procedure for Turbocharged Subaru Vehicles | 04/17 |
| Technicians: What Is Your Role in Product Quality? | 04/17 |
| Lost keys? Contact the Subaru Techline..... | 05/17 |
| Application chart for Immobilizer | 06/17 |
| DCM and ECM swapping..... | 08/17 |
| Authorization Requests | 08/17 |
| CPO Procedure | 08/17 |
| Calling the Techline Revisited..... | 08/17 |
| Lost Keys? + Immobilizer Chart | 09/17 |
| Understanding DTC's and How to Proceed Properly with Repairs | 09/17 |
| Requesting Techline callback's | 09/17 |
| The Subaru Parts Collection Center | 09/17 |

01-General Information

| | |
|--|----------|
| The Key to the Highway..... | 11/17 |
| Following the Service Manual for Repairs..... | 11/17 |
| WQK-47 Equipment Cleaning Procedure..... | 11/17 |
| Authorization Requests (AR) for Paint and Glass Over \$500 | 12/17 |
| CPO Procedure for Turbocharged Subaru Vehicles | 12/17 |
| Calling TechLine Revisited | 12/17 |
| QMR of the Month Program Enhancement..... | 01/18 |
| Reviewing Data Files | 01/18 |
| Calling the TechLine Revisited | 02/18 |
| Locating TechTIPS..... | 02/18 |
| Understanding Power Supply | 02/18 |
| Body Plug Relocation..... | 02/18 |
| Calling Subaru TechLine..... | 04/18 |
| Icy Road Warning Indicator Operation | 04/18 |
| Clearing Trouble Codes..... | 05/18 |
| Subaru Diagnostics | 05/18 |
| 2019MY Ascent Owner’s Manual Utilization | SE 05/18 |
| Understanding Readiness Codes | 06/18 |
| Why Was That Part Replaced? | 06/18 |
| System Owner Manuals | 07/18 |
| Understanding DTCs and How to Proceed Properly with Repairs | 07/18 |
| Stickers on the Windshield..... | 09/18 |
| Authorization Requests (AR) for Paint and Glass over \$500..... | 09/18 |
| QMR of the Month..... | 10/18 |
| 2019MY Forester Quality Monitoring Team New Model Launch..... | 10/18 |
| 2019MY Forester: Auto Start-Stop and Driver Monitor System Diagnostic Information..... | 10/18 |
| The Importance of Searching for TSBs and TechTips | 12/18 |
| QMR of the Month..... | 01/19 |
| Subaru Technicians Honored at ASE Annual Meeting..... | 01/19 |
| TechLine Case Follow Up..... | 01/19 |
| The Radio Keeps Playing and a “Turn Engine Off Before Exiting” Message Appears – Why?..... | 01/19 |
| QMR of the Month..... | 02/19 |
| 2019 National Training Competition | 02/19 |
| QMR of the Month – Trip Winner Announcement | SE 02/19 |
| QMR of the Month..... | 03/19 |
| 7th Annual National Technician Competition Conclusion | SE 03/19 |
| QMR of the Month – Trip Winner Announcement | SE 03/19 |
| QMR of the Month..... | 04/19 |
| Understanding Customer’s Concern..... | 04/19 |
| QMR of the Month..... | 05/19 |
| Use of Silicone Spray Precautions..... | 05/19 |
| Brake Lamp Switch Replacement Web Based Training..... | 05/19 |
| QMR of the Month..... | 06/19 |
| Understanding DTCs and How to Proceed Properly with Repairs | 06/19 |
| CPO Procedure for Turbocharged Subaru Vehicles | 06/19 |
| QMR of the Month | 07/19 |
| G Type, H Type, and I Type Immobilizer Registration..... | 07/19 |
| Important Battery Sensor Procedures – 2019MY Crosstrek Plug-In Hybrid (PHEV) Model..... | 07/19 |
| Melting Plastic Parts..... | 07/19 |
| QMR of the Month..... | 08/19 |
| Helpline Diagnostic Information | 08/19 |

01-General Information

| | |
|---|-------|
| QMR of the Month..... | 09/19 |
| Subaru Select Monitor (SM4) Unresponsive When Connecting to Some 2020MY Vehicles | 09/19 |
| QMR of the Month..... | 10/19 |
| QMR of the Month..... | 11/19 |
| Authorization Request Pictures..... | 11/19 |
| QMR of the Month..... | 12/19 |
| Calling the Techline Revisited..... | 12/19 |
| Hints for Searching Separate Publications with Online Reference | 01/20 |
| Application Chart for Immobilizer System..... | 01/20 |
| Subaru National Technician Competition Selection Announcement | 03/20 |
| Disinfecting Vehicles | 04/20 |
| CPO Procedure for Turbocharged Subaru Vehicles | 04/20 |
| Authorization Requests (AR) for Paint and Glass over \$500.00..... | 04/20 |
| Lost Keys? Contact the Subaru Techline | 05/20 |
| Techline Case Follow Up | 06/20 |
| New Claims System Coming June 8th – Things to Know for Authorization Requests | 06/20 |
| Cell Phones, Air Tools and the Techline | 08/20 |
| Calling The Techline Revisited..... | 09/20 |
| Sending account to Techline | 09/20 |
| Subaru Express Service – Low-Touch Best Practices for Technicians..... | 10/20 |
| Oil Capacity | 10/20 |
| CPO Procedure for Turbocharged Subaru Vehicles | 10/20 |
| Techline Staffing Changes | 01/21 |
| Special Edition: Escalation Process What, Why, and How | 01/21 |
| Combination Meter and BIU shipments to SOA | 02/21 |
| Lost Keys? Contact the Subaru Techline | 03/21 |
| Dash Camera Etiquette – Behave like you’re being watched | 04/21 |
| Understand DTCs and How to Proceed Properly with Repairs | 05/21 |
| Do Not Print Technical Service Bulletins Reminder | 06/21 |
| CPO Procedure for Turbocharged Subaru Vehicles | 10/21 |
| Sending Immobilizer Components, Broken on Arrival | 11/21 |
| Tech TechShare QMR and You | 02/22 |
| Lost Keys? Contact the Subaru Techline. Updated Immobilizer Chart..... | 03/22 |
| Calling the Techline Revisited..... | 04/22 |
| When Diagnostics Don’t Diagnose, Checking ALL Power Supplies..... | 04/22 |
| 22MY Pre-Delivery Inspection (PDI) Fuse Location Reminder..... | 04/22 |
| Replacing components on the CAN network & Central Gateway Control LAN Registration..... | 05/22 |
| Solterra DTC’s Resulting from Service/Maintenance Activities: P0A1B1F, P0A1C1F, U113B87 | 08/22 |
| 22MY WRX One Touch Turn Signal Operation..... | 08/22 |
| Hints for searching Accesory Installation Directions with Online Reference | 09/22 |
| Canadian to US Spec & Vice Versa..... | 10/22 |
| CPO Procedure for Turbocharge Subaru Vehicles..... | 10/22 |
| QMR if the Month Program | 11/22 |
| Virtual Meeting Rooms..... | 04/23 |
| Updating Technician Profiles for Techline Communications | 04/23 |
| SXM Traffic & Weather Discontinued | 05/23 |
| Techshare – Opening an Infotainment case & Attaching files to open Techline cases..... | 05/23 |
| Towing a Subaru Revisited..... | 06/23 |
| Understanding Power Supply | 07/23 |
| 2023 American National Technician Competition | 08/23 |
| DCM and ECM swapping..... | 09/23 |
| ASE Training Conference | 09/23 |

01-General Information

| | |
|--|-------|
| Lock Cylinder Replacement | 09/23 |
| CPO Procedure for Turbocharged Subaru Vehicles | 10/23 |
| Subaru of America Announces Winners of the 2023 American National Technical Competition..... | 10/23 |
| WRD-23 – Installing the Wrong Length Bolts..... | 10/23 |
| Techline Staffing Changes | 11/23 |
| The Importance of Searching For TSBs and TechTIPS..... | 12/23 |
| Secondary DTCs | 01/24 |
| Bulkhead Area Rattle FA24 Equipped Vehicles..... | 01/24 |
| Stickers On The Windshield | 03/24 |
| The Next Phase of Techline And TechShare | 04/24 |
| How To Send GTS Plus Project files | 05/24 |
| Lost Keys? Contact the Subaru Techline. Updated Immobilizer Chart..... | 06/24 |
| General Customer Interview and 3C's | 08/24 |
| Technical Service Helpline Efficiency..... | 09/24 |
| Repair Information..... | 10/24 |
| Lost Keys/Component Clearing Reminders..... | 02/25 |
| Simultaneous Multiple System Monitoring..... | 06/25 |
| Sending Immobilizer Components, Broken on Arrival..... | 07/25 |
| 2026 Outback PDI Reminder..... | 08/25 |

02-Engine

| | |
|--|-------|
| 1.8 Engine Head Gasket Torque Change/Oil Leakage | 05/91 |
| Legacy Throttle Sensor Switch Adjustment | 08/91 |
| Noisy Lash Adjusters | 09/91 |
| Legacy Exhaust Valves..... | 09/91 |
| Legacy Cylinder Head Resurfacing (Grinding) Specifications Clarification | 10/91 |
| Justy Cylinder Head Installation and Retorquing Clarification..... | 11/91 |
| Legacy Turbo Models - Oil In the Coolant | 08/92 |
| Oil Leaks..... | 09/92 |
| Correction to Legacy Turbo Oil Leaks in the September Update | 10/92 |
| Justy Balancer Chain Replacement | 11/92 |
| 1991MY-‘1992MY Legacy Turbo and All ‘92MY N.A. M/T “High Idle Complaint” | 12/92 |
| 1992MY Legacy Turbo Stalls After Start-Up Hot or Cold | 12/92 |
| 1992MY SVX Trouble Code 56, EGR System..... | 12/92 |
| Loyale “Engine Ping” Complaint SPI..... | 01/93 |
| 1992MY SVX Auxiliary Air Valve Disconnection | 04/93 |
| All Justy Models Drivability Complaints | 08/93 |
| Justy with Multiple Failure Codes Including Code 41 in ECU Memory..... | 09/93 |
| L-Series/Loyale 1.8 Liter OHC Valve Servicing | 09/93 |
| Correction to All Justy Models Drivability Complaints, August Update..... | 10/93 |
| 1993MY Legacy Models, Electronic Control Unit “Rom” Installation | 10/93 |
| Replacement Engine Oil Filters | 12/93 |
| Loyale and Legacy HLA Noise | 04/94 |
| 1995MY Legacy Spark Plugs | 10/94 |
| Synthetic Lubricant Usage | 10/94 |
| Idle Quality Complaints On ‘95MY Legacy | 02/95 |
| Synthetic Engine Oil | 02/95 |
| Engine Testing-Back to Basics..... | 04/95 |
| Synthetic Lubricant Usage - Updated Information | 07/95 |
| Oil Viscosity Change for 1996MY Subaru Vehicles..... | 10/95 |
| 2.5 Liter Motor Engine Knocking or Tapping Noise..... | 01/96 |
| 1997MY Engine Noise | 09/96 |
| Legacy 2.2L and Impreza 1.8L, 2.2L Engine Oil Filling..... | 09/96 |
| Welcome To Shim City | 10/96 |
| New Cambelt Tensioner | 04/97 |
| Assembling 1997MY and Newer Engines | 08/97 |
| Molybdenum Coating On Pistons | 10/97 |
| Engine Noise | 11/97 |
| 2.5L Engine Cylinder Head Bolt Tightening Sequence | 11/97 |
| Legacy Engine Belt Guides | 05/98 |
| 1996MY 2.5L Exhaust Valves | 09/98 |
| 2.2L Front Crankshaft Oil Seals..... | 10/98 |
| 1999MY Legacy Short Blocks..... | 11/98 |
| Leaking Front Crankshaft Oil Seals..... | 01/99 |
| SIA Installed Engine Oil | 03/99 |
| 2000MY Spark Plug Application Chart (revised 01-31-00)..... | 04/00 |
| Engine Noise when Cold | 08/00 |
| Oil Pumps – Replacement vs. Resealing | 01/01 |
| 3.0L 6 Cylinder Valve Train Servicing | 02/01 |
| Subject: Engine Noise when Cold..... | 02/01 |
| Three Bond 1280B | 05/01 |

02-Engine

| | |
|--|----------|
| 2002MY WRX Turbo Cool Down Procedure | 06/01 |
| Oil filters: H-4 versus H-6 Engines | 03-04/02 |
| 2.0L Camshaft Cap Torque Correction | 08/02 |
| DOHC Turbo Valve Specification | 09-10/02 |
| Subject: Engine Noise when Cold | 01-02/03 |
| Radiator Hose Leakage | 01-02/03 |
| SOA Replacement Ignition Wire Set | 01-02/03 |
| Coolant Seepage from Water Pump | 05/03 |
| 2004 Baja and Forester Turbo Engine Oil Filters | 05/03 |
| Cam Belt Tensioner Replacement..... | 07/03 |
| Vehicle Re-engineering/modifying | 07/03 |
| All Turbo Model Oil Filters | 07/03 |
| Head Gasket Repairs | 11/03 |
| Oil Filter Application Clarification | 11/03 |
| Engine Noise – All H6 Vehicles..... | 01/04 |
| H6 Cylinder Head Bolt Torqueing Procedures | 02/04 |
| Cylinder Bore Size Location Information..... | 03/04 |
| Cruise Control Cable Retainer Clip: WWQ-01 | 04/04 |
| Pressure Washing of Vehicle Engine Compartment – All Models | 08/04 |
| Intercooler Spray Tank | 03/05 |
| Oil Classification Change for 2006MY Vehicles | 07/05 |
| Shortblocks Replaced Under Warranty | 08/05 |
| P/N 11063AB120: LH Cylinder Head Assembly | 09/05 |
| Engine Testing – Back to the Basics | 10/05 |
| Safe Handling of Sodium Filled Valves..... | 10/05 |
| Coolant Seepage from Water Pumps | 10/05 |
| Remanufactured SOHC Shortblocks and Bulletin 02-96-05 | 11/05 |
| Bank1, Bank 2 | 01/06 |
| Valve Stem Oil Seals | 02/06 |
| Rubbing Mark on Timing Belt..... | 02/06 |
| Platinum Spark Plug Change Intervals..... | 04/06 |
| Turbo Failures..... | 05/06 |
| H6 Oil Level Explained | 06/06 |
| Basics, Basics, Basics | 06/06 |
| Turbocharger Oil Supply Filter..... | 03/07 |
| Engine Oil Specification Information | 05/07 |
| 3.6L H-6 Oil Filter Wrench Information..... | 07/07 |
| Cranks Over But Won't Start?..... | 10/07 |
| 2008 M/Y 3.6L Engine Oil Dipstick | 11/07 |
| Tribeca Oil Cooler Line Clamps..... | 11/07 |
| Revised Turbocharger Oil Supply Piping..... | 01/08 |
| Subaru Valve Adjustment Information | 02/08 |
| More Valve Adjustment Information | 04/08 |
| Engine Oil Pan Drain Plug Gaskets: NOT All the Same!..... | 05/08 |
| Don't Forget To Check Those Banjo Bolt Filters | 07/08 |
| WWM-96 Rear Suspension Sub-Frame Corrosion Campaign | 11/08 |
| Bank-Specific Misfires & Active Valve Control System (Variable Valve Timing- VVT)..... | 01/09 |
| Oil Filter Replacement Precautions..... | 02/09 |
| Important Short / Long-Block Replacement Reminder | 03/09 |
| P0171, Rough Running Condition after Cold Start..... | 04/09 |
| Turbocharged Engines: Oil Supply Reminder | 08/09 |
| 2010 M/Y Legacy & Outback 3.6L Engine Cover Removal | 10/09 |

02-Engine

| | |
|---|-------|
| Engine Oil Leaks – A Reminder | 05/10 |
| Valve Adjustment and Clearance Measurement the Right Way..... | 06/10 |
| 4-Cylinder Crankshaft Oil Seal Replacement Procedures..... | 07/10 |
| Don't Forget to Check the EGR Valve | 12/10 |
| DTC P0128 Information | 12/10 |
| 2011 M/Y Forester N/A Revised Oil Filler Cap..... | 02/11 |
| Leaking Engine Oil Seals? Don't Forget to Check the PCV! | 02/11 |
| Fluid Leak Detection Made Easier..... | 04/11 |
| Revised Cylinder Head Gasket Diagnostic Procedure..... | 05/11 |
| 2010 M/Y and Newer Oil Pan Damage..... | 06/11 |
| 2011 M/Y Forester (FB Engine) Cam Position Sensor Information..... | 06/11 |
| 2010 M/Y and Later Impreza WRX and STI Turbo Charger and Stay Bracket | 06/11 |
| FB25/20 Engine Crankshaft Sensor Reluctor Indexing | 10/11 |
| Excessive Noise from the Engine Under Boost | 02/12 |
| 2010 and Later Legacy and Outback 3.6 Engine Cover Removal..... | 05/12 |
| 2007 to 2009 Cylinder Head Identification..... | 06/12 |
| BZR Fuel Injection Operational Characteristics | 06/12 |
| Turbo Charges And Piping | 08/12 |
| Front Chain Cover Oil Leaks | 12/12 |
| Too Much Oil in the Engine | 03/13 |
| Understanding The Relationship Between Cam Crank Position Sensors | 04/13 |
| 2013 Legacy/Outback Spec Change to Engine Under Cover | 04/13 |
| 2012 WRX and STI Motor Mounts..... | 05/13 |
| Remanufactured Short Blocks..... | 05/13 |
| 2.0 and 2.5 FA/FB Chain Driven Engine Timing Information | 09/13 |
| Engine oil expansion, Fact or Fiction | 12/13 |
| FA and FB Engine Connecting Rod Bolt Removal Tip | 02/14 |
| FA and FB Engine Timing ChainTensioner Initial Setting Information | 03/14 |
| Piston Ring Installation TIPS | 03/14 |
| Discoloration of Cylinder Walls | 04/14 |
| Too Much Oil In The Engine Revisited | 06/14 |
| Hard Starting, Extended Engine Cranking Concerns Revisited..... | 12/14 |
| FA and FB Engine Crank Sprocket Timing Mark Important Reminder | 04/15 |
| 2015-16 MY WRX Engine Cover Removal Precaution..... | 09/15 |
| Cam Sprocket Replacement for P000A-P000D A Reminder..... | 10/15 |
| Addressing Accessory Drive Belt Noise | 02/16 |
| Timing Chain Cover Installation..... | 04/16 |
| Smoke from Exhaust on DIT Turbo vehicles | 12/17 |
| Allowable Repairs to CVT Assemblies | 03/18 |
| Engine Oil Pressure Specification Discrepancies | 07/18 |
| Fluid Leak Detection Made Easier..... | 11/18 |
| H6 Cylinder Head Replacement Precaution | 06/19 |
| P0507 After Engine Service, Abnormal Idle Speed..... | 03/20 |
| Rough Idle with AVCS DTCs | 03/20 |
| Improved Diagnosis of Engine Oil Leakage, Leak Trace Powder Revisited | 03/21 |
| 2019 and up 2.4L Turbo, P0299 | 07/21 |
| New and Remanufactured Short Block Replacement Tips & Break-In Procedure..... | 08/21 |
| P0171, Rough Running Conditon After Cold Start..... | 02/22 |
| Diagnosing P0128 on Thermo Control Valve Equipped Vehicles | 06/22 |
| Leak-Down Testing..... | 10/22 |
| FA24 DIT Post Engine Repair DTC P04F0..... | 03/24 |
| White or Blue Smoke on Start Up From Tail Pipe | 10/24 |

02-Engine

| | |
|---|--------|
| Engine Testing - Back to Basic..... | .03/25 |
| Thermostat Installed on Thermo Control Valve Equipped Vehicles..... | .05/25 |
| P0507 After Engine Service, Abnormal Idle Speed..... | .06/25 |
| Leak Down Testing..... | .09/25 |
| Compression Testing..... | .09/25 |

03-Drive Train-Transaxle

03-Drive Train-Transaxle

| | |
|--|----------|
| Shifter-Rattle "L" Series 4WD M/T and XT FWD or 4WD M/T | 07/91 |
| Legacy Rear Diff..... | 08/91 |
| Manual Transmission Gear Oil | 01/92 |
| L-Series and XT Models With Stepped Flywheels | 04/92 |
| All Subaru Models Rear Differential Assembly Replacement | 05/92 |
| Legacy/SVX Limited-Slip Rear Differential..... | 06/92 |
| 1992MY Loyale Shifter Rattle On 4WD 5-Speed Models | 08/92 |
| All Four-Wheel Drive Vehicles..... | 11/92 |
| All Subaru Models Wheel Bearing Replacement | 06/93 |
| Legacy Axle Repairs | 07/93 |
| Justy Drive Axle Installation | 09/93 |
| Diagnosing 3SP Automatic Transmissions Starting In Second Gear..... | 11/93 |
| Justy ECVT Transmissions That Won't Up-Ratio After Rebuild..... | 11/93 |
| Rear Differential Replacement | 12/93 |
| 3 Speed Automatic Clutch Drum Wear | 01/94 |
| Manual Shift Lock Release on '94MY SVX | 02/94 |
| 3-Speed Automatic Differential Rebuilding..... | 05/94 |
| Replacing AWD Rear Wheel Bearings on Legacy, Impreza, and SVX | 04/95 |
| Inspection of Clutch Free Play During PDI..... | 07/95 |
| Automatic Impreza Rear Differentials..... | 05/96 |
| Outback Gear Ratios..... | 05/96 |
| Where's The Hill Holder? | 10/96 |
| Inspection of Clutch Free Play During PDI | 11/96 |
| Noise from Rear Axle Oil Seal-Legacy Models..... | 01/97 |
| '97MY Legacy Rear Differential Crossmember Bracket Noise & Vibration..... | 01/97 |
| Rear Differential Modifications | 04/97 |
| All Subaru Models with Stepped & Flat Flywheels..... | 07/97 |
| Additional Parts Information on Differential Modifications..... | 07/97 |
| Identifying 1997 Subaru Legacy Propeller Shafts | 07/97 |
| 1997MY Legacy Rear Differential Crossmember Bracket Noise & Vibration..... | 10/97 |
| Grease Leaking From Inner Axle Joints | 02/98 |
| Rear Differential Vent Oil Leakage..... | 04/98 |
| Legacy Engine Belt Guides | 05/98 |
| 1998MY Vehicles Leaking Axle Grease..... | 09/98 |
| M/T Case Boss Wear | 09/98 |
| 5MT Popping Out Of First Gear | 10/98 |
| Shifter Rattle..... | 02/99 |
| All 1999MY Manual Transmission Vehicle..... | 03/99 |
| Transmission/Rear Differential Gear Ratios | 06/99 |
| Popping Out Of Fifth Gear | 01/00 |
| 1999/2000MY Manual Transmissions Popping Out Of 1st Gear | 04/00 |
| 2001MY Outback H6-3.0 VDC Precautions | 11/00 |
| Variable Torque Distribution | 05/01 |
| All Subaru Rear Differentials | 10/01 |
| Use of Correct Fluids | 08/02 |
| Parts Supersession 2002MY Outback & Impreza 1st Driven Gear | 09-10/02 |
| Transmission Popping Out of 3rd Gear..... | 05/03 |
| On The Car Rear Wheel Bearing Replacement Procedure..... | 09/03 |
| Impreza WRX Driveability | 04/04 |
| 2005MY Manual Transmission Speedometer Gears..... | 06/05 |

03-Drive Train-Transaxle

| | |
|--|-------|
| STi Rear Differential Oil | 07/05 |
| Impreza STI Characteristics | 01/06 |
| Clutch Pedal Squeak | 05/06 |
| Manual Transmission Center Differential Damage | 10/06 |
| STI / DCCD “Klunking Noise” | 02/08 |
| 6 M/T “Quick TIPS” | 03/08 |
| DTC P1720, DCCD Code in Memory, 2008 STI | 09/08 |
| Squeaking Noise When Operating the Clutch Pedal | 02/09 |
| 2010 M/Y Legacy & Outback Sound at Initial Start-Up | 08/09 |
| Tribeca Rear Differential Temp Light Flickering..... | 04/10 |
| Updated M/T Transmission Drain Plug Gasket Information..... | 06/10 |
| 2010-11 M/Y Legacy / Outback “Howling” from Under the Vehicle..... | 01/11 |
| 2010 M/Y & Later Legacy / Outback 6 M/T Reverse Gear Damage..... | 01/12 |
| BRZ Manual Transmission Sounds | 06/12 |
| Color Change To Manual Trans Oil Level Dipstick | 10/12 |
| All Manual Transmission Equipped Vehicles..... | 11/12 |
| 2015 WRX Short Throw Shifter Precautions | 05/14 |
| Transmission Cooler Flushing | 08/15 |
| BRZ 6M/T Rattling Sound on Deceleration w/AC On | 09/15 |
| Reminder-Cleaning and Lubrication of Clutch Release Components | 11/15 |
| P2751 and no CVT Engagement | 05/16 |
| AT Learning Control Information | 06/16 |
| Transmission Replacement Procedures..... | 06/16 |
| No Movement after Valve Body Replacement on 10-12 Legacy/Outback CVT | 08/16 |
| Clutch Release Component Lubrication | 10/16 |
| Clutch Release Component Lubrication and Inspection Revisited..... | 11/16 |
| Unnecessary CVT Replacement’s | 12/16 |
| HARMAN AUDIO UNITS: Audio Volume Turned To Max When Monitoring Infotainment Data Monitor | 03/17 |
| AT Learning Control Information | 11/17 |
| Smoke from Exhaust on DIT Vehicles | 12/17 |
| P2751 and no CVT Engagement | 09/18 |
| Selectable Shift Fork Identification Marks | 01/19 |
| Squeak/Chirp Sound from High-Torque CVT When Shifting from P/N to D | 04/20 |
| AT Learning Control Information | 07/20 |
| Wiring Clarification for Guide Plate B Installation (TSB 16-112-18R) | 07/20 |
| P2751, Vehicle does not Move When in Gear | 09/20 |
| Front Differential Failure After Transmission R&R | 11/20 |
| Binding/Sound While Turning | 11/20 |
| Vibration After Transmission or Engine Removal | 04/21 |
| Ascent or Legacy/Outback 2.4L Binding When Turning Basic Diagnosis Overview..... | 04/21 |
| Squeak/Chirp Sound from High-Torque CVT When Shifting from P/N to D..... | 01/22 |
| Hub Bearing and Backing Plate Replacement..... | 01/22 |
| Transmission Oil Residue, New Vehicles..... | 06/22 |
| Crankshaft Position Sensor Plate Installation & Damage..... | 09/22 |
| AT Learning Control Revisited (Relearn)..... | 12/22 |
| Torque Converter Relearn Procedure | 12/23 |

04-Steering

| | |
|---|-------|
| Loyale Power Steering Pump Failures..... | 05/91 |
| XT-6 Mps Controller Set..... | 01/92 |
| XT-6 Electronic Controlled Motor Drive Power Steering Service Manual Supplement | 04/92 |
| XT-6 Motor Power Steering “Motor Pump” | 05/92 |
| All Models Power Steering Pumps..... | 06/92 |
| Testing Power Steering Pumps | 06/93 |
| SVX Power Steering Pump Replacement | 02/94 |
| Steering Rack Noise..... | 01/97 |
| Power Steering Pump Replacement | 03/97 |
| 2004MY Impreza and Forester Steering Column Cover | 10/03 |
| Parts Ordering Update for VSC Steering Angle Sensor..... | 10/03 |
| Power Steering Rack Repairs | 11/05 |
| 2006MY STI Steering Angle Sensor..... | 02/06 |
| Power Steering Pump Noise | 04/07 |
| 2005 & Later SIA-Built Steering Rack Rebuilding Tool Info | 10/08 |
| Power Steering Rack Serviceability | 06/11 |
| Electronic Power Steering | 10/14 |
| Electronic Power Steering Concerns or DTCs | 12/23 |
| C254E, Inspection Mode B, End Stop Learning..... | 03/25 |

05-Suspension-Wheels & Tires

05-Suspension-Wheels & Tires

| | |
|---|-------|
| Legacy Rear Stabilizer Link Bushing Seat Change | 07/91 |
| Loyale Rear Alignment | 10/91 |
| All Models Alignment (Front & Rear) Tips | 02/92 |
| Legacy 4WD Noise Coming From Right or Left Rear Area | 10/92 |
| Legacy Front End “Pop” Noise | 10/92 |
| All Four-Wheel Drive Vehicles | 11/92 |
| All Models Wheel Lug Torque | 11/92 |
| 1993MY Impreza Rear Suspension “Passive Four Wheel Steering” | 05/93 |
| All Subaru Models with Air Suspension, Including Legacy (“O” Rings) | 06/93 |
| Production Line Installation of Oil Filter and Power Steering Reservoir Filling | 06/93 |
| All Subaru Models Front End Alignment | 08/93 |
| 1992MY SVX Rear Suspension | 08/93 |
| Impreza Wheels - 13” vs. 14” | 01/94 |
| Impreza Rear Strut Noise Production Change | 02/94 |
| 1991MY Legacy Complaint of Banging Over Bumps, Especially Prevalent In the Right Rear | 03/94 |
| Impreza Rear Strut Noise Production Change | 04/94 |
| Impreza Tire Rotation/Maintenance | 06/94 |
| Procedures for Yokohama Tire Complaints | 02/95 |
| Noisy Impreza Rear Struts | 09/95 |
| Front Suspension Noise, 1995/96MY Subaru Legacy | 04/96 |
| Impreza Outback Tires | 09/96 |
| 1996MY & 1997MY 2.2L Manual Transmission Equipped Vehicle | 09/96 |
| Additional Tire Information For ‘97MY Impreza Outback | 11/96 |
| Axle Shaft Grease | 08/99 |
| Recommended Winter Tires for 2000MY Outback | 01/00 |
| 2000MY Outback Winter (Snow) Tire Information (supplemental) | 03/00 |
| Tire Questions and Information Handling Procedures | 09/01 |
| WRX and STI Recommended Winter/Snow Tires | 11/03 |
| Stick-On Wheel Weights | 09/04 |
| 2003MY Keyless Entry Control Module Interchangeability | 09/04 |
| Tire Pressure Monitoring System | 10/04 |
| 2005MY Legacy/Outback – Use of Tire Chains | 12/04 |
| Tire Pressure Monitoring System (TPMS) Equipped Vehicles | 12/04 |
| STi Clunk Noise in Rear | 02/05 |
| Rear Stabilizer Link Positioning | 10/05 |
| Tire Pressure Monitoring System – A Reminder | 11/05 |
| B9 Tribeca Spare Tire Availability | 02/06 |
| Tire Pressure Monitoring System (TPMS) – Additional Information | 03/06 |
| Tire Valve Stem Caps | 03/06 |
| 2005~06MY Legacy/Outback Lower Control Arm Bushings | 05/06 |
| TPMS Valve Core Tool | 06/06 |
| B9 Tribeca Torque Support Plate Revised Torque Specification | 08/06 |
| Oil Seepage / Leaking From Struts | 01/07 |
| Customer Concern about Tire Conicity & Vehicle Drift | 02/07 |
| 2008 MY Tire Pressure Monitor (TPMS) Changes | 05/07 |
| Emergency Wheel Lock Removal | 06/07 |
| Wheel Lug Torque Specs | 11/07 |
| Use of Nitrogen in the Tires of Subaru Vehicles | 12/08 |
| 2010-11 Legacy / Outback Steering Vibration Updates: Helpful Hints | 09/10 |
| Tire Pressure Monitor System Reminders | 10/10 |

05-Suspension-Wheels & Tires

| | |
|--|-------|
| 2011 M/Y Tire Pressure Monitor System “Quick TIP” | 11/10 |
| Rear Stabilizer Bar Identification | 03/11 |
| Front / Rear Suspension Strut Piston Seal Damage | 11/11 |
| Front-End Rattling Noises Over Bumps | 11/11 |
| Tribeca Spare Tire Color Change | 10/12 |
| 2005 And Up Front Lower Control Arm Bushings..... | 05/13 |
| Tire Pressures-Check that Spare | 11/13 |
| Wheel Lug Socket Recommendation..... | 03/14 |
| Abnormal Noise Diagnosis | 07/16 |
| New Model Alignment Specifications | 11/18 |
| Abnormal Noise Diagnosis | 12/18 |
| 2019 Ascent Noise from Rear Over Rough Roads..... | 10/19 |
| New Model Alignment Specifications | 02/20 |
| C2921 and Intermittent TPMS DTC Diagnosis | 04/20 |
| Abnormal Noise Diagnosis | 01/21 |
| Front Lower Control Arm Bushing Repair Procedure | 03/21 |
| AWD light flashing, STI & WRX..... | 05/21 |
| Noises from Strut Area..... | 07/21 |
| TPMS Sensor Installation | 12/21 |
| Flat Spots and Road Force Tire Balance | 02/22 |
| Ascent Noise from Rear Over Bumps or When Turning..... | 07/22 |
| Wilderness (Outback/Forester) & Outback Onyx XT Model 5 Wheel Tire Rotation..... | 02/23 |

06-Brakes

| | |
|---|-------|
| Legacy ABS Control Unit Code 10 | 01/92 |
| ABS Light Illumination Code 16 (G-Sensor) | 02/92 |
| Legacy Brake Vibration Complaints | 06/92 |
| Legacy Front Disc Brake Pad Wear | 11/92 |
| Legacy Right-Hand Drive Vehicles | 12/92 |
| Legacy ABS-2E System | 02/93 |
| Anti-Lock Brakes For Legacy | 03/93 |
| Legacy Brake Pads | 10/93 |
| 1994MY Impreza Hill Holder "Ghost Cars" | 01/94 |
| Legacy Brake Rotors | 02/94 |
| Impreza Throttle Position Switch Adjustment | 06/94 |
| Non-Approved Adjustments on Legacy, Impreza, & SVX Throttle Plates and ISC Valves | 06/94 |
| Rusty Brake Rotors | 07/94 |
| Brake Rotor Machining With Pro-Cut Equipment | 08/94 |
| TCS Operation with 'T-Type' Spare | 10/94 |
| ABS Code 16 - Faulty ABS Control Unit or 'G' Sensor (AWD, M/T Model) | 10/94 |
| Reading ABS Codes on Early Subaru Legacy Models | 07/95 |
| Subaru Legacy - ABS Light on | 08/95 |
| Brake Fluid Basics | 09/95 |
| ABS And Select Monitor Usage | 09/95 |
| ABS/TCS Equipped Legacy Vehicles | 10/95 |
| 1995MY/1996MY Subaru Legacy with ABS | 11/95 |
| 1996MY Subaru Legacy Equipped With ABS/5.3 System | 11/95 |
| ABS-2E Control Units & ABS Code 23 | 12/95 |
| Vehicle Not Complying With Federal & State Regulations | 12/95 |
| Intermittent Wheel Sensor Codes in Early Legacy ABS Systems (Non ABS-2E) | 12/95 |
| Brake Noise...What Is Normal? | 02/96 |
| 5.3 ABS System Service Manual | 06/96 |
| Component Relocation with 5.3 ABS System | 06/96 |
| ABS Equipped Subaru Vehicles System Check | 08/96 |
| New 5.3I Type ABS System | 02/97 |
| 5.3I ABS System Information Update | 03/97 |
| ABS 5.3I Service Manual | 04/97 |
| Identifying ABS Systems | 05/97 |
| ABS 5.3I ABS Warning Light Operation | 10/97 |
| ABS/TCS Code 57 | 01/98 |
| Use of Non-Approved Brake Additives | 05/98 |
| 1999MY Forester ABS | 02/99 |
| Brake Judder & Noise; All Models | 03/99 |
| 2002MY Impreza Brake Rotor Scoring..... | 06/01 |
| Bulletin Numbers 03-31-03 & PT 370303..... | 01/04 |
| Bleeding Brembo Brake System on WRX STI Models..... | 03/04 |
| STI Brake Shim Kit | 09/04 |
| Brake Pad Wear Indicator | 03/05 |
| B9 Tribeca Brake Servicing | 05/05 |
| Preventive Measure for Surface Rust around Disk Brake Pad..... | 05/06 |
| Brake Rotor Concentric Scaring | 01/07 |
| VDC Control Module Servicing | 09/07 |
| ABS Code C0111- ABS Motor Relay Function | 12/07 |
| ABS / VDC Detail Codes and How to Use Them | 03/08 |

06-Brakes

| | |
|--|-------|
| New TPMS Transmitter Design Reminders..... | 06/08 |
| Brake Rotor Information | 12/08 |
| Tapping or Clicking Noise, 2008-09 Impreza..... | 03/09 |
| Brembo-Equipped Disc Brake Noise | 03/09 |
| More C0054 & C0074 Information..... | 04/09 |
| EPB Emergency Manual Release Procedure | 11/09 |
| 2010 M/Y Legacy & Outback Master Cylinder Removal Precaution..... | 02/10 |
| “Click or Knock” Sound When Releasing the Brake Pedal..... | 05/10 |
| WVY-35 Master Cylinder Installation Precaution | 01/12 |
| ABS Brake System Applied Model Information | 03/12 |
| Vehicles Equipped with Eyesight..... | 07/12 |
| Important Precautions For Eyesight Equipped Vehicles | 08/12 |
| 13 BRZ Revised Vehicle Stability Control Diagnostics..... | 11/12 |
| 12/13 Impreza Parking Brake Information | 11/12 |
| EyeSight System Temporary Stop Information | 02/13 |
| Click Or Knock Sound When Releasing The Brake Pedal (Reminder) | 02/13 |
| Proper Reporting of Eyesight Related Issues | 04/13 |
| Precautions & Diagnostic Tips for Eyesight Equipped Vehicles..... | 04/13 |
| Brake Override System Operation and Hesitation Complaints..... | 11/13 |
| 2015 Legacy and Outback Electronic Parking Brake Codes C1956 or C1957..... | 08/14 |
| What’s That Green Stuff under the Master Cylinder Reservoir Cap | 05/15 |
| Brake Fluid Color Change | 07/15 |
| Hill Holder or Parking Brake (EPB) Won’t Release | 11/15 |
| Eyesight Replacement Parts | 08/16 |
| 2017 Reverse Automatic Braking (RAB), Red Area Appears In Back-Up Camera Display | 01/17 |
| Hill Start Assist Light On but No Codes..... | 03/17 |
| 2017 Impreza Brake Caliper Oil Residue..... | 11/17 |
| Tap or Click – Type Sound Heard When Coming to a Stop – 2019MY Ascent | 01/19 |
| C0271 After Park Brake Actuator Replacement..... | 02/19 |
| Reverse Automatic Braking (RAB)- Important Information | 10/19 |
| 2017 and Up Impreza Brake Caliper Assembly Oil Residue | 12/19 |
| 2018+ STI Green Brake Caliper Discoloration..... | 09/20 |
| VDC Control Module Replacement Followed by SRH Warning Light Information..... | 01/21 |
| C1921 – Electronic Parking Brake Inoperative | 02/21 |
| One-Time Use Bolts for the Brake Caliper Support | 09/22 |

07-Electrical

| | |
|---|-------|
| Justy ECVT/Ignition Relay | 07/91 |
| Legacy Intermittent Hard Or No Start/Ground Shock Tower | 07/91 |
| Legacy Ignition Relay | 07/91 |
| Justy MPI Codes 11, 13 | 07/91 |
| Phantom Code 22, Knock Sensor 87-89MY "L" And XT Series..... | 09/91 |
| A/T Shift Lock System/Loyale | 12/91 |
| L-Series OHV Engine-Engine Will Not Shut-Off | 01/92 |
| SVX and Legacy Brake Lights Staying On | 01/92 |
| Legacy Poor Radio Reception/Low Volume Output | 03/92 |
| 90MY to Present Justy MPI Distributor Wiring | 04/92 |
| Legacy S/W Fuse No.5 Continually Blows-Out | 05/92 |
| Legacy Sunvisor Lighted Mirror Wiring #15 Fuse | 05/92 |
| Legacy Starters | 10/92 |
| 1992 MY Legacy & SVX Ignition Relay | 10/92 |
| Aftermarket Batteries | 11/92 |
| 1992MY SIA Legacy S/W Rear Gate Telltale Light Won't Go Out | 11/92 |
| Justy Trouble Code 23: Pressure Sensor | 01/93 |
| 1993MY Impreza Relays | 05/93 |
| Electrical Tips | 07/93 |
| Legacy Sunroof Wiring Schematic & Switch Operation | 09/93 |
| Electrical Problems? Check the Fuse | 10/93 |
| Impreza Headlamp Information | 10/93 |
| 1990MY Legacy with Code 41 in ECU Memory | 11/93 |
| 1990MY Legacy Code 42 Throttle Position Switch from ECM | 11/93 |
| ROM Application Chart | 11/93 |
| 1993MY Loyale Intermittent Wiper Wiring Diagram | 01/94 |
| Six-Step Troubleshooting Method | 02/94 |
| Rear Defogger Wiring & Terminal Repair Kit | 02/94 |
| 1990MY-Present Loyale Fuel Pump Control Unit Wiring Diagram | 03/94 |
| 1992MY SVX ROMS | 03/94 |
| Battery Charging | 03/94 |
| ECVT Trouble Code 31 | 04/94 |
| ECVT - Select Monitor Speed Sensor Reading | 04/94 |
| Impreza Headlights | 04/94 |
| Legacy Fuel System Wiring Diagram | 05/94 |
| Impreza Fuel Tank Sending Unit Specifications | 05/94 |
| 1995MY Legacy Electrical Component Location Quick Reference List | 07/94 |
| Legacy Fuel System Wiring Diagram | 08/94 |
| SVX Spark Plug Servicing | 09/94 |
| Ignition Relays | 10/94 |
| Ignition Relays - The Sequel | 10/94 |
| 1995MY Legacy Speed Limiting Device | 11/94 |
| SPI Trouble Code 13 (Crank Angle Sensor) From ECU | 11/94 |
| OBD II Check Engine Light | 12/94 |
| Speed Sensor 2 | 01/95 |
| 1994MY Legacy Seat Heaters | 01/95 |
| Cold Shift Locks (Impreza Shift Locks That Won't Unlock When Cold) | 02/95 |
| 1985MY & Later L-Series MPFI Improper Engine Operation above 2000 RPM | 03/95 |
| Battery Replacement | 03/95 |
| Electrical Diagnosis, the Helpline, & You | 04/95 |

07-Electrical

| | |
|---|----------|
| Battery Charging | 05/95 |
| Electrical Condition Reporting | 06/95 |
| ROM Installation | 08/95 |
| 1 Mw Min. | 09/95 |
| 1996MY Subaru Legacy Outback Fog Lamps | 10/95 |
| 1995MY Subaru Legacy Outback Rear Power Outlet | 11/95 |
| Identification of Cam and Crank Sensors | 07/96 |
| 1995MY/96MY Subaru Legacy Blows Fuse SBF-2 | 07/96 |
| 1997MY Legacy Power Door Lock System | 09/96 |
| Sticking or Difficult Auto Down P/W Switch Buttons (Mistakenly Printed In Section 11) | 10/96 |
| Diagnostic Trouble Code P0341 | 10/96 |
| Loose Window Regulators | 10/96 |
| Rear Defogger Timer | 03/97 |
| Legacy Heater Control Panel Bulbs | 03/97 |
| '98MY Forester Transit Connector Location | 08/97 |
| '98MY Forester Trailer Hitch Wiring Harness | 08/97 |
| '95MY-'97MY Legacy Moisture Accumulation in the Headlights | 04/98 |
| 2000MY Legacy Battery | 09/99 |
| Wiring Harness Connector I5 | 09/99 |
| Electrical Problems? Check The Alternator. | 11/99 |
| 2000MY Legacy Blows Fuse #5..... | 01/00 |
| 2000MY Subaru Legacy Turn Signal Operation..... | 02/00 |
| 2000MY Legacy & Outback Vehicles Fog Light Operation..... | 04/00 |
| Grounds, Grounds, Grounds..... | 07/00 |
| Daytime Running Lights | 08/00 |
| Windshield Wiper Deicer System not Working | 11/00 |
| Turn Signals Flashing Rapidly | 11/00 |
| Blower Motor Resistor Repairs | 01/01 |
| In-Dash Cigarette Lighter Usage..... | 06/01 |
| Alternator Supplier Update..... | 08/01 |
| Legacy Transit (D-check plug) Connectors..... | 03-04/02 |
| Fuse 4 Blows-Out..... | 03-04/02 |
| Legacy Rear Wiper Operation..... | 03-04/02 |
| 2005MY Legacy/Outback Trailer Hitch Harness Location | 07/05 |
| Backup Power Supply Fuse | 10/05 |
| 2005MY Forester Diagnostic Connector..... | 11/04 |
| 2005MY Legacy/Outback Electrical Diagnosis | 02/05 |
| Body Integrated Unit (BIU) Replacement | 03/05 |
| Fuse Label Correction..... | 03/05 |
| HVAC & Audio Unit Inoperative After Wiring Harness Change | 04/05 |
| 2005MY Baja with Poor Radio Reception..... | 04/05 |
| HVAC Inoperative After Wiring Harness Change—More Information | 05/05 |
| 2003MY Forester Fuse Information..... | 08/05 |
| Battery Going Dead or Alarm Going Off | 09/05 |
| Information Requested For Harness Repair Kits..... | 11/05 |
| 2006MY Legacy/Outback and B9 Tribeca Combination Meter Self Diagnosis | 02/06 |
| Change of Seat Heater Relay | 02/06 |
| Low Battery Voltage | 06/06 |
| 2005MY Forester A/F & O2 Sensor Relay Location..... | 06/06 |
| SBF-5 Fuse Blows On 2005 MY / 2006 MY Impreza Vehicles..... | 07/06 |
| “Dark Current” Or Excessive Battery Draw..... | 02/07 |
| Erratic Tail Light Operation..... | 04/07 |

07-Electrical

| | |
|--|-------|
| More “Dark Current” Information | 04/07 |
| Headlight Bulb Replacements –A Reminder | 05/07 |
| New Style 2008 MY Legacy, Outback & Tribeca Keys..... | 06/07 |
| Midtronics inTELLECT EXP Battery Tester Logic Update | 06/07 |
| Headlight Bulb Socket Repairs | 07/07 |
| 2008 MY High Security Keys..... | 08/07 |
| 2008MY Impreza Headlight Switch Operation..... | 09/07 |
| 2008 Impreza Stop Light Switch C0074 and C0054 | 01/08 |
| BIU Replacement and Keys | 05/08 |
| 2008 Impreza Data Link Connector Color Change | 06/08 |
| Legacy & Outback Door Switch (Nov 2004 production & after)..... | 06/08 |
| Wiring Harness Connector Similarities & Cautions | 07/08 |
| Forester Sunroof Reverses When Closing | 12/08 |
| 2008-09 Impreza, Erratic Outside Temperature Gauge Operation | 01/09 |
| Door & Ignition Lock Cylinder Replacement Clarification | 02/09 |
| 2009 M/Y Forester Power Window Information | 03/09 |
| Power Door Locks Inoperative, 2009 M/Y Forester | 04/09 |
| “Dark Current”Revisited..... | 06/09 |
| 2010 M/Y Legacy & Outback Auto Up / Down Feature Operation..... | 08/09 |
| Speedometer Inoperative? Don’t Overlook the Sunroof Wiring | 08/09 |
| 2010 M/Y Legacy & Outback Low-Beam Bulb Replacement | 08/09 |
| 2010 M/Y Legacy & Outback Headlight Bulb Replacement Information | 09/09 |
| 2010 M/Y Legacy & Outback Power Window Operation | 10/09 |
| Re-Coding Laser-Cut Keys | 01/10 |
| 2010 M/Y Legacy & Outback Oil Level Warning Information | 02/10 |
| 2010 M/Y Legacy & Outback BIU Interchangeability | 02/10 |
| 2010 M/Y Forester “Resonating” Noise When Using the Horn..... | 03/10 |
| 2010 M/Y Forester Dome Light Erratic Operation..... | 05/10 |
| 2010 and 2011 Driver’s AUTO-UP Reset Information..... | 10/10 |
| 2008 – 2011 Impreza Front Turn Signals Blink Too Fast..... | 01/11 |
| Remote Trunk Release Inoperative After BIU Replacement | 05/11 |
| 2008 M/Y and Later Impreza Stop Light Switch Information..... | 05/11 |
| Sunroof Operation Service Bulletins | 05/11 |
| New DTC’s After Bulkhead Harness Replacement | 06/11 |
| CAN System Diagnostic Information..... | 07/11 |
| Immobilizer Codes Stored, Engine Starts and Stalls Condition..... | 08/11 |
| 2011 M/Y Impreza High Beams Not Bright Enough? | 10/11 |
| Headlight Aiming Precautions | 11/11 |
| Tom-Tom Equipped Volume Control Information | 12/11 |
| 2012 M/Y Impreza No Start, SBF-6 Blown | 01/12 |
| 2012 Impreza Key Information..... | 03/12 |
| Sunroofs and Car Washes | 04/12 |
| Battery Testing, the Importance of Using the Right Standard | 04/12 |
| Re-Programming Information for All 2011-12 M/Y Vehicles | 05/12 |
| 2013 BRZ Auto Up/Down Window Feature | 09/12 |
| Hard To Fill Fuel Tank | 09/12 |
| Eyesight Camera Adjustment..... | 10/12 |
| 13 MY Legacy And Outback Accessory Charging..... | 11/12 |
| Electrical Devices And Air Bag Systems..... | 12/12 |
| 14 MY Forester Turbo Battery Cable Precaution/ DTC P0606..... | 02/13 |
| Appearance of Water in BRZ Back Up Light..... | 03/13 |
| Memory Height Learning Procedure | 04/13 |

07-Electrical

| | |
|---|-------|
| Erratic Digital Fuel Gauge Operation, 2012 My and Later Impreza, BRZ, and 2014 Forester..... | 04/13 |
| Immobilizer/ Key Registration Information | 04/13 |
| 2014 Forester Information Display Selection Knob(or the Right Side or Other Trip Knob) | 04/13 |
| Campaign WQF-42 Information | 05/13 |
| Fuel Gauge Diagnostic's..... | 05/13 |
| 2014 Forester Turbo, ECM Electrical Testing Reminder | 06/13 |
| 2014 Forester Power Rear Gate (PRG) Initialization Procedure..... | 06/13 |
| 2014 Forester Non-Turbo ECM And BIU Locations..... | 06/13 |
| 2014 Forester L/F Power Window auto up/down operation..... | 08/13 |
| HVAC Electrical Connections | 09/13 |
| BIU Replacement on all Push-button Start Vehicles | 10/13 |
| 2014 Forester Seat heater Operation and Switch Functions..... | 11/13 |
| Headlight Adjustment Reminders | 11/13 |
| ODS Code 29 or 37, Electrical Devices and Air Bags revisited..... | 12/13 |
| Appearance of Water Droplets in BRZ Exterior Lamps | 01/14 |
| Important Hybrid Vehicle Aux Battery Precautions..... | 01/14 |
| Operation of SI-Drive, Sport Sharp(S+) Mode after Cold Start..... | 02/14 |
| Midtronics GR8Use During Control unit Programming..... | 02/14 |
| 2010-14 Legacy& Outback Fuse # 16 Failed in the Main Fuse Box..... | 03/14 |
| DTC P0724, Brake Switch Circuit High Input | 03/14 |
| Passenger Side Power Window Auto Up/Down Function..... | 08/14 |
| 2015 Legacy/Outback Power Window Auto Up/Down Operation Revisited | 09/14 |
| 2015MY Legacy and Outback Under Hood Main Fuse Box (M/B) Information | 09/14 |
| 2015 Legacy and Outback Cold Weather Light Operation | 10/14 |
| 2015 Legacy and Outback Under-Hood Main Fuse Box (M/B) Information..... | 10/14 |
| 2015 Legacy and Outback Keyhole Shadow From Projector Beam Headlamp..... | 10/14 |
| Dark Current Draw Revisited..... | 11/14 |
| Bluetooth Pre-Call Worksheet..... | 11/14 |
| 2015 Legacy/Outback Unnecessary Power Window Switch Replacements | 12/14 |
| Body Integrated Unit (BIU) Replacement/ Interior Lights Flashing | 01/15 |
| Identifying Electrical Harness Connectors..... | 04/15 |
| Electrical Diagnosis and Aftermarket Equipment..... | 04/15 |
| DTC Diagnosis and Related Wiring Harness Checks..... | 05/15 |
| 2010-2016 Forester TPMS light flashing, Sensor Registration Issues | 09/15 |
| Spark Plug Information a Reminder | 03/16 |
| Battery Servicing Precautions..... | 03/16 |
| GR-8 1100 EST Battery Diagnostic Station, Power Supply Mode | 05/16 |
| No Crank No Start Diagnosis | 06/16 |
| Blue-Tooth Pre-call Worksheet..... | 07/16 |
| Ignition Key Cannot Be Removed From Ignition Switch | 10/16 |
| Quick Reference Immobilizer Type..... | 10/16 |
| Replacing B-Type BIU | 10/16 |
| Fuel Gauge Diagnosis Revisited..... | 11/16 |
| Power Window erratic, cannot program memory | 01/17 |
| No Hybrid Auto Start Stop or Ev Travel..... | 01/17 |
| BIU replacement..... | 01/17 |
| Satellite Signal Lost When Traveling South 2014-UP Forester..... | 02/17 |
| PAK file error messages | 05/17 |
| B1650 Proper Diagnosis..... | 06/17 |
| Blind Spot Detection Off | 01/18 |
| Ground Circuit Identification | 03/18 |
| No Hybrid Auto Start Stop or EV Travel | 03/18 |

07-Electrical

| | |
|---|-------|
| ECM Reprogramming..... | 05/18 |
| Audio Unit Service/Diagnostic Menu | 06/18 |
| Quick Reference Immobilizer Type..... | 08/18 |
| Replacing B-Type BIU | 08/18 |
| Ascent Automatic Wiper Rain Sensor Initialization | 10/18 |
| 2019MY Forester, Driver Monitoring System (DMS) Inoperative | 11/18 |
| 2019MY Forester, Loose Negative Battery Cable/Terminal Connections..... | 11/18 |
| Performing Variant Work When Replacing Combination Meter | 12/18 |
| Automatic Start-Stop System Enable Conditions | 12/18 |
| 2019MY Forester, Driver Monitoring System (DMS) Inoperative *UPDATE* | 01/19 |
| Gen 3 Clock Related Concern | 02/19 |
| 2018 – 19MY Legacy & Outback – B1650 | 02/19 |
| 2019MY Forester- Rear Seat Heaters Inoperative..... | 03/19 |
| 2019MY Forester- Automatic Seat Retraction Feature Operation..... | 03/19 |
| Electrical Diagnosis and Aftermarket Equipment..... | 03/19 |
| 2019MY Forester, Driver Monitoring System (DMS) Inoperative B2632 B2642 | 04/19 |
| Hill Start Assist Lamp Illuminated Without Associated DTCs or Customer’s Concern..... | 04/19 |
| 2019MY Forester Manual Override for Power Rear Gate | 05/19 |
| 2019MY WRX, Telematics “i” Button Sticking..... | 05/19 |
| Identical Electrical Connectors | 06/19 |
| 2019 Forester Door Mirror Reverse Tilt-Down Feature..... | 06/19 |
| 2020MY Legacy & Outback, DTCs B2259, B2244, B282C, & B2C22 | 11/19 |
| Midtronics DSS-5000 and DCA-8000 Tips and Tricks | 12/19 |
| Mirror Tilt Inoperative | 01/20 |
| Revised Ascent Sunroof Glass (Lid) and Sun Shade Initialization Procedures..... | 01/20 |
| Change of Length of ECM Calibration ID (CID) Numbers | 01/20 |
| 2019MY and up Forester MFD Displays Incorrect Vehicle Angle..... | 02/20 |
| Ascent Sunroof and Sunshade Motors | 02/20 |
| Power Rear Gate (PRG) Inoperative with Ignition ON and / or Engine Running..... | 02/20 |
| Flashing Lights on Rain Sensor Equipped Vehicles | 03/20 |
| Heated Seat Operation..... | 03/20 |
| Parasitic Draw (Dark Current) Testing and Telematics DCM..... | 05/20 |
| Replacing B/G-Type BIU | 09/20 |
| G and H Type Immobilizer Registration | 10/20 |
| Identical Electrical Connectors | 10/20 |
| Electrical Connector & Pin Discrepancy | 11/20 |
| WRE-21 Ignition Coil Connector Removal and Wire Clip Loss – How to Repair | 05/21 |
| Auto Headlight Strategy Logic from My19+ Foresters | 07/21 |
| Power door lock inoperative, erratic or rapid operation (All Models) | 07/21 |
| Door Lock Battery Back Up Unit..... | 08/21 |
| Infotainment Continues to Play at Key Off and Door Open (All models)..... | 09/21 |
| Diagnosing Network U-Codes | 10/21 |
| Parasitic Draw Testing, A Different Approach..... | 10/21 |
| Erratic Digital Fuel Gauge Operation, 2012MY and later Impreza, BRZ and 2014MY Forester | 11/21 |
| Fuel Gauge Discrepancy, not reading correctly | 11/21 |
| Lane Keep Assist Inoperative, Even When Set To “ON” | 12/21 |
| Wiring Harness Ground Bolt Torque Spec..... | 01/22 |
| Check Board Harness Diagnosis | 03/22 |
| Headlight appearance “Dark spot in headlight patterns” | 04/22 |
| 2019MY(+) Hybrid Inverter Cable Installation | 08/22 |
| 2010-2018 Forester TPMS light flashing, Sensor Registration Issues..... | 08/22 |
| Replacing B/G-Type BIU | 09/22 |

07-Electrical

| | |
|--|-------|
| Identical Connectors Revisited, Again! | 10/22 |
| CAN Communication Diagnosis – Where to Start?..... | 01/23 |
| BIU Replacement TIPS and Destination Setting | 01/23 |
| Diagnosing Network U-Codes | 02/23 |
| Parasitic Draw (Dark Current) Diagnostics..... | 03/23 |
| Installing Window Tint & Applying Water Inside a Vehicle (Brake lights stay on) | 04/23 |
| DTCs, Crank/No Start, Key “chip” falls out, BIU..... | 05/23 |
| Door Lock Backup Unit Revisited – Door locks inop afte the vehicle is shut off..... | 07/23 |
| Security Alarm Operation History | 03/24 |
| 2025 Forester Battery Tray | 06/24 |
| Parasitic Draw From The PRG Latch – Check The Root Cause!..... | 07/24 |
| Thinking, The Service Manual, and The Use Of Diagnostic Flow Charts | 08/24 |
| Smart Charging and Battery Voltage | 08/24 |
| Circuit vs Fuse Number | 09/24 |
| Driver Monitor and Seat Memory Won’t Set (B2642, B2632, U0208) | 0/24 |
| Blower Outlet Request Temperature, HVAC CM PIDS..... | 02/25 |
| Replacing B-type and G-type BIU..... | 05/25 |
| Dark Current (Parasitic Draw) Testing on Subaru Solterra..... | 05/25 |
| Simultaneous Multiple System Monitoring..... | 06/25 |
| 2025 Forester PRG Switch Design Change..... | 06/25 |
| Front Door Power Window Erratic Operation 19-25 Ascent 20-25 Legacy & Outback..... | 06/25 |
| Driver’s Seat Automatic Retract Seat On Entry Feature..... | 07/25 |
| Excessive Dark Current/Parasitic Draw Due to Vehicle Communication Network Activity..... | 08/25 |
| 2025 Outback PRG Switch Design Change..... | 08/25 |

08-Instrument & Controls

| | |
|---|-------|
| High Reading Temperature Gauge, Digital Dash 85MY & 86MY “L” Series, Including XT | 08/91 |
| L-Series Speed Sensor Replacement | 02/92 |
| 1992MY Legacy FWD Modified Fuel Tank Sender Unit | 09/92 |
| Corrections to Previous Helpline Updates | 11/92 |
| Odometer Labels | 02/93 |
| Legacy Knock Sensor Testing | 03/93 |
| Legacy All Wheel Drive Fuel Gauge | 04/93 |
| Impreza Combination Meter Tachometer | 05/93 |
| Legacy Postal Vehicles with Single Action Power Door Locks | 11/93 |
| Speedometer Inaccuracies | 01/95 |
| Warning Light Operation | 02/95 |
| Legacy and Impreza Fuel Tank Sending Units | 05/95 |
| Instrument Cluster Circuit Boards | 10/96 |
| Fuel Gauges on “E” | 10/96 |
| 1998MY Subaru Forester/Impreza Digital Odometer | 09/97 |
| Odometer Policy..... | 02/01 |
| Ambient Temperature Sensor | 04/04 |
| SI-Drive Multi-Information Clock Display Characteristics..... | 04/08 |
| 2010 M/Y Legacy & Outback Clock Setting Procedure..... | 08/09 |
| Adjusting the Clock and Settings of the Multi-Function Display..... | 05/10 |
| Shift Indicator Light Applicability, 2012M/Y Impreza | 04/12 |
| BRZ Trunk Release Operation..... | 07/12 |
| Navigation Screen Displaying The Language Menu | 11/12 |
| 2014 Forester Multi Function Display Messages..... | 08/13 |
| 2015MY Legacy/Outback, Journey Time Alert on Combination Meter Tell tail Display | 09/15 |
| Resetting Applied Model & Option Codes for Combination Meters | 12/19 |
| Combination Meter Settings: Kilometers to Miles..... | 05/20 |
| Reading and Writing of the ECU Configuration and Odometer Value Clarification..... | 06/20 |
| 2015MY Legacy/Outback, Journey Time Alert on Combination Meter Telltale Display | 06/22 |

09-Cooling, Fuel, & Exhaust System

09-Cooling, Fuel, & Exhaust System

| | |
|--|----------|
| Justy FWD-ECVT Noise from Exhaust Pipe Joint | 05/91 |
| Legacy 4EAT Radiators | 02/92 |
| Subaru Exhaust Systems | 04/92 |
| 1992MY SIA Models Production Fuel Filter | 05/92 |
| Legacy Exhaust Whistle Turbo & Naturally Aspirated | 06/92 |
| 1992MY Legacy FWD Modified Fuel Tank Sender Unit | 09/92 |
| Corrections to Previous Helpline Updates | 11/92 |
| Coolant Recycling | 06/93 |
| Summer Low RVP Fuels | 06/94 |
| Fuel Quality Check | 06/94 |
| Fuel Switching | 09/94 |
| Impreza Fuel Tank Sending Unit Assemblies | 09/94 |
| Impreza Fuel Tank Capacity | 10/94 |
| Replacing Loyale Thermostats | 11/94 |
| 2.2L Impreza AWD Fuel Senders | 04/95 |
| Reformulated Gasoline | 05/95 |
| Loyale Water Pump Leaks | 07/95 |
| Modified Fuel Injectors | 10/96 |
| Cooling Fan Operation | 09/97 |
| 1999MY Legacy Excessive Crank Time | 03/99 |
| Vehicle Won't Take Fuel | 03/99 |
| Vehicles That Won't Take Fuel | 09/99 |
| Fuel System Quick Connector | 10/99 |
| Don't Touch That Screw! | 01/00 |
| Sulfur Smell from the Exhaust | 05/00 |
| Use of Genuine Air Cleaner Element..... | 11/00 |
| H-6 Extended Crank Time | 01-02/02 |
| Forester Fuel Line Noise..... | 09-10/02 |
| WRX STi Driveability..... | 08/03 |
| 2004MY Legacy Fuel Filter Replacement..... | 09/03 |
| H6 Drivability | 11/03 |
| New Product Orientation for the Cooling System Conditioner | 04/04 |
| 2004MY Legacy/Outback H-6 and H-4 (NA) Fuel Line Removal | 05/04 |
| 2005MY Legacy Fuel Line Rattle..... | 11/04 |
| Fuel Order in Cold Weather (Service Bulletin Reminder) | 11/04 |
| Fuel Line Tool | 12/04 |
| Gas Mileage | 03/05 |
| Fuel Hose Retainer Clips..... | 06/05 |
| B9 Tribeca Fuel Line Tool | 04/06 |
| Subaru Vehicles and Driveability..... | 09/06 |
| STI Models Fuel Recommendation | 11/06 |
| Fuel Odor on Initial Cold Starts..... | 02/07 |
| Engine Cooling System Service & Care Recommendations..... | 06/07 |
| Fuel-Related Driveability Concerns..... | 08/07 |
| Genuine Subaru Cooling System Conditioner Information | 10/07 |
| Subaru Super Coolant..... | 11/07 |
| P0171 and "Hard Start" Concerns | 12/07 |
| More Subaru Super Coolant Information | 03/08 |
| Wynn's Cooling System Equipment Announcement..... | 08/08 |
| "Back To Basics" Rattling Noises From Under the Car | 02/09 |

09-Cooling, Fuel, & Exhaust System

| | |
|--|-------|
| 2009 M/Y Forester Fuel Gauge Inconsistency | 02/09 |
| 2010 M/Y Impreza, Rattling Noise from Exhaust | 10/09 |
| More “Super Coolant” Information..... | 10/09 |
| WVJ-20 (Baja Fuel Pump Outlet Pipe) Revised Product Campaign Bulletin Information..... | 11/09 |
| 2011 M/Y Impreza Fuel Door Update | 12/10 |
| 2011 M/Y Forester Fuel Pressure Testing Information | 02/11 |
| Rough Idle Condition Following WVU-31 Reprogramming..... | 06/11 |
| DTC P0453 Diagnostic Information..... | 11/11 |
| FB Engine Fuel Pressure Testing Information | 03/12 |
| BRZ High Pressure Fuel Pump | 07/12 |
| BRZ Exhaust System Hardware..... | 08/12 |
| Radiator Leaks And Damage | 08/12 |
| Locksmith Information..... | 09/12 |
| Use of Dye In AC Systems | 09/12 |
| 12 Impreza Muffler Appearance Change | 10/12 |
| New Fuel With 15% Ethanol | 10/12 |
| AF sensor and O2 sensor Removal..... | 01/13 |
| New Fuel 15% Ethanol Reminder..... | 08/13 |
| Hard to Fill Fuel Tank Revisited | 12/14 |
| Cooling System Appears to be Overfilled at PDI | 06/15 |
| P05A0 and Active Grill Shutter Inspection | 01/17 |
| Fuel Tank Cannot be Filled | 07/17 |
| Won't Take Fuel Concerns – Revisited | 08/21 |
| DTC P26A3, P26A5, P26A7 Thermo Valve Diag, w/codes P2004, P2005, P0087,P088, P0091 | 12/22 |
| Low Pressue Fuel Line Connection..... | 08/23 |
| Won't Take Fuel Concerns – Revisited | 02/24 |
| DTC P0087 and/or Engine Runs Rough – Crosstrek and Impreza..... | 05/25 |

10-Heating Ventilation & A/C Systems

10-Heating Ventilation & A/C Systems

| | |
|--|-------|
| A/C Service Oil Adjustment | 06/91 |
| A/C Diagnostic Aids | 08/91 |
| A/C Pulser System Electrical Diagnosis 89MY & 90MY Loyale | 08/91 |
| 1992MY Legacy A/C Compressor Bracket Discontinuation | 11/91 |
| Justy Wynn's Air Conditioning Installation | 03/92 |
| The Use of A/C Refrigerants Other Than R-12 | 07/92 |
| Justy Air Conditioning Information | 07/92 |
| Air Conditioning Evaporator Odor | 08/92 |
| SVX Zexel Auto A/C | 09/92 |
| Legacy A/C Compressor | 10/92 |
| Legacy A/C Kit Supersession | 10/92 |
| HFC134a Air Conditioning Refrigerant | 02/93 |
| R134a Air Conditioner Refrigerant Service Bulletin | 03/93 |
| Legacy Zexel Air Conditioning | 04/93 |
| Legacy Compressor Belt Tension | 04/93 |
| 1993 MY Impreza Air Conditioning Inoperative | 07/93 |
| Loyale Factory Installed A/C Does Not Operate | 07/93 |
| HFC 134a Air Conditioning Systems | 07/93 |
| SVX Auto A/C Display Degrees Celsius to Degrees Fahrenheit | 11/93 |
| Bulletin 10-64-92 Heater Vent Door Binding or Leaking Air | 12/93 |
| Refrigerant Cross Contamination | 01/94 |
| 0Z-12: The Facts | 02/94 |
| SVX Complaints of No Heat from Dash Vents | 04/94 |
| 1995MY Impreza Coupe - Bubbles from the Dash Vents | 10/94 |
| A/C Reminder | 05/95 |
| PAG Oils | 05/95 |
| Air Conditioner Hoses | 08/95 |
| 1995MY RHD Postal Legacy Air Conditioning System | 08/95 |
| A/C System Diagnostic Tips | 08/95 |
| A/C Testing For System Leakage | 08/95 |
| SVX A/C Cutting out When Ambient Temperature Is Hot; SVX Engine Running Hot | 09/95 |
| SVX Evaporator Thermo Sensor, Intake Sensor | 10/95 |
| A/C Performance-All Models | 10/95 |
| Refrigerant Recovery and Recycling Certification | 06/96 |
| CFC R-12 Substitute Refrigerants | 06/96 |
| Refrigerant Substitutions Warning | 08/96 |
| SVX A/C Temperature Control Indicating Centigrade vs. Fahrenheit | 10/96 |
| A/C Odors | 05/97 |
| 1997MY Legacy A/C Seal Ring (Axis Seal) Change | 05/97 |
| 1998MY Subaru Forester Dash Vent Noise | 09/97 |
| 1998MY Subaru Forester Squeaking Noise with A/C on | 09/97 |
| Dust and Dirt Entering Rear of Vehicle | 11/97 |
| Subaru Impreza Center Dash Vent Airflow | 07/98 |
| Subaru A/C Retrofit Kits | 09/98 |
| Use of A/C Dyes in Subaru Air Conditioning Systems, Manufacturer's Recommendations | 09/98 |
| Seasonal Reminder | 05/99 |
| A/C Retrofit Kit Information | 07/99 |
| A/C Inoperative – Impreza/Forester Vehicles | 10/99 |
| 2000MY Legacy Heater Control Cables..... | 05/00 |
| 2001MY A/C Disconnect Procedure | 07/00 |

10-Heating Ventilation & A/C Systems

| | |
|---|----------|
| Mode Control Panel Change..... | 02/01 |
| 2001MY Legacy Evaporator Thermostat Probe Location | 07/01 |
| Legacy H6 A/C Compressor Cutting Out | 08/01 |
| Valeo/Zexel A/C TXV Fastener Torque Specification | 08/01 |
| H6 Climate Control System Information..... | 09/01 |
| Change To 2002MY Legacy/Outback A/C Information..... | 09/01 |
| 2001/2002MY Legacy Blower Motor Noise..... | 11/01 |
| Blower Motor Noise..... | 08/02 |
| Blower Motor Noise..... | 01-02/03 |
| Auto. A/C System Aspirator Tubes..... | 07/03 |
| Service Bulletin 10-72-02R – An Update..... | 10/03 |
| B9 Tribeca Air Conditioning Information | 09/05 |
| Water Leaking Onto Passenger Floor Board Area | 09/05 |
| Water Leaking From A/C Evaporator | 10/05 |
| 2005MY Legacy/Outback: Water Leaking from A/C Evaporator | 11/05 |
| 2005~06MY Legacy/Outback Center Dash Vent Temperature..... | 05/06 |
| B9 Tribeca Air Conditioning Information | 06/06 |
| H6 A/C Compressors Cutting Off | 06/06 |
| 06MY Impreza Models: Manual Climate Control System Air Flow Dial “Spring Back”..... | 07/06 |
| Refrigerant Dye Use to Detect Refrigerant Leaks | 10/06 |
| A/C Operation Logic Change for 2007MY | 11/06 |
| R134-A Recycling Recovery and Recharge Machines: New Manufacturing Standards..... | 12/06 |
| 2007 MY Forester A/C Compressor Changes | 04/07 |
| A/C Certification –It’s the Law | 04/07 |
| Erratic Dash Vent Temperatures..... | 02/08 |
| HVAC Servo Harness Connector Confusion..... | 01/09 |
| 2010 – 11 Legacy / Outback Vibration Felt in the Brake Pedal | 11/10 |
| Reminder- Use of A/C Leak Detection Dyes..... | 08/11 |
| Center Dash A/C Vents Closing, 2010-12 M/Y Legacy / Outback Models | 11/11 |
| 2013-14 Legacy and Outback Center Console Rear Air Vent Function..... | 03/14 |
| A/C Diagnosis | 07/17 |
| Condensation Inside Vehicles | 12/17 |
| R-134 A/C Oil Guidelines..... | 07/18 |
| B2242 Set With no Trouble Symptom | 02/19 |
| Recovery of Contaminated R-1234yf | 08/20 |
| 2020+ Legacy/Outback Passenger Air Mix and Intake Air Door Actuators | 10/20 |
| 20-21MY LGY/OBK, “Setting temperature shift” in A/C CM customization..... | 05/21 |
| 2022 WRX AC Condenser, Oil Residue | 04/22 |
| HVAC Temperature Sync..... | 03/23 |
| Air Conditioning Refrigerant Types | 07/23 |
| Intermittent A/C Concerns | 10/23 |
| Dynamic Ventilation Control-HVAC Controls Not Shown..... | 07/24 |

11-Emission Systems

| | |
|--|--------------|
| Justy "Check Engine" Light On/EGR Hose Pulling Off | 11/91 |
| ROM Reminder/Legacy A/T Vehicles | 12/91 |
| SVX Trouble Code 12 | 12/91 |
| SVX Code 37 O2 Sensor (LH) | 01/92 |
| L-Series SPI Code 34 (EGR Solenoid) | 02/92 |
| All Models False Trouble Codes | 04/92 |
| Legacy Turbo Sport Sedan Code 45 (Pressure Sensor, Pressure Exchange Solenoid Valve) | 06/92 |
| Legacy Code 32 O2 Sensor | 06/92 |
| Justy Code 13 | 08/92 |
| ROM Installation Tips | 09/92 |
| ECU Memory-All Models | 09/92 |
| Justy Trouble Code 23: Pressure Sensor | 01/93 |
| O2 Sensors for XT4 and XT6 Vehicles | 12/93 |
| Legacy Code 32 O2 Sensor | 03/94 |
| Carbureted Vehicles with ID Codes While Engine Is Running | 06/94 |
| OBD II - DTC P0441 "Evaporative Emission Control System Incorrect Purge Flow" | 11/94 |
| OBD II Test Drives | 11/94 |
| Legacy and Impreza Engines with No Injection Pulse #1 Cylinder | 03/95 |
| Impreza Air Suction Valve Noise | 03/95 |
| 1995MY Subaru Legacy DTC P0505 - Idle Control System Malfunction..... | 06/95 |
| 1995MY Subaru Legacy DTC P0325 - Knock Sensor Circuit Malfunction | 06/95 |
| 1995MY Subaru Legacy DTC P0130 - Front O2 Sensor Circuit Malfunction | 06/95 |
| Rough Idle on MPFI Vehicles | 07/95 |
| 1994MY Impreza ROM Sockets | 07/95 |
| DTC P0505 Idle Control System When Solenoid Measures 5w or Less | 09/95 |
| Extreme Cold Weather Engine Warm Up & OBD II | 12/95 |
| Loose Fuel Caps & Trouble Code P0440 | 07/96 |
| 1997MY Legacy Warranty Claims For Loose Fuel Caps | 09/96 |
| Legacy (Non Turbo), SVX, & Impreza ISC Valves | 09/96 |
| DTC P0440 & Legacy Fuel Caps | 11/96 |
| Blue Vs. Gray Connectors during Diagnosis | 11/96 |
| Extreme Cold Weather Engine Warm-Up & OBD-II | 11/96 |
| DTC P1500 Radiator Fan Relay One Circuit | 03/97 |
| 1997MY Subaru Impreza Outback Sport | 03/97 |
| Understanding P0440 | 04/97 |
| DTC P0507- Idle Control System RPM Higher Than Expected | 05/97 |
| DTC P0500 | 07/97 |
| Additional Information regarding Code P0440 | 07/97 |
| OBD-II Cylinder Misfire Codes | 08/97 |
| More P0440 Information | 10/97 |
| Exhaust Smell during Cold Start | 01/98 |
| Model Year 1998 Changes In P0440 Evap. Operation | 1/98 & 05/98 |
| DTC P0440 Revisited | 05/98 |
| DTC P0440 Tip | 11/98 |
| DTC P1507 | 11/98 |
| DTC P0705 Diagnostics | 05/99 |
| Freeze Frame Data | 08/99 |
| Evaporative System Diagnosis | 09/99 |
| OBD Readiness Codes | 11/99 |
| DTC P0440 1998/1999MY Forester | 1/99 |
| WXV-79 Engine Control Module Service Program..... | 11/00 |

11-Emission Systems

| | |
|---|----------|
| Freeze Frame Data | 05/01 |
| Ignition Coil Service Precaution | 01-02/02 |
| 2002MY Legacy Atmospheric Pressure Solenoid Valve Operation | 03-04/02 |
| DTC P1591 2002MY Impreza WRX M/T..... | 03-04/02 |
| C.I.D. Number for Reprogramming | 03-04/02 |
| WWG-90 Campaign Bulletin Correction | 08/02 |
| ECM Reflashing Claim Coding | 01-02/03 |
| Diagnostic Trouble Codes After WWK-94..... | 05/03 |
| ECM Calibration Identification Numbers..... | 05/03 |
| ECM Reflashing..... | 05/03 |
| Control Unit Reflashing Information | 07/03 |
| Diagnostic Trouble Code (DTC) Detecting Criteria..... | 08/03 |
| Rough Idle/Check Engine Light after Battery Disconnect | 09/03 |
| Evaporative Canister Rattle Noise in '04MY Impreza..... | 09/03 |
| ECM Reprogramming – A Reminder | 01/04 |
| 2004MY Legacy PZEV Vehicles | 04/04 |
| DTC P1507 on 1996MY-1999MY Legacy Vehicles | 04/04 |
| Updated Reprogramming Sheet | 05/04 |
| ECM Reprogramming Fax Forms..... | 09/04 |
| Freeze Frame Data | 09/04 |
| Air Fuel Ratio Sensor Kits..... | 12/04 |
| 2005MY & Reflashing..... | 12/04 |
| DTC P0171 | 04/05 |
| Updated Reprogramming Sheet | 08/05 |
| DTC P0171 | 09/05 |
| Freeze Frame Data & Calling the TechLine | 09/05 |
| ECU Reflashing | 10/05 |
| DTC P0715..... | 10/05 |
| DTC P0171 – 2006MY H4 Legacy/Outback | 11/05 |
| Throttle Sensor and Tumble Generator Valve (TGV) Sensors | 11/05 |
| DTC P2097 & Reflashing | 01/06 |
| 3.0L Models: Fuel Requirements Revised..... | 02/06 |
| DTC P0400 Diagnosis | 06/06 |
| DTC P1443 | 08/06 |
| DTC's & Reflashing..... | 09/06 |
| Clearing DTC's on 2005-2007MY SIA-Built Vehicles | 02/07 |
| Diagnostic Help for Evaporative System Codes | 04/07 |
| Reprogramming Reminder: Jumper Harness Connectors..... | 05/07 |
| DTC P0457 | 09/07 |
| DTC P1443 and the 2008 M/Y Impreza | 11/07 |
| Misfire Codes “Don't Forget To Check...”..... | 01/08 |
| Secondary Air Injection System Codes | 12/08 |
| WVH-18 & WVI-19 Service Program Information | 07/09 |
| “Rusty” Appearance of the Exhaust System | 05/10 |
| 2010 Legacy GT DTC P0171..... | 05/10 |
| TIPS on Inspecting DTC P0171 or P0172 | 07/10 |
| New 2011 M/Y Forester Evaporative System Testing | 12/10 |
| 2011 M/Y Forester: Sound From Under the Rear of the Car..... | 04/11 |
| Rust Stains on Stainless Steel Exhaust Systems | 06/11 |
| DTC P0457 Information | 07/11 |
| 2011 M/Y Forester, DTC P2610 | 10/11 |
| Troubleshooting DTC P0457 on 08 and Later Model Years..... | 02/13 |

11-Emission Systems

| | |
|---|-------|
| Getting to the Bottom of Extended Cranking..... | 03/13 |
| WQD-40 A Reminder..... | 04/13 |
| Repeat 420 Codes on High Mileage vehicles | 08/13 |
| More Information on Stainless Steel Exhaust System Surface Rust | 05/14 |
| Secondary Air Injection DTC's P2441 and P2442 | 07/15 |
| DTC P0171 Diagnostics..... | 07/16 |
| ELCM (Evaporative Leak Check Control Module) Self Testing for Diagnosis | 03/17 |
| DTC P0171 Diagnostics..... | 12/17 |
| DTC P1378- "Pre-Ignition Detected" – 2019MY Ascent..... | 07/18 |
| 2019MY Ascent: DTC P0606, Control Module Processor: Diagnostic Hints | 10/18 |
| 2015MY Legacy/Outback Seat Heater Operation Overview | 12/18 |
| Secondary Air Injection Diagnostic Trouble Codes P2441 and P2442 | 04/19 |
| ELCM Self Testing for Diagnosis..... | 10/19 |
| P04AE Diagnostic Issues for 2019-2020MY Ascent | 11/19 |
| DTC P0171 Diagnostics..... | 12/20 |
| EVAP System Smoke testing | 12/20 |
| DTC P0171 Diagnostics..... | 02/22 |
| Mode \$06 and CID/CVN Collection..... | 12/22 |
| EGR, EVAP & AVCS Readiness Monitors 21MY+ | 03/23 |
| A/F or O2 sensor contamination | 05/23 |
| Low Boost Pressue, WRX STi Only..... | 09/23 |
| P149X EGR Solenoid Valve Signal Circuit Malfunction..... | 09/25 |

12-Body, Glass, & Upholstery

12-Body, Glass, & Upholstery

| | |
|---|-------|
| Legacy Glove Box Rattling Noise | 05/91 |
| Wiper Blades | 08/91 |
| Legacy Sunroof Shade Servicing | 10/91 |
| Legacy Wiper Blade Improvements | 10/91 |
| Legacy Wind Noise | 03/92 |
| Legacy Modified Wiper Arms | 03/92 |
| SVX Glass Replacement | 04/92 |
| Legacy Upper Windshield Molding Loose | 05/92 |
| Door Glass Squeaks Going Up & Down | 11/92 |
| Windshield Wiper Maintenance Tips | 12/92 |
| 1992MY SVX Interior Noise Complaints | 08/93 |
| 1992MY SVX Sunroof sticking (Difficult to Open) | 08/93 |
| Customer Complaints of Whistle Noises | 12/93 |
| Seat Belts | 01/94 |
| 1993MY SIA Built Legacy, Headliner Droop | 03/94 |
| 1993MY Legacy SIA Built Legacy, Headliner Droop | 04/94 |
| Legacy Trim Item Characteristics | 04/94 |
| Legacy Door/Ignition Key Code Location | 04/94 |
| Sunroof Water Leak Diagnosis | 05/94 |
| Keys Plates | 10/94 |
| Door Lock/Linkage Inoperative | 11/94 |
| 1995MY Legacy Wagon Rear Cargo Anchors | 12/94 |
| 1995MY Legacy Power Door Locks | 12/94 |
| Foggy Film on Windows | 12/94 |
| 1995MY Subaru Legacy "Fluttering" Noise | 08/95 |
| Subaru Outback Front License Plate Mounting Kit | 10/95 |
| Winter Driving Tip, Interior Window Fogging | 01/96 |
| Foggy Film on Windows | 01/96 |
| Legacy Wind Noise | 02/96 |
| Water in the Rocker Panels | 07/96 |
| Loose Bolts on Window Regulators | 09/96 |
| Poor Drainage from Rocker Panels: 1995/96MY Legacy Models | 09/96 |
| '97MY Legacy Body Creaking Noise, RH Side Rocker Panel Area | 02/97 |
| Proper Operation of Seat Belts, ELR vs. ALR | 08/97 |
| New Cup Holder For '98MY Legacy | 11/97 |
| Replacement Wiper Blade Refills | 09/98 |
| Improper Driver's Side Window Operation | 10/98 |
| 1999MY Impreza Wind Noise | 01/99 |
| Bumper Cover Installation Tip | 02/99 |
| Front Seat Tracks | 04/99 |
| 1999MY Forester Radio Antenna | 04/99 |
| Tether Anchor Points 1995 – 1999MY Legacy Sedan/SUS | 07/99 |
| 2000MY Legacy Front License Plate Mounting | 09/99 |
| 2000MY Wiper Washer System | 09/99 |
| Upholstery Items – Repair/Replace | 10/99 |
| Forester Tailgate Squeaks/Rattles/Popping | 11/99 |
| Metallic Window Tint Films..... | 04/00 |
| Front License Plate Mounting For 2001MY Forester..... | 04/00 |
| Wind Noise/Crossbar Installation..... | 08/00 |
| Inoperative Windshield Washers..... | 02/01 |

12-Body, Glass, & Upholstery

| | |
|--|----------|
| WRX Aluminum Hood Precaution | 10/01 |
| 2002MY Impreza Sedan Trunk Lock Cylinder..... | 01-02/02 |
| Windshield Wiper Washer Connection..... | 11/02 |
| Sound Dampening Pad | 04/03 |
| Adhesive Residue on Painted Surfaces | 08/03 |
| Creaking Noise from Door Checker | 08/03 |
| 2003MY Forester Washer Nozzles | 09/03 |
| 2003-04MY Front Seatback Cover Reinstallation | 11/03 |
| 2001-02MY Forester Sunroof Leak | 11/03 |
| 2004MY Forester Rear Gate Damper Stay..... | 11/03 |
| Striker Color Change..... | 02/04 |
| 2003MY Forester: Water Leak from Roof Rail Clip | 03/04 |
| Forester Bumper Fastener Bolt Change | 03/04 |
| 2005MY Legacy Seat Belt Chime Activation..... | 08/04 |
| Seatbelt Reminder System Disablement | 08/04 |
| ODS Code 29 | 09/04 |
| Frozen Wiper Blades | 12/04 |
| Wiper Blades & Winter Weather | 01/05 |
| 2005MY Legacy/Outback Moon Roof Sunshade Block & Rod Assembly..... | 02/05 |
| B9 Tribeca Front License Plate Mounting | 04/05 |
| Wiper Blades & Visibility..... | 06/05 |
| Adhesive Residue On '06MY Forester Rear Tailgate Garnish..... | 07/05 |
| Wind Noise Diagnosis | 10/05 |
| VIN Plate Location Change | 10/05 |
| Wiper Blades – The Basics | 10/05 |
| 2006MY Impreza Tool Tray..... | 10/05 |
| Front Washer Nozzle Does Not Spray Properly | 01/06 |
| Ashtray Door Paint | 04/06 |
| 2005MY Legacy Repair Procedure of Overhead Console when the Lid is Hard to Open/Close..... | 04/06 |
| 2003~05MY Forester Sunroof Squeaks..... | 05/06 |
| 2004-2007MY Forester Sunroof Operation..... | 09/06 |
| Baja Factory Installed “Hard” Bed Cover Replacement Keys..... | 12/06 |
| Forester Rear Gate Handle Binding | 01/07 |
| B9 Tribeca Body “Popping-Type” Noise From the Right Front Strut Area..... | 01/07 |
| 2007 MY Legacy & Outback Overhead Console Door Binding | 04/07 |
| 2003-2008 MY Forester Sunroof Squeak | 04/08 |
| 2009 MY Forester Side View Mirror Torque | 05/08 |
| 2009 MY Forester Undercoated Wheel Wells | 06/08 |
| Rear Wiper Blade Refill | 05/07 |
| Impreza, Water in the Trunk | 03/07 |
| 2008 M/Y Impreza, Rattling Noise from the Right Front..... | 09/08 |
| 2009 Forester Buzzing or Rattling Noise from the Front Doors..... | 11/08 |
| Forester Sunroof Not Closing Properly | 11/08 |
| Subaru Genuine Wiper Blade Inserts..... | 01/09 |
| 2009 M/Y Impreza Rear Seat Updates | 02/09 |
| 2009 M/Y Forester Rear Combination Lamps | 03/09 |
| 2009 M/Y Forester Tailgate Grommet Removal..... | 03/09 |
| 2009 M/Y Forester Rattling Noise from Rear of Head Liner | 04/09 |
| 2010 M/Y Legacy & Outback Power Lumbar Support Operation..... | 09/09 |
| 2008-09 M/Y Impreza, Rattling or Vibration Noise from Right Front..... | 09/09 |
| 2009-10 M/Y Forester Rear Gate Creek..... | 11/09 |
| 2010 M/Y Outback Flapping or Fluttering Noise..... | 11/09 |

12-Body, Glass, & Upholstery

| | |
|--|-------|
| 2009-10 M/Y Forester Rear Seat Rattle / Squeak..... | 01/10 |
| Buzzing / Vibration Noises from Inside the Doors | 12/09 |
| 2010 Legacy / Outback Rattle From Overhead Console Area | 04/10 |
| Whistling Noise from Windshield Area at Highway Speed..... | 05/10 |
| Slow or Erratic Door Glass Operation..... | 05/10 |
| Stained Rocker Sill Moldings | 11/10 |
| Forester and Impreza Rear Quarter Glass Moldings | 01/11 |
| Bare Metal Visible in Tie-Down Areas of Undercarriage..... | 04/11 |
| Popping or Creaking Sound from L/Rear, 2010 M/Y Forester..... | 05/11 |
| Buzzing / Vibration Noises Inside the Doors, 2008 and Later Impreza..... | 07/11 |
| Windshield Cracks on the Inside..... | 07/11 |
| 2011 M/Y Forester, Rattling Noise from the Rear Roof Area | 10/11 |
| Heat-Damaged Plastic Parts..... | 10/11 |
| WV-32 Campaign, Cowling Clip Removal Tips..... | 10/11 |
| Windshield Cracks on the Inside, A Reminder | 11/11 |
| 2010-11 M/Y Outback "Popping" or "Tick" Noise from the "B" Pillar Area | 11/11 |
| 2012 Impreza Glove Box Light | 07/12 |
| Cleaning Spotted Window Glass | 07/12 |
| BRZ Rear Fold Down Seats | 07/12 |
| BRZ Protective Sun Visor Cover | 08/12 |
| A-Pillar Trim Tether Clips | 08/12 |
| Impreza Rear Package Shelf Rattling Noise | 09/12 |
| 2010 to 2012 Headliners..... | 09/12 |
| Removal of protective film on side sill plate cover 13 BRZ | 10/12 |
| 12 MY Tribeca Roof Rail..... | 11/12 |
| 09-13 MY Forester Rear Seat Reclining Button | 11/12 |
| 13 MY BRZ Rear Bumper Removal..... | 11/12 |
| Windshield Cracks on the Inside (Reminder) | 01/13 |
| WQA-37 Campaign (Special Pliers)..... | 03/13 |
| Melting Plastic Parts..... | 05/13 |
| BRZ Front Bumper Cover Removal Precautions..... | 01/14 |
| 2014 Forester Power Rear Tailgate..... | 04/14 |
| Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Cross trek..... | 06/14 |
| 2015 Legacy and Outback Seat Heater Overview | 08/14 |
| 2015 Legacy/ Outback Center Console Compartment Door Information..... | 09/14 |
| Design Change to the Zippers Used On Front Seat Backrest Covers..... | 09/14 |
| Rattle Sound from Right Side of Dash Area..... | 01/15 |
| Whitish Discoloration/ Deposits on Front Door Panels, 12MY and Later Impreza and Crosstrek 2015 WRX and STI | 01/15 |
| Fuel Door Freeze Up..... | 04/15 |
| Erratic Washer Fluid Level Warning Lamp Illumination | 09/15 |
| Glass Authorization Request-Additional photo required..... | 11/15 |
| 2015 Legacy/ Outback, Rattling Sound from Front of Vehicle | 12/15 |
| Interior Rear View Mirror Separation Reminder | 07/16 |
| Water Draining from Body Panels | 11/18 |
| Snowflake Type Damage to Glass | 01/19 |
| Cleaning Spotted Window Glass | 02/19 |
| 2019MY Ascent, Spare Tire Hoist Precautions | 05/19 |
| Rattle Sound from Steering Wheel Area | 02/20 |
| Ascent Wind Rushing Noise..... | 03/20 |
| 2019MY and up Forester- Airbag Warning Light Illumination Caused by the Use of Water and / or Glass Cleaner | 06/20 |

12-Body, Glass, & Upholstery

| | |
|---|-------|
| Water leaking into cabin from door trim all models and model years | 08/20 |
| Ascent Sunroof Frame Assembly..... | 05/21 |
| Rattle sound from driver side dash area..... | 06/21 |
| 2022MY BRZ Front and Rear License Plate Installation | 11/21 |
| Diagnosing Repeat P2762 and P2757..... | 07/22 |
| Accessory Catalog update..... | 01/23 |
| 20MY+ Legacy/Outback Manual Adjustment of Power Seat after Motor Failure..... | 01/23 |
| Condensation in Headlights and Taillights | 04/23 |
| Windshield Wiper Cowl Fitment Deformation | 06/23 |
| 24MY Legacy/Outback Carpet Seam..... | 03/24 |
| 2019 – 2024 Forester Rattle or Clicking Noise | 04/24 |
| Oily Residue on Inside of Windshield..... | 10/24 |
| Oily Residue on Inside of Windshield..... | 08/25 |

13-Paint

13-Paint

| | |
|---|-------|
| 3M Paint Polishing Assistance | 03/92 |
| '95MY Legacy Outback Paint | 01/95 |
| Correction to Service Bulletin 13-67-95r | 11/95 |
| Helpline Update | 01/96 |
| Water Spotting On Painted Surfaces | 09/96 |
| Paint Procedures for Subaru Bumpers | 08/01 |
| Trim and Paint Code Update..... | 04/04 |
| 2005MY Forester LL Bean Models Color Code Information Correction..... | 11/04 |
| Paint Discoloration in Wheel Opening Areas | 10/09 |
| Finishing Plastic Parts | 04/10 |
| XV Crosstrek Paint Schemes/Under Hood Insulator | 11/12 |
| Paint Condition on Hood – Moisture Stain..... | 12/18 |

14-Special Tools

14-Special Tools

| | |
|---|----------|
| Select Monitor Cartridge | 10/91 |
| 4EAT Valve Body Servicing | 12/91 |
| 4EAT Band Servo Servicing | 12/91 |
| System Check Units for '85MY, '86MY, and '87MY | 04/92 |
| SVX Select Monitor Cartridge | 04/92 |
| Select Monitor Repair | 08/92 |
| Air Conditioning Refrigerant Recycler | 08/92 |
| Special Tools for Rear Wheel Bearing Replacement on Legacy All-Wheel Drive Models | 09/92 |
| Select Monitor Cartridge Application Chart | 11/93 |
| Transmission Pressure Gauge Set | 03/94 |
| Select Monitor Repair | 11/96 |
| Subaru New Select Monitor Repairs..... | 07/99 |
| 2001MY Subaru Forester select monitor cartridge | 02/00 |
| New Select Monitor Repairs – An Update..... | 11/00 |
| New Select Monitor Cartridge..... | 01/01 |
| Subaru Fuel Injector Cleaner Tool | 05/01 |
| Select Monitor Cables..... | 10/01 |
| Select Monitor Image Loader Software/Hardware | 03-04/02 |
| Oxygen Sensor Removing Tool..... | 01-02/03 |
| 2003MY Impreza Select Monitor Cartridge Application | 01-02/03 |
| Select Monitor Repairs – An Update..... | 10/03 |
| 2005MY Legacy/Outback Key Cutter..... | 10/04 |
| Kent-Moore Website | 11/04 |
| Select Monitor Repairs: Latest Information..... | 03/05 |
| SDS (Subaru Diagnostic System) & Mode Files..... | 02/06 |
| SDS Kit & Pre-Testing Your Subaru Select Monitor III | 03/06 |
| Subaru Select Monitor III & CID Numbers..... | 03/06 |
| Updated Repair Center Phone Number for Kent-Moore..... | 06/06 |
| New Menu Prompts When Calling the SDS Technical Support Helpline..... | 07/06 |
| Mid-Tronics EXP-1000 | 08/06 |
| New Special Tool Kit SOA321064 Sent To All Subaru Dealers | 10/06 |
| Front Fender Insulator for WRX and STI (Excluding STI Limited)..... | 12/06 |
| Latest SSMIII Software Download Version | 03/08 |
| Re-Booting Your SDS Notebook..... | 04/08 |
| Latest SSMIII Software Download Version | 06/08 |
| SDS Notebook (CF-18) Helpful Hints..... | 07/08 |
| Latest SSM III Software Version Download | 09/08 |
| Legacy / Outback M/T High Idle Re-Flash Clarification..... | 10/08 |
| SSM III Pulse / Analog Kit (Oscilloscope) Information..... | 10/08 |
| Issues with Using SMART (Subaru LMS System) | 11/08 |
| Replacement Cables For Subaru Diagnostic System (SDS)..... | 03/09 |
| Fuel Alcohol Tester | 04/09 |
| Fuel Pressure Tester Warning from SPX | 09/09 |
| Select Monitor (SDS) Issues with Campaign WVM-23 | 12/09 |
| Important Engine Support Bracket Return Information | 04/10 |
| SDS Printer Problem... Who You Gonna' Call?..... | 06/10 |
| Techline Pre-Call Worksheets | 08/10 |
| CF-U1 Reprogramming Kit Monitor Use..... | 07/11 |
| Flashwrite Error Code 4404..... | 08/11 |
| Power Steering Rack Service Tool Information..... | 09/11 |
| Using the Service-Techline Reporting Feature on Subarunet..... | 09/11 |

14-Special Tools

| | |
|--|-------|
| Body Repair Manual User Information | 11/11 |
| 2012 Impreza Special Tool Shipments | 12/11 |
| New Snap-On Ball Joint Remover Instructions..... | 04/12 |
| Connecting Rod Bolts on FA and FB Engines | 09/12 |
| Printing Freeze Frame Data | 09/12 |
| Special Tools For The BRZ..... | 09/12 |
| Engine Bridge Replacement Parts | 11/12 |
| Test Harness Probes | 12/12 |
| Using Your Oscilloscope | 12/12 |
| SDI Interface Box and Self Shut Timer | 01/13 |
| 14MY Forester SSM3 Operation | 01/13 |
| SSM3 Unit Of Measurement | 08/13 |
| Subaru Special Tools Website URL Update | 01/14 |
| GR-8 Battery Testing Information | 03/14 |
| New SSM4 software on the C2 Toughbook..... | 06/15 |
| Recommendations for use of the Denso DST-I diagnostic interface..... | 09/15 |
| Stopper Tool for CVT and Automatic Transmissions | 11/15 |
| April 2016 SSM4 Changes | 04/16 |
| Precautions When Using the DST-I Box..... | 08/16 |
| New Function SSM4 October Version..... | 11/16 |
| SSM3? SSM4? Generic? What Diagnostic Scan Tool Should I Use?..... | 04/17 |
| New Special Tool – Relay Pliers | 02/18 |
| WUE-90 Stop Lamp Switch Recall, Special Tool Tip..... | 05/19 |
| False Error Message Displayed When Scanning 2019MY Impreza Sedan with SSM4 | 07/19 |
| Errors when Programming with Flashwrite® 2 | 02/20 |
| Special Tools - Denso USB Cable..... | 04/21 |
| Midtronics DSS-5000 Helpful Hints | 04/22 |
| Denso USB Cable & ECM/TCM Reprogramming | 07/22 |
| Changing Interface Settings for DST-i and DST-010..... | 11/22 |
| DST-010 Firmware Upgrade | 02/23 |
| Test Mode of SSM-5, Unable to Perform SSM5 Programming | 09/24 |

15-Accessories

| | |
|---|-------|
| Radio Display Interruption with Brake Pedal Application | 05/91 |
| Justy Radio Display Fade | 07/91 |
| SVX Security System | 10/91 |
| Legacy, Noise Heard Through Speakers When the Illumination Control Is Varied, Clarion Radio | 10/91 |
| Quick Cruise Control Check | 12/91 |
| SVX Radio Servicing | 12/91 |
| SVX Security System | 01/92 |
| SVX Compact Disc Player | 02/92 |
| SVX Security System Warning | 02/92 |
| Legacy Cruise Control Installation | 03/92 |
| Loyale Cruise Control for 92MY | 03/92 |
| L-Series Poor Radio Reception | 03/92 |
| L-Series Clarion 10 Watt ETR and Panasonic Elite LC Cassette Deck Incompatibility | 03/92 |
| Radio/Cassette/CD Exchange Or Out Of Warranty Repair Programs | 04/92 |
| Accessory Cruise Control Installation in Rural RHD Legacy Postal Models | 04/92 |
| Legacy Security System Wiring Information | 04/92 |
| 1992MY Legacy Cruise Control Installation | 06/92 |
| Loyale SOA386C110 Cruise Control Installation Tips | 06/92 |
| Legacy Station Wagon "LS" Power Antenna | 07/92 |
| Legacy Security System Installation 1991MY to Present Station Wagon Models | 07/92 |
| Loyale (SOA386C110) Cruise Control Installation Tips Correction | 07/92 |
| Tips for Installing Security System SOA386R100 in A 1992MY Loyale | 03/93 |
| Impreza IAC Formerly Called FICD Adjustment | 04/93 |
| SVX Audio Assembly Removal | 06/93 |
| 1993MY SVX New Security System Installation Tips | 08/93 |
| Legacy Panasonic 80 Watt Radio Noise in Speakers | 08/93 |
| Poor Radio Reception AM or FM | 10/93 |
| Legacy & SVX Security System Transmitter Battery Servicing | 10/93 |
| SVX New Security System Programming Tips | 10/93 |
| SVX Rear Speakers Buzzing | 01/94 |
| 1995MY Legacy Security System | 07/94 |
| 1995MY Legacy LSI Security System | 09/94 |
| Accessory Block Heaters | 10/94 |
| 1990MY-1994MY Legacy Security System Operation Q&A | 10/94 |
| Installing 1995MY Legacy Roof Racks | 11/94 |
| Impreza Accessory | 01/95 |
| Hubcaps | 01/95 |
| Accessory "Outback" Wheel Covers | 03/95 |
| 1995MY Subaru Legacy Front End Cover (Bra) | 03/95 |
| Installing Impreza Fog Lamp Kits | 03/95 |
| Cruise Control & the Use of the Select Monitor | 04/95 |
| 1995MY Legacy Cruise Control Corrections | 04/95 |
| 1995MY Legacy LSI Security System Module I/O Chart | 04/95 |
| 1995MY Legacy S/W Accessory Fork Mount Bike Carrier | 05/95 |
| Impreza Foglight Installation | 05/95 |
| Radio Noise | 06/95 |
| 1995MY Subaru Legacy LSI Alarm System | 06/95 |
| 1995 Subaru Legacy Cruise Control | 06/95 |
| Testing Cruise Control Pumps | 09/95 |
| Installation of Subaru Impreza 'LX' S/W Rear Spoiler | 09/95 |
| 1995MY Subaru Legacy with Panasonic Radios | 11/95 |

15-Accessories

| | |
|--|-------|
| 1995MY/1996MY Subaru Impreza & Legacy Cruise Control Applications | 11/95 |
| Alloy Wheel Center Caps | 12/95 |
| Impreza Fog Lamp Kit P. N. H4510FA100 Fuse Location & Wiring Changes For '96MY | 12/95 |
| Outback Trailer Hitch Part Number L1010AS000 Change In Torque Spec. | 12/95 |
| Cruise Control for 2.2 Liter '96 MY Impreza Manual Trans. Vehicles | 12/95 |
| Cruise Control for Newer Legacy Models | 12/95 |
| Legacy Remote Keyless Entry System | 12/95 |
| Legacy Keyless Entry Diagnosis | 01/96 |
| Legacy Accessory Keyless Entry System | 01/96 |
| Legacy Roof Rack Installation Information | 02/96 |
| Installation Instruction Supplement For '96MY Impreza Foglamp Kit #H4510FA100 | 04/96 |
| Interior Lights Stay On When Leaving the Car | 04/96 |
| 1995MY & Up Legacy LSI Keyless Remote System | 04/96 |
| Keyless Entry Erratic Transmitter Operation | 05/96 |
| Modification to Keyless Entry System Instructions | 05/96 |
| Revised 1996 1/2MY and 1997MY Legacy Cruise Control Supplemental Installation Instructions | 07/96 |
| 1995 & 1996MY Subaru Legacy W/Power Antenna | 08/96 |
| 1997 Legacy Keyless Entry | 08/96 |
| Legacy Outback Trailer Hitch Harness | 08/96 |
| Legacy Outback Crossbar Installation Tips | 08/96 |
| Legacy LSI Security System | 10/96 |
| 1996MY Impreza Accessory Keyless Entry Kit H7110FS000 | 01/97 |
| 1997MY Impreza Accessory Cruise Control | 01/97 |
| Outback Roof Rack Crossbar Bolt Part Number Correction | 01/97 |
| Legacy Subwoofer/Preamp, P/N H6300AS030 | 02/97 |
| Legacy Outback Trailer Hitch Wiring Harness | 02/97 |
| Legacy Keyless Entry with Security Upgrade | 02/97 |
| Correction to Installation Instructions for Keyless Entry Kits H7110AS000 & H7110AS300 For 1995MY & 1996MY Legacy | 02/97 |
| 1997MY Impreza Keyless Entry Kit H7110FS000 with Incorrect Wiring Harness | 02/97 |
| 1997MY Legacy Keyless Entry/ Security System Programming Button Locations | 02/97 |
| 1997MY Legacy Keyless Entry & Security Upgrade Modifications | 03/97 |
| Legacy Keyless Entry/ Security System Upgrade | 04/97 |
| 1997MY Impreza Foglamp Installation Tips For Kit #H4510FA200 | 05/97 |
| 1997MY Legacy; Programming Replacement Keyless Entry Control Unit | 07/97 |
| New CD Changer Installation Procedures | 08/97 |
| Forester Removable Antenna | 09/97 |
| 1996MY Subaru Legacy Keyless Entry System Not Operating Correctly | 09/97 |
| Subaru Keyless Entry Batteries | 09/97 |
| Accessory Gauge Pack Information | 10/97 |
| 1998MY Forester Keyless Entry System Information | 10/97 |
| 1998MY Impreza Cruise Control Connector | 01/98 |
| Keyless Entry System Operation | 01/98 |
| Forester Accessory Brush Guard | 01/98 |
| 1998 Impreza Foglight Kit #H4510FA200 | 02/98 |
| 1998 Subaru Forester Power Mirror Kit | 03/98 |
| Update of Keyless Entry Bulk Head Harness Change | 04/98 |
| Keyless Entry/Alarm System Upgrade | 04/98 |
| 1998MY Impreza Foglight Kit #H4510FA200/220 Correction | 04/98 |
| Subaru Keyless Entry/ Security System Reference Guide | 04/98 |
| Subaru Accessory Installation Manual | 04/98 |
| Programming SVX Alarm Systems | 04/98 |

15-Accessories

| | |
|---|----------|
| 1998MY Subaru Forester Power Mirror Kit P/N Correction | 05/98 |
| Legacy Station Wagon Audio Harness | 05/98 |
| Accessory Operator Instructions for 1999MY | 07/98 |
| 1999MY Legacy Accessory Changes and Corrections | 07/98 |
| Rear Differential Protector | 08/98 |
| Poor AM Radio Reception on Forester Vehicles | 10/98 |
| 1999MY Legacy Accessory Cruise Control | 11/98 |
| Keyless Entry/ Security System Transmitter Batteries | 01/99 |
| 1999MY Cal. Spec. Impreza Security Kit Availability | 01/99 |
| Shock Sensor Mounting for Forester/Impreza with Security Upgrade | 01/99 |
| Keyless Entry into 1999MY Forester Vehicles with 'All Weather Package' | 01/99 |
| Keyless and Security System Quality Improvements | 01/99 |
| 1999MY Forester Radio Noise/Poor Reception | 04/99 |
| 1999MY Forester – Clicking Noise from Right Front Speaker | 05/99 |
| Alpine Keyless Entry with Security Upgrade System Operation Reminder | 07/99 |
| Lighted Mirror Sunvisor Replacement Bulbs | 08/99 |
| No Radio Volume – 2000MY Legacy Limited Model Wagons | 08/99 |
| 1999MY/2000MY Legacy Alpine Keyless Entry/ Security System Dome Light Operation | 10/99 |
| Trailer Hitch Bike Attachment | 11/99 |
| 2000MY Legacy Rear Spoiler | 11/99 |
| Auto Dimming Mirror/Compass..... | 01/00 |
| Rear Gate Bar P/N E7510IS001 2000MY Legacy Wagons..... | 05/00 |
| Compass Mirror 2000MY Legacy & 2001MY Forester..... | 05/00 |
| Electrochromic Compass Mirror | 05/00 |
| Accessory Installation Instructions on Web | 05/00 |
| CD Player/Changer Visual Reference..... | 05/00 |
| Performance Gauge Pack Operation | 05/00 |
| 2000MY Legacy/Outback Hood Deflector 'W' Clips Installation | 07/00 |
| Replacing a Keyless Entry Transmitter Battery | 08/00 |
| 2001MY Forester Front Splash Guard Installation (P/N J1010FC000)..... | 08/00 |
| Accessory Block Heaters..... | 10/00 |
| Internal Trunk Release Handle | 01/01 |
| 2002MY Impreza Accessory Application – Compass Mirror | 03/01 |
| 2002MY Impreza Trailer Hitch P/N I1010SS000 | 03/01 |
| 2002MY WRX/Impreza TechTIPS Special Edition..... | 03/01 |
| Cross Bar Positioning..... | 05/01 |
| Short Throw Shifter | 05/01 |
| Accessory Updates..... | 07/01 |
| Titanium Shift Knob (P/N C1010FA100) Shift Emblem Location | 09/01 |
| WRX Performance Gauge Pack..... | 10/01 |
| Impreza Sedan Spoiler Installation Tips..... | 10/01 |
| Forester Splash Guard Installation Tips | 10/01 |
| WRX Steering Column Mounted Boost Gauge..... | 11/01 |
| 2002MY Impreza Subwoofer/Amplifier Compatibility..... | 11/01 |
| 2002MY Impreza Front Under-Spoiler Installation Change..... | 11-02/02 |
| 2002MY WRX Front End Cover | 01-02/02 |
| 2002MY Impreza 120 Watt Subwoofer Bracket Change..... | 01-02/02 |
| EC Compass Mirror Calibration | 03-04/02 |
| BAJA Bed Extender | 09-10/02 |
| Seat Heater Information | 03/03 |
| New Baja & Legacy Hood Deflector Installation | 03/03 |
| Impreza Sedan Spoiler Changes..... | 05/03 |

15-Accessories

| | |
|---|-------|
| Baja Bed Cover Replacement | 05/03 |
| STI Security Module Torque Specifications | 07/03 |
| Bumper Beam Plug for Baja Trailer Hitch..... | 07/03 |
| 2004MY Forester Hood Deflector/Protector | 08/03 |
| Tonneau Cover Replacement Parts For Legacy 00MY~03MY | 08/03 |
| 2004MY STI Single Turbo Gauge Installation/Intercooler Removal | 08/03 |
| Revised Electronic Control Compass Mirror..... | 08/03 |
| 2004MY Forester Single Turbo Gauge Installation/Interior Trim Removal | 08/03 |
| WRX STI Audio System..... | 08/03 |
| WRX Performance Suspension Kit (STI) | 09/03 |
| Baja Sport Activity Lights..... | 09/03 |
| Baja Sport Activity Lights - Relay Location..... | 01/04 |
| Forester Crossbar Design Revision..... | 01/04 |
| Baja Bed Cover Replacement (Reprint from May 2003) | 01/04 |
| Poor Radio Reception | 02/04 |
| Baja Sport Activity Lights – Relay Location – Correction | 02/04 |
| What’s That Noise? | 04/04 |
| Poor Radio Reminder | 04/04 |
| Cruise Control Actuator..... | 04/04 |
| Trailer Hitch Installation | 07/04 |
| '05MY Sedan Spoiler Template..... | 07/04 |
| '05MY Splash Guard Tape Area..... | 07/04 |
| '05MY Cargo Net Anchors | 07/04 |
| '05MY Legacy & Outback Hood Protector Mounting Points | 07/04 |
| 2005MY Legacy and Outback Crossbar Positioning | 07/04 |
| EC Compass Mirror Mounting..... | 07/04 |
| 2005MY Legacy & Outback Ambient Temperature Sensor | 07/04 |
| Subwoofer | 07/04 |
| Rear Cargo Net Pre-Arranged Drill Marks..... | 07/04 |
| Trailer Hitch Installation | 07/04 |
| Impact Sensor (Shock Sensor) Activation..... | 07/04 |
| Impact Sensor (Shock Sensor) Location..... | 07/04 |
| 2005MY Legacy/Outback H-4 & H-6 Model Relay Location | 07/04 |
| Sedan Spoiler Tether Location..... | 07/04 |
| 2005MY Key and Remote Transmitter New Vehicle Check-In Procedure | 08/04 |
| Non-Aero Cross Bar Kit | 09/04 |
| Sub-Woofer Wiring Harness Re-Routing | 11/04 |
| Engine Block Heaters | 11/04 |
| Immobilizer Information..... | 12/04 |
| Immobilizer Registration & Cell Phones | 12/04 |
| 2005MY Legacy Air Filtration Retrofit Kit..... | 04/05 |
| Don’t Get Alarmed..... | 05/05 |
| Keyless Remotes..... | 06/05 |
| 2005MY Legacy & Outback Air Filter Installation | 07/05 |
| Navigation Screen Removal for Subaru B9 Tribeca..... | 07/05 |
| B9 Tribeca Special Edition 2005 (Accessory Information) | 07/05 |
| Immobilizer Security Codes | 08/05 |
| False Shock Sensor Activation..... | 08/05 |
| B9 Tribeca False Alarm Activation..... | 10/05 |
| 2006MY Legacy/Outback Impact Sensor Installation..... | 11/05 |
| EC Mirror Configuration & Application | 01/06 |
| Auto-Dimming Compass Mirror (P/N H501SAG100) | 03/06 |

15-Accessories

| | |
|--|-------|
| 2006MY Forester Impact Sensor Adjustment..... | 03/06 |
| Forester Crossbar Noise | 04/06 |
| Keyless Entry Remote Inoperative | 05/06 |
| Navigation Display Illumination in Cold Weather..... | 05/06 |
| 2006 Immobilizer Component Replacement Guide | 07/06 |
| XM Satellite Radio Installation Instructions | 08/06 |
| Immobilizer Code Requests | 11/06 |
| “Teaching Codes” With an Immobilizer System..... | 11/06 |
| Special 2007MY Issue: B9 Tribeca Accessories | 12/06 |
| XM Satellite Radio “Re-Pinging” | 01/07 |
| Horn Beeps Erratically When Using RES System | 01/07 |
| NAV System Software Update Availability | 03/07 |
| Immobilizer Programming & RES Parts Information | 03/07 |
| Immobilizer Interface Programming | 03/07 |
| Remote Engine Start System- Start Attempt Failure | 04/07 |
| OnStar Analog System Phase-Out Information | 05/07 |
| 2007-08 MY Remote Engine Start Information | 07/07 |
| Remote Engine Start Programming Problems | 08/07 |
| Sirius Satellite Radio Diagnostic Flow Chart..... | 08/07 |
| 2008 MY Impreza Outback Sport & 5-Door Roof Rack Accessory Cross Bars..... | 09/07 |
| NAV / Aftermarket RES System Interference | 09/07 |
| Satellite Radio Diagnosis Quick TIP | 09/07 |
| Immobilizer “Invalid Teaching Code” Message..... | 10/07 |
| 2008 M/Y Impreza Accessory TIPS | 10/07 |
| Understanding the Security System Indicator Light | 11/07 |
| RES System “Quick TIPS” | 12/07 |
| More Immobilizer Helpful Hints | 01/08 |
| Tribeca Crossbar Rattling Noise | 01/08 |
| Erratic Horn Operation | 02/08 |
| Audio System Upgrades: XM / Sirius / iPod Interface | 03/08 |
| Important Information Regarding The iPod Interface..... | 03/08 |
| RES Troubleshooting Guides | 03/08 |
| Dealer Accessibility to Immobilizer Security and Key Codes..... | 04/08 |
| 2009 MY Forester Accessory Installation TIPS..... | 05/08 |
| Impreza Shock Sensor Installation..... | 07/08 |
| Immobilizer Teaching Codes, 2005-09, Breaking the Code | 07/08 |
| Remote Engine Start Troubleshooting Guides | 08/08 |
| 2009 M/Y Forester Wheel Arch Molding Installation Guide..... | 08/08 |
| 2009 M/Y Forester Puddle Light Connectors | 09/08 |
| Quick Tip: Hands-Free Installation, 2009 M/y Forester & Impreza | 09/08 |
| Are You NOT Hearing Voices?..... | 09/08 |
| Reminder: RES Kits Are Not Interchangeable..... | 10/08 |
| 2009 M/Y Forester Trailer Hitch / Arch Molding Information | 10/08 |
| iPod Interface Information, 2008-09 MY Impreza & 2009 M/Y Forester..... | 11/08 |
| Immobilizer Code / Subaru Lock Info Site (SLIS) Information | 11/08 |
| 2009 Forester Satellite Radio-Equipped Tuner Clarification | 11/08 |
| iPod Interface Charging Information | 12/08 |
| Back-Up Sensor False Alarms, 2008-09 Tribeca..... | 12/08 |
| Low Speaker Volume, 2008 M/Y & Later Impreza & Forester | 12/08 |
| Accessory Bluetooth “No Caller ID” Message | 02/09 |
| Audio / NAV Unit Removal Precautions | 03/09 |
| RES Antenna Ring Replacement Information | 04/09 |

15-Accessories

| | |
|--|-------|
| 2008-09 M/Y Impreza & 2009 M/Y Forester Wind Noise When Using Ski Carrier..... | 04/09 |
| Revised Impreza Roof Rack Crossbar | 05/09 |
| 2010 M/Y Legacy & Outback Keyless Entry Inoperative..... | 07/09 |
| 2010 M/Y Legacy & Outback Denso A/C Compressor Warning..... | 08/09 |
| iPod Charging Information | 08/09 |
| 2010 M/Y STI Satellite Radio Information | 09/09 |
| 2010 M/Y Legacy & Outback RES Reminders | 09/09 |
| 2010 M/Y Tribeca Radio Removal w/ Center Dash Speaker..... | 10/09 |
| 2010 M/Y Tribeca Back-Up Sensor Kit Applicability..... | 11/09 |
| 2010 M/Y Legacy Sedan Erratic Alarm Activation | 11/09 |
| Navigation Discs, There IS A Difference! | 12/09 |
| Teaching Codes... A Reminder | 01/10 |
| Remote Engine Start Programming | 01/10 |
| Remote Keyless Entry Fob Supersession | 02/10 |
| 2.5L Accessory Block Heater Installation Precaution | 03/10 |
| 2007 - 09 RES Performance Issues in Cold Weather | 03/10 |
| Electrical Problem? Check That Compass Mirror Harness | 03/10 |
| 2001 – 04H6 A/C Compressor Short-Cycling Reminder | 04/10 |
| Keyless Entry Inoperative After Starting Engine with RES..... | 04/10 |
| Decreased Radio Volume in Reverse..... | 05/10 |
| Satellite Radio Artist / Song Information Not Scrolling | 05/10 |
| Helpful Bluetooth Information and FAQ's..... | 06/10 |
| 2011 M/Y Legacy / Outback Bluetooth Microphone Inoperative | 07/10 |
| Excessive A/C Pressures | 07/10 |
| Remote Engine Start (RES) Troubleshooting Reminder..... | 07/10 |
| 2009 – 10 Forester 6 CD Changer Audio Unit Information..... | 07/10 |
| No or Reduced Sound from Rear Speaker Concerns..... | 08/10 |
| Thule Cargo Box Replacement Keys and Lock Cylinders | 08/10 |
| 2010 – 11 M/Y Outback Rocker Trim Removal..... | 08/10 |
| RES Service Kit Reminders..... | 09/10 |
| 2011 M/Y Impreza Bluetooth / Subwoofer Interference..... | 09/10 |
| Mobile Internet Installation Information..... | 09/10 |
| Media Hub Installation Reminder | 09/10 |
| TomTom Navigation System Information..... | 11/10 |
| Deformed Cargo Mats..... | 11/10 |
| 2011 M/Y Forester Block Heater Installation Instruction Change | 12/10 |
| Navigation “Hard Keys” Flashing / Screen Issues | 12/10 |
| RES System Key / Remote Registration Information | 12/10 |
| Kenwood Navigation System Troubleshooting Guide Released..... | 12/10 |
| Aftermarket GPS Signal Interference Issues..... | 12/10 |
| 2011 Legacy / Outback Revised Dash Speaker Grilles..... | 01/11 |
| Sunroof Motor Replacement Precaution..... | 01/11 |
| Updated RES and TomTom Troubleshooting Guides..... | 01/11 |
| Updated Subwoofer Harness Now Available | 02/11 |
| 2011 M/Y Outback Compass Mirror “Lock-Up”..... | 02/11 |
| No sound Heard When Using Bluetooth..... | 03/11 |
| No Sound Output from the Audio Unit..... | 04/11 |
| Crackling Sound from the Speakers w/ Key off..... | 04/11 |
| Radio Volume Changes by Itself While Driving | 04/11 |
| iPod Scrolling With TomTom Audio System | 05/11 |
| Block Heaters and DTC P0126..... | 05/11 |
| Panasonic Audio Unit Exchange Procedure Change..... | 06/11 |

15-Accessories

| | |
|---|-------|
| Tribeca Rear A/C Inoperative or Poor Performance | 07/11 |
| Rattling Noise from Right Side of Engine | 07/11 |
| Troubleshooting Guides on STIS..... | 07/11 |
| 2011 M/Y Impreza, Crank / No Start, Security Light Flashing | 08/11 |
| Bluetooth Connection Concern, Can You Hear Me Now? | 09/11 |
| Bumper Corner Molding Installation Information | 09/11 |
| Blank or “White Screen” Navigation Display..... | 09/11 |
| Use of Aftermarket Engine Under-Covers..... | 11/11 |
| Engine Block Heaters and DTC P0126 (Updated)..... | 11/11 |
| 2012 M/Y Impreza Immobilizer Changes | 01/12 |
| 2010-11 M/Y Legacy / Outback Bluetooth Inoperative | 01/12 |
| 2012 M/Y Impreza Audio Unit Exchange Information | 01/12 |
| 2012 M/Y Impreza Remote Engine Start Programming Information..... | 01/12 |
| Rear Seat Entertainment Troubleshooting and User Guides | 02/12 |
| 2010 and Later (Non-Interface) RES Diagnosis, Don’t Overlook This Step | 02/12 |
| 2012 M/Y Impreza RES Key Fob Flashing..... | 03/12 |
| Fujitsu-Ten Navigation Units and SD Cards- Important Information..... | 04/12 |
| 2010-12 M/Y Outback Cargo Mat Precaution..... | 04/12 |
| Revised Home-Link Mounting Adapter | 04/12 |
| Fujitsu-Ten Navigation Screen Display | 05/12 |
| 2013 BRZ Antitheft Security/Alarm System Activation..... | 07/12 |
| Push Button Start Vehicles Equipped With Remote Engine Start | 09/12 |
| Accessories and Eyesight | 10/12 |
| 2013 Smart Engine Start | 10/12 |
| Resources For XM Traffic Inquiries/Concerns | 11/12 |
| Bluetooth Information..... | 12/12 |
| 13MY Legacy/Outback Navigation Volume Adjustment..... | 01/13 |
| Wheel Locks..... | 01/13 |
| Voice Clarity | 03/13 |
| F-10 Diagnostics..... | 03/13 |
| Voice Recognition | 03/13 |
| 2014 Forester and 2013 Legacy Keyless Access and Keyless Entry | 05/13 |
| Navigation Voice Guidance | 05/13 |
| 2014 Forester Speaker Kit Installation..... | 05/13 |
| F-10 Audio/Navigation Units-No power or Display..... | 08/13 |
| Major RES (Remote Engine Start) Differences 2007 to 2014 | 09/13 |
| HomeLink Mirror Programming Information..... | 01/14 |
| 2010-14 Outback Rear Bumper Under guard Accessory Reminder | 03/14 |
| 2015 Legacy and Outback Keyless Entry Audible Signal Feature | 08/14 |
| 2015 Legacy/Outback XM Reverting to Preview Channel..... | 11/14 |
| 2015 Legacy/Outback, Starlink , iHeart Radio Application Information | 12/14 |
| Damaged USB Ports..... | 02/15 |
| Selectable Run Time for 2015 Remote Engine Start..... | 03/15 |
| Remote Engine Start (RES) Inoperative, No Response from Remote on Push-Button (Smart) Start Models | 05/15 |
| Use of Aftermarket Accessory Engine/Fuel Economy Monitors | 07/15 |
| Subaru STARLINK telematics Retailer PDI Process..... | 08/15 |
| Gen 1 F10 Navigation System-Red Light Alert Function..... | 08/15 |
| 2015MY Legacy & Outback, GPS Signal Loss w/F10 Navigation System | 10/15 |
| Accessory Floor Mat Reminders and Precautions..... | 11/15 |
| Accessory Bumper Cover/Installation Tips and Best Practices..... | 11/15 |
| Identifying Fujitsu-Ten Navigation Units | 11/15 |

15-Accessories

| | |
|---|-------|
| New F-10 Gen 2.1 Audio/Navigation System and Siri | 11/15 |
| Why Do My Outside Mirror Approach Lights Appear Green..... | 01/16 |
| Accessory Door Edge Guard Removal Process | 03/16 |
| Bluetooth Operation and Diagnosis | 04/16 |
| Clarion Audio Units and Audiobook CD's | 04/16 |
| Audio/ Navigation Head Unit Quick Reference Information | 04/16 |
| 2013 WRX or STI Special Edition Graphics..... | 05/16 |
| Door Edge Guards / Installation Tips and Best Practices..... | 05/16 |
| Auto Dimming and Home Link Accessory Mirror Wiring Harness Troubleshooting Reminder..... | 07/16 |
| Microphone Not Working? Check the Telematics System..... | 07/16 |
| 2017 Forester Telematics Fuse Change Information | 09/16 |
| Keyless Access with Push Button Start Vehicles-Erratic Beeping When Entering the Vehicle | 09/16 |
| Long Range Remote Start FAQ..... | 09/16 |
| RES Inoperative? Check the RES Antenna | 11/16 |
| Display Audio (Non Navigation) Clock Not Synchronized | 12/16 |
| No Back Up Camera After Radio Removal | 12/16 |
| Clock Settings | 12/16 |
| 2017 Auto-Dimming Outside Mirror Limited Movement..... | 01/17 |
| 2017MY Forester Wheel Arch Molding Installation | 01/17 |
| 2017 MY Impreza, Remote Engine Start (RES) Remote Fob Registration Tips..... | 02/17 |
| RES Hood Switch..... | 02/17 |
| 2017MY Impreza Audio Unit Stays Powered Up After Key Off ... Or Does It? | 02/17 |
| 2017 MY Impreza Remote Engine Start (RES) Time-out Function | 02/17 |
| 2017MY Impreza- Serial Numbers On Gen 3 Harman Audio Units..... | 03/17 |
| 2017MY Impreza Key Start RES Tips..... | 03/17 |
| Bluetooth Concerns?..... | 05/17 |
| Does this Accessory work with this car? | 05/17 |
| LED Lighting | 06/17 |
| Combination Meter Replacement | 07/17 |
| Eyesight Programming | 08/17 |
| Long Range RES Quirks..... | 08/17 |
| Eyesight Diagnostic Tips | 09/17 |
| Iphone Contact Options | 10/17 |
| Navigation and Head Unit Diagnosis | 10/17 |
| New Questionnaire for Harman Gen 3 Audio/Navigation concerns..... | 11/17 |
| Long Range RES Transmitter Programming | 12/17 |
| 2017 and Later Impreza, Inoperative Long-Range RES Remotes (Fobs)..... | 01/18 |
| Remote Engine Start Hood Switch Installation Review for 2017-2018MY Impreza/2018MY Crosstrek Models.. | 02/18 |
| Thule Roof Rack Wind Noise Complaints | 03/18 |
| 2017MY+ Impreza/Crosstrek (Turn Start) Remote Engine Start Registration | 04/18 |
| Remote Start Quick Reference | 04/18 |
| 2014-2018MY Forester, Rear-View Mirror Removal Helpful Hints..... | 05/18 |
| 2014 Keyless Access with Push Button Start Vehicles – Erratic Beeping when Entering the Vehicle..... | 05/18 |
| Air Conditioning Season is Here | 06/18 |
| Contact Pictures and Head Units..... | 06/18 |
| Harman Version 4 Application..... | 08/18 |
| DCM Information | 08/18 |
| Combination Meter Replacement | 09/18 |
| Fujitsu/Denso 10 iPhone Contact Picture Display – Update..... | 10/18 |
| Sirius XM List and Voice Tuning Concerns on Gen 2 & 2.1 Denso (D10) Audio Units..... | 10/18 |
| 2019MY Impreza/Crosstrek Remote Engine Start (Key Start) – Control Module Installation | 10/18 |
| Air Conditioning Leak Revisited | 11/18 |

15-Accessories

| | |
|--|-------|
| 2019 Forester Remote Engine Start Changes and Precautions..... | 12/18 |
| 2019 Impreza Sport Remote Engine Start Climate Control Settings | 12/18 |
| Reporting Inaccurate Navigation Map Data..... | 01/19 |
| Unexpected / Abnormal Stop While Operating Remote Engine Start | 01/19 |
| 19MY Remote Engine Start – Push Button Start | 02/19 |
| Use of Aftermarket Accessory Engine / Fuel Economy Monitors | 03/19 |
| Basic Diagnostics for Remote Engine Start (RES) Systems | 03/19 |
| Testing and Diagnosis of the Telematics Wifi Hotspot and Appointment Scheduler..... | 03/19 |
| How to End Speaker Output Check when Using SSM | 04/19 |
| Telematics Operational Concerns Accompanied by DTC B2A15..... | 05/19 |
| Harman Audio / Navigation System Concerns..... | 05/19 |
| Harman Audio Unit Phonebook Contact Limits | 07/19 |
| 2015 to Current WRX/STi Popping Sound After Installing Accessory Subwoofer..... | 07/19 |
| Updated Infotainment “Conditions” Information | 08/19 |
| Homelink Mirror Programming Information..... | 09/19 |
| Swapping Electrical Components: The Hardest Lessons Learned are Usually the Most Expensive | 09/19 |
| Telematics Subscription Error Codes 202 and 204..... | 09/19 |
| Telematics RES Feature Inoperative and Revised B2A16 Diagnostics | 09/19 |
| 2020 Legacy & Outback RES Fob Programming Procedure | 10/19 |
| 2020 Legacy & Outback Immobilizer Registration Process TSB 15-246-19R..... | 10/19 |
| Speed Volume Control | 10/19 |
| Updated Infotainment “Conditions” Information | 11/19 |
| 2020MY Legacy & Outback New Immobilizer Registration Procedures | 11/19 |
| 2020MY Legacy and Outback, DTC U0254 | 12/19 |
| Remote Engine Start (RES) Run Time | 03/20 |
| Review of and Additional DTC B2A15 Telematics Information | 04/20 |
| Updated Infotainment “Conditions” Information | 04/20 |
| Incorrect Operation of Audio Unit After Rockford Fosgate Upgrade Installation | 05/20 |
| A/C and Heat Conditions: Use of Recirculation / Recirc Button..... | 05/20 |
| DTC Code B2253 - Damaging a Speaker Coil due to the Electric Current to the Speaker Coil | 06/20 |
| Telematics – Attention to the Details Can Insure a Smooth DCM Replacement | 07/20 |
| Updated Helpful Infotainment Operational Tips..... | 07/20 |
| Remote Engine Start/ Power Rear Gate Inoperative on Push to Start Vehicles | 08/20 |
| Starlink App Soft Key Grayed Out | 11/20 |
| STARLINK Update – Retirement of the 3G Cellular Network | 12/20 |
| Wireless Phone Charging Accessory | 12/20 |
| Remote Engine Start (RES) – No Start After Registration, MY20+ Legacy/Outback or MY19+ Impreza/ Crosstrek (Key Start) | 01/21 |
| Homelink Mirror, No Operation with Key Off..... | 02/21 |
| Failed RES: Reference Error Code SER-4357..... | 02/21 |
| CP1 software version verification..... | 02/21 |
| Blind Spot Detection Disabled, No DTCs found | 03/21 |
| CP1 Panel and Steering Switch, Knob Switch Checks | 03/21 |
| Gen 4 CP1 Denso – Bookmark Feature | 04/21 |
| Roof rail usage/stowing on 2020+ Outbacks | 06/21 |
| Gen 2: Denso tech, SXM inoperative after updating..... | 06/21 |
| Gen 4: Denso CP1 Updating and initialization Screen reminder..... | 06/21 |
| Gen 4 Denso CP1 – Volume adjustment is not available, and audio is not playing after reboot | 06/21 |
| Gen 3, 3.1 and 3.1 alpha Harmon and Gen 4 Denso CP1 – Prevent Pandora application from automatically launching when connecting phone to vehicle | 07/21 |
| Gen 3, 3.1 and 3.1 alpha Harmon and Gen 4 Denso CP1 – Check for conflicting accessories prior to performing a software update via USB Port | 08/21 |

15-Accessories

| | |
|---|-------|
| Gen 3 Bluetooth streaming stuttering issue update AKA BT Skipping with Apple watch paired | 08/21 |
| Apple CarPlay Connections | 09/21 |
| 3G Sunset Video Announcement, STAR-U Training | 09/21 |
| Ascent Wireless Charger Installation, White Shifter Lever Rod Orientation..... | 09/21 |
| Auto Start Stop Inoperative or Automatically Disabled at Engine On..... | 10/21 |
| Aftermarket Accessories causing DTCs, Immobilizer concerns and Inoperative Systems | 11/21 |
| Harman Bluetooth voice commands and Contact Emojis | 11/21 |
| B2255 and B2256 misdiagnosis and Diagnostic changes..... | 11/21 |
| 2022 BRA Auto-Dimming Homelink Mirror Inoperative | 12/21 |
| DTC P0116 Setting with Engine Block Heater Use..... | 12/21 |
| 2022MY Forester, HVAC Gesture Control | 01/22 |
| GEOTAB, Fleet Tracking Device | 02/22 |
| Keyless entry Inoperative & Turn-Key Immobilizer Programming Inoperative, Similar Connectors..... | 02/22 |
| 2022 WRX CID Identification | 03/22 |
| Determining a Cockpit Information Display Failure | 03/22 |
| Poor Bluetooth Quality Concerns | 03/22 |
| Generation 4 Eyesight Camera Removal and Installation | 03/22 |
| The Telematics LED: When green does not mean GO..... | 04/22 |
| Charging Cables and Touch Screen Concerns..... | 05/22 |
| CP1 Navigation shows the wrong location | 05/22 |
| Harman 3.1 Base & Base+ Only, Ghost Image or Double Image..... | 05/22 |
| Importance of Inspecting for Aftermakret devices, Check the USB port & LEDs | 05/22 |
| Keyless Access Output Volume | 06/22 |
| Service Provider Software Information, Infotainment Portal | 06/22 |
| Version 4 Eyesight and Immobilizer Registration U1C00 | 07/22 |
| Telematics TSB/TechTIPS Quick Reference Guide..... | 09/22 |
| STARLINK App Soft Key Grayed Out Revisited | 10/22 |
| Starlink Telematics – Comm Check, Test Calls, Remote Service requests, Failed Calls..... | 12/22 |
| CP1.0/1.5 Software Version Verification | 01/23 |
| SXM Preset channel logo blank on CP 1.5 equipped vehicles, ‘23MY Outback/Legacy & Ascent..... | 01/23 |
| STARLINK App Will No Longer Be Supported..... | 02/23 |
| Eyesight Camera Replacement & Programming U1C00, U0146, B28A2, B28A1, U1P07, U1P08,U1C07, U1C08 | 04/23 |
| Fuel consumption widget “missing” on Denso CP 1.0/1.5 equipped vehicle | 05/23 |
| 24MY Crossterk/Impreza Wide Angle Mono Camera Cover Removal..... | 06/23 |
| Gen 4 Eyesight – Wide Angle Mono Camera Calibration..... | 06/23 |
| All Vehicles Equipped with CP 1.5, Auxiliary Port Noise | 07/23 |
| Microphone Troubleshooting | 07/23 |
| Repairing Starlink Telematics DTCs | 07/23 |
| Keyless Access with Push Button Start Vehicles – Erratic Beeping when Entering the Vehicle..... | 08/23 |
| After iOS 16.4 Software Update, Bluetooth Text Messaging Not Available, CP 1.0/1.5..... | 08/23 |
| Denso Gen 4 CP 1.0/1.5 Black or Blank Display..... | 08/23 |
| Wireless Phone Charging Accessory | 08/23 |
| EyeSight Cameras and Windshield Replacement..... | 09/23 |
| Clock Displays Incorrect Time | 10/23 |
| Starlink Telematics – Comm Check, Test Calls, Remote Service requests, Failed Calls..... | 11/23 |
| Microphone Inoperative, Telematics DCM Comm Check Failure & Starlink RES inoperative | 11/23 |
| EyeSight HALT Codes 41, A0 & CC..... | 11/23 |
| Unit Registration, Codes/DTCs After Replacing a Module, U1C00, U01046, B28A2, B28A1, U1P07, U1P08, U1C07, U1C08..... | 11/23 |
| Alarm Goes Off Randomly | 12/23 |
| Harman error message “Software download failed. Do you want to retry?” | 12/23 |

15-Accessories

| | |
|--|-------|
| “Registration Manual For Immobilizer” What is it? Where is it? | 12/23 |
| 2022MY Forester, HVAC Gesture Control | 01/24 |
| Eyesight Inoperative? Check Wiper Blades! | 01/24 |
| 2020MY – 2024MY Outback Trailer Hitch Installation L101SAN000 | 02/24 |
| Disabled Keyless Access Function | 02/24 |
| Telematics Repairs: Beyond Parts Replacement | 02/24 |
| Gen 4 Eyesight Course Adjustment NG 140B 140C | 03/24 |
| WHITE SHIFT LEVER ROD ORIENTATION..... | 04/24 |
| SXM Preset Not Saving | 04/24 |
| Crankshaft Position Sensor Plate Installation and P0336..... | 05/24 |
| Cockpit Information Display (CID) Diagnosis and Black Screen | 05/24 |
| Obtaining Map Update Activation Code | 05/24 |
| General Infotainment Troubleshooting | 06/24 |
| Side Window Deflector Installation | 06/24 |
| Navi Volume Inoperable CP1.0..... | 06/24 |
| APPLE CARPLAY CONNECTION..... | 07/24 |
| Level Up Your Telematics Service with Quality Monitoring Reports (QMRs)..... | 07/24 |
| Eyesight Aiming Completion and Automatic Adjustment Status..... | 07/24 |
| DCM Comm Checks Crucial in Massachusetts (MA) and Beyond | 08/24 |
| Microphone Inoperative, Telematics DCM Comm Check Failure, SXM Presets Inoperative and Remote Engine Start Inoperant | 08/24 |
| Antenna Wiring Test Plan | 09/24 |
| Checklist for One-Way Audio Complaint (caller cannot hear driver)..... | 09/24 |
| Bluetooth Connection, How Does It Work? | 10/24 |
| Gen 3 Telematics Valet Mode i-call Inoperative..... | 03/25 |
| New Solterra Connect..... | 03/25 |
| Phone Pairing Concerns..... | 03/25 |
| Poor Bluetooth Quality Concerns..... | 04/25 |
| Solterra Audio Unit White Screen..... | 04/25 |
| Solterra Telematics Re-enrollment After Subscription Expiration..... | 04/25 |
| MySubaru App Refresh..... | 05/25 |
| Homelink Mirror Identification..... | 06/25 |
| No Sound Output from Speakers..... | 07/25 |
| Eyesight Prohibited Areas..... | 08/25 |
| Head Unit Valet Mode Reset..... | 08/25 |
| Low Phone Battery Message..... | 09/25 |
| Know the difference between Comm Check, i-call, and Provisioning..... | 09/25 |

16-Automatic Transmission

16-Automatic Transmission

| | |
|--|-------|
| Metallic Noise on Light Acceleration- 4EAT Equipped Vehicles | 05/91 |
| 3AT Oil Strainer Screen Deterioration | 05/91 |
| 4EAT Slow Engagement | 06/91 |
| Legacy Transmission Oil Cooler Flushing | 06/91 |
| ECVT Transfer Cover Gasket/Erratic 4WD Dash Lamp Illumination | 06/91 |
| 4EAT Failure After Replacement of Reduction Shaft | 06/91 |
| FT4WD Binding On Corners | 08/91 |
| ECVT Main Drive Shaft Seal Ring | 09/91 |
| Justy ECVT Technical Information Supplement | 10/91 |
| Legacy A/T Oil Pump Cover Bolt Torque Clarification | 11/91 |
| A/T Pressure Checking Tip | 11/91 |
| A/T Thrust Bearing Identification | 01/92 |
| Justy ECVT Cable Adjustments | 01/92 |
| 4EAT Parking Pawl Campaign Full Time 4WD | 03/92 |
| 4EAT Planetary & High Clutch Parts (L-Series, Legacy, XT, SVX) | 06/92 |
| 4EAT Servicing & Repairs | 06/92 |
| 3AT Torque Converter Seal Failures | 06/92 |
| 4EAT Servicing | 07/92 |
| 4EAT Transmission Diagnosis Training Material | 07/92 |
| All Models with 4EAT, Pump Cover Production Change | 07/92 |
| Legacy ATF Filter Replacement | 08/92 |
| ATK-50 4EAT Filter Installation | 08/92 |
| Legacy and SVX 4EAT Torque Bind Complaints | 10/92 |
| Aftermarket Batteries | 11/92 |
| All Four-Wheel Drive Vehicles | 11/92 |
| Automatic Transmission Rebuilding | 12/92 |
| Justy ECVT..... | 12/92 |
| 4EAT All Wheel Drive Complete Unit Exchange | 01/93 |
| 4EAT Torque Converter Clutch Always Engaged Causing Engine Stall | 02/93 |
| 4EAT Auxiliary ATF Filter | 02/93 |
| 3AT (Lock-Up) Torque Converter Engagement on FWD Loyale | 02/93 |
| 1990-1993MY All Models With 4EAT Low Temperature Operation | 03/93 |
| Modified 4EAT Pump Gasket | 04/93 |
| 1992MY Legacy 4EAT ATK-50 VIN Range Clarification | 04/93 |
| Alternate ECVT Pulley Alignment Formula | 04/93 |
| 1990MY-1993MY All Models 4EAT Low Temperature Operation Correction to 03/93 Update | 05/93 |
| Legacy 4EAT Squeaking Noise from Torque Converter | 06/93 |
| Justy ECVT Valve Body Cleaning | 09/93 |
| Speedometer Cable Adapter on 4EAT Transmissions | 10/93 |
| Duty Solenoid "C" Swapping For Testing Purposes | 12/93 |
| 3 Speed Automatic Clutch Drum Wear | 01/94 |
| AWD Rear Axle Binding | 02/94 |
| Legacy Torque Converter Bolt Removal | 05/94 |
| High Clutch Seizure/Failure, SVX and Legacy Turbo Service Bulletin 16-58-94 | 05/94 |
| 3-Speed Automatic Differential Rebuilding | 05/94 |
| 4EAT Gasket and Seal Kit | 06/94 |
| 3AT Malfunction | 08/94 |
| 4EAT - No Movement in Any Gear | 09/94 |
| 'ATF Temp' Indicator Light – 1995MY Legacy | 09/94 |
| 4EAT Operation – 1995MY Legacy | 09/94 |
| 1995 Legacy with Apparently Non-Existent Codes From TCU | 10/94 |

16-Automatic Transmission

| | |
|--|----------|
| 4EAT Cold Weather Operation | 11/94 |
| 4EA Shift Problem Diagnostics | 12/94 |
| ECVT Loss of Line Pressure | 03/95 |
| 1995MY 4EAT Vehicle Noise | 05/95 |
| 1995MY Subaru Legacy/Impreza Shift Lock Diagnosis | 09/95 |
| 4EAT Low or Erratic Line Pressure | 09/95 |
| Repeat ECVT ECU Failures | 10/95 |
| Correct Axle Ratios | 11/95 |
| Over-Cautious November Update “Correct Axle Ratios” Information | 12/95 |
| 1996MY Subaru Legacy ATF Cooler Hose Re-Routing | 02/96 |
| Change In Configuration of 4EAT Pinion Shaft | 04/96 |
| 4EAT Delayed Engagement into Drive When Warm | 05/96 |
| ‘Manual Rom ID...Error 3’ | 05/96 |
| 4EAT AWD Extension Case Roller Bearing Removal | 07/96 |
| 4EAT Systems Diagnosis | 07/96 |
| 4EAT Transmission Binding In Turns | 08/96 |
| Late 1995MY & 1996MY Transfer Clutch Chatter | 09/96 |
| Limited Slip Additive | 11/96 |
| 4EAT Cold Weather Operation | 11/96 |
| 4EAT Speed Sensors | 04/97 |
| Checking Tire Pressures At PDI | 05/97 |
| Remanufactured Transaxle Program | 07/97 |
| Vehicle Engine RPM Goes To Zero When Coming To A Stop | 08/97 |
| 1998MY Subaru Impreza FWD Fuse Holder | 11/97 |
| Rear Axle Binding On Turns - (One More Time) | 01/98 |
| 1999MY 2.2L 4EAT Subaru Legacy Models Harsh Downshifting | 09/98 |
| 1999MY 4EAT Transmission Operation | 10/98 |
| Transmission Repairs or Replacements | 04/99 |
| Transmission Control Units (TCU) Part Numbers | 09/99 |
| 1999MY and Later (Second Generation 4EAT) Trouble Codes..... | 02/00 |
| 4EAT Torque Bind..... | 11/01 |
| Phase 2 4EAT (1999MY to Present) Repairs | 03-04/02 |
| 4EAT Remanufactured Transaxle Program – A Reminder | 08/02 |
| Remanufactured Transmission Paperwork Packets | 09-10/02 |
| 2003MY 4EAT Differential Drain Plug..... | 11/02 |
| 2003MY Legacy 2.5GT Sport Shifter Cold Weather Operation | 01-02/03 |
| Slope Control Change for 2003-2004MY Vehicles | 04/03 |
| 2004 Direct AT Control Valve Body Assembly Collection | 09/03 |
| (2004 Baja turbo and Forester turbo) Remanufactured Transmission Installations | 10/03 |
| Phase II 4EAT Stud Leak Repair..... | 11/03 |
| Procedures for Handling Returns/Claims – Remanufactured Transmissions | 03/04 |
| Phase 2 4EAT Transmission Characteristics – A Reminder | 05/04 |
| 2005MY Legacy & Outback AT Models Ring Indicator Removal | 08/04 |
| Transmission Information Worksheet | 08/04 |
| 5AT Transmission Removal/Installation Precaution | 08/04 |
| 2005MY Legacy/Outback AT Models Ring Indicator Removal – Revised..... | 10/04 |
| Inspection and Correction Methods of Connector T4/B11..... | 12/04 |
| T.S.B. # 16-67-04..... | 01/05 |
| Remanufactured Automatic Transmission Core Fluid Draining Process | 03/05 |
| WWV-06 Campaign | 04/05 |
| TCM Code 45 and the SSM III | 01/06 |
| Phase 2 4EAT Transmission Characteristics..... | 05/06 |

16-Automatic Transmission

| | |
|---|-------|
| 2004-2005MY Baja (4AT) Noise on Turns | 09/06 |
| Package Changes to Remanufactured Transmissions | 10/06 |
| 5A/T Remanufactured Transmission and “Learning Control” | 12/06 |
| Discontinuation of Spin-On ATF Filter | 08/07 |
| Direct Control 4AT Transmission Information..... | 08/07 |
| More ATF HP Fluid Information | 09/07 |
| Performing 5 AT “Learning Control” | 09/07 |
| 5 A/T Turbine Speed Sensor Precaution | 11/07 |
| DTC P0741 | 12/07 |
| Learning Control Procedure Applicability | 03/08 |
| 5AT Re-Manufactured Transmission Availability Announcement..... | 04/08 |
| Quick Tip: Don’t Forget To Do The Learning Control! | 01/09 |
| Legacy / Outback 3.0L 5 A/T Converter Bolts | 03/09 |
| DTC P1714 (4AT) TPS Power Supply Circuit | 03/09 |
| DTC P0712, AT Fluid Temperature Sensor Low Input, D4AT..... | 06/09 |
| 2010 M/Y Legacy & Outback Lineartronic™..... | 09/09 |
| 5AT Turbine Speed Sensor Reminder | 11/09 |
| “Binding on Turns” A Reminder..... | 12/10 |
| 4EAT Cold Weather Shift Characteristics Reminder | 01/11 |
| Servicing the CVT Front Differential Fluid | 02/11 |
| A/T Light Flashing but No DTC Stored (DTC P0712); Erratic Shifting Complaint..... | 03/11 |
| 2011 M/Y Tribeca 5A/T, Flywheel Cover | 11/11 |
| DTC P0890 “A/T Self-Shut Relay Diagnosis (Low)” | 12/11 |
| CVT Replacement Reminder..... | 01/12 |
| 2012 M/Y Impreza CVT Valve Body Replacement Information..... | 01/12 |
| A/T Shifting Concerns? Measure Those Tires! | 02/12 |
| Generation 1 CVT Transmission Servicing..... | 02/13 |
| CVT Torque Converters..... | 02/14 |
| Cold Weather CVT Operation, Engine RPM, and Cabin Heat..... | 04/14 |
| Automatic Transmission Fluid Usage Chart..... | 04/16 |
| Binding On Turns and Other Transmission Issues | 11/16 |
| CVT Fluid..... | 06/17 |
| Damaged Transmission and Front Differential Cases due to over-torque of fill/drain plugs..... | 09/17 |
| Allowable Repairs to CVT Assemblies | 10/17 |
| CVT Application and Generation Chart..... | 03/18 |
| Torque Converter Relearn | 03/18 |
| CVT Repairs | 09/18 |
| Service Manual Correction: Rear Transmission Crossmember/Transmission Mount Removal – Impreza and Crosstrek CVT Models | 10/18 |
| Vibration After Transmission or Engine Removal | 06/19 |
| 2020MY Legacy and Outback New CVT Fluid..... | 09/19 |
| Transmission Control Module (TCM) Freeze Frame Data (FFD) Block 2 | 06/20 |
| Automatic Transmission Fluid Types..... | 10/20 |
| Torque Converter Relearn | 11/20 |
| CVT Fluid Identification | 11/22 |
| DTC P1867 & P0867 | 05/23 |
| Diagnosing Repeat P2762 and P2757..... | 02/25 |
| CVT Remanufactured Transmissions..... | 07/25 |
| Send .SEPF instead of .CSV when requesting CVT assistance..... | 09/25 |

17-SRS Air Bag

17-SRS Air Bag

| | |
|--|-------|
| SVX (SRS) Supplemental Restraining System “Air Bag” | 01/92 |
| Legacy Models Equipped With Air Bag | 06/92 |
| 1989MY-92MY Passive Restraint Seatbelt System | 03/93 |
| 1993MY Legacy “SRS” Airbag Light Stays On | 04/93 |
| 1993MY Impreza “SRS” Airbag Light Stays On | 05/93 |
| Diagnostic Information for Subaru SRS Systems | 12/93 |
| Passive Restraints | 04/94 |
| Checking Air Bag Harnesses | 09/94 |
| Security System in 1994MY SVX with Dual SRS System | 10/94 |
| 1995MY Subaru Legacy Passenger SRS | 06/95 |
| Diagnosing SRS (Air Bag) Codes | 07/95 |
| Removal of Passenger’s Air Bag Module | 04/96 |
| Deployed SRS Air Bags | 06/96 |
| Passenger’s Side Air Bag | 11/96 |
| De-Powered Air Bags | 02/98 |
| All 1998MY Model Air Bag Applicability | 03/98 |
| Availability of Retrofit Air Bag ‘On - Off’ Switches | 08/98 |
| Subaru Vehicles Equipped with SRS Side Airbags..... | 08/00 |
| 10 Year SRS Inspections..... | 08/00 |
| Diagnosing SRS (Air Bag) Codes..... | 10/00 |
| Subaru Vehicles Equipped with SRS Side Airbags..... | 07/01 |
| 2002MY Impreza SRS Harness Change..... | 10/01 |
| 2003MY Forester SRS Codes 41 or 42..... | 07/03 |
| Air Bag Connector..... | 09/03 |
| Service Bulletin 17-09-04..... | 12/04 |
| SRS Codes 41 & 42..... | 03/05 |
| ODS DTC Code 28 – Spacer Kit..... | 04/06 |
| 2010 Legacy / Outback Seat Belt Twist..... | 03/10 |
| Front Passenger SRS Frontal Airbag (ODS) Indicator Light Information..... | 08/11 |
| WQA-37 Forester Rear Center Seat Belt Recall Supplemental Information..... | 04/12 |
| WUM-98 Supplier and Date Codes..... | 03/20 |
| SRS Air Bag, Rear Seatbelt Chimes | 10/21 |
| 19-22MY Ascent Airbag connector identification, DTC B1910..... | 11/22 |
| Airbag Test Harness Par Number and I/O..... | 02/23 |
| Rear Seatbelt Warning Light Inoperative..... | 08/23 |
| Load Sensor Locations B1791, B1792, B1793, B1794..... | 05/24 |

18-Service Manual Corrections

18-Service Manual Corrections

| | |
|--|-------|
| Legacy Knock Sensor | 09/91 |
| Service Manual Shuffle | 12/91 |
| Diagnosing SVX Trouble Code 37 O2 Sensor LH | 03/92 |
| Loyale Passive Restraint and 3-Point Seat Belt Timer Locations | 04/92 |
| XT6 Electronic-Controlled Motor Drive Power Steering Service Manual Supplement | 04/92 |
| Service Bulletin Manual Supplement Volume 12 Correction | 05/92 |
| 1992MY Legacy Service Manual Correction | 10/92 |
| 1995MY Subaru Legacy Service Manual Corrections | 03/95 |
| 1995MY Legacy Service Manual Revision | 07/95 |
| 1996MY Legacy Service Manual Supplement | 09/95 |
| Impreza Service Manual Supplement | 12/95 |
| Service Bulletin Manual & Service Helpline Update Supplement | 12/95 |
| 1998MY Impreza Service Manual | 11/97 |
| Copying Pages from Service Manuals | 03/98 |
| Correction to Subaru Forester Service Manual | 04/98 |
| Evaporative System Diagnosis T.R.B. Corrections | 08/99 |
| 2000MY Subaru Legacy & Impreza Service Manuals..... | 01/00 |
| Rear Wheel Alignment Specification Correction..... | 01/00 |
| 2000MY Subaru Legacy Service Manual Correction..... | 02/00 |
| Service Bulletin 13-74-00 Correction | 08/00 |
| Service Manual Corrections, 2001MY Forester and Legacy..... | 08/00 |
| Service Manual Correction 2001MY Legacy..... | 08/00 |
| Correction to Service Bulletin 10-70-00..... | 03/01 |
| Updated Service Manual Information | 02/11 |
| STIS: Help Us to Help You | 05/11 |
| WVX-34 Reminder..... | 01/13 |
| WQA-37 Information..... | 01/13 |
| Errors in Service Manuals, What to Do | 12/18 |
| Ascent Sunshade Reinitialization Procedure Clarification | 09/19 |
| C1532 Trouble Tree Correction | 09/19 |

19-Special Edition

| | |
|--|-------|
| Air Condition Season | 07/20 |
| Combination Meter Replacement | 09/20 |
| Escalation Process, Contacting Techline | 01/21 |
| Updates to Subaru-U | 04/21 |
| Transfer Clutch System Diagnostics Consolidated | 12/21 |
| Evaporative Diagnostics & Smoke Testing, ELCM Force test | 07/22 |
| Troubleshooting & Identifying USB Types with Techline Recommendations..... | 04/23 |
| Interactive & Retrievable Diagnostic Service Manuals (ISM)..... | 04/23 |
| Techline Case Submission Now Through Techshare | 07/24 |
| PHEV-SHEV-BEV..... | 08/25 |

20-EV (Electric Vehicle)

20-EV (Electric Vehicle)

| | |
|---|-------|
| Solterra DTC's Resulting from Service/Maintenance Activities: P0A1B1F, P0A1C1F, U113B87 | 08/22 |
| One-Time Use Brake Bolts | 09/22 |
| Solterra DTC's Resulting from Service/Maintenance Activities: P0A1B1F, P0A1C1F, U113B87 | 11/22 |
| Changing Interface Settings for DST-i and DST-010..... | 11/22 |
| Accessory Catalog update..... | 01/23 |
| Solterra Activity Mount Bumper Template part # PT97442230..... | 02/23 |
| Solterra Wheel Hanger | 03/23 |
| Solterra AC refrigerant check, use the scan tool! | 03/23 |
| Solterra Connect Telematics Diagnosis, DCM Activation & Registration..... | 04/23 |
| Solterra Front Camera Calibration..... | 06/23 |
| Towing a Subaru Revisited | 06/23 |
| Solterra Diagnostic Procedure for P15B071& B14FC71 | 06/23 |
| Solterra Power Windows Inop, Accessory Illuminated Sill Plates | 07/23 |
| Solterra Maintenance, "Bolts and Buts on Chassis" Torque Specification..... | 10/23 |
| Solterra Reverse Buzzer Setting Change..... | 11/23 |
| Solterra Connect Service Mode..... | 01/24 |
| Solterra "S Pedal Drive" Operation | 02/24 |
| How To Record GTS Data..... | 04/24 |
| Solterra ECU Update Process Change..... | 02/25 |
| Solterra Charging and Range..... | 02/25 |
| Solterra Post Component Installation Programming..... | 04/25 |
| GTS+ How to Change Live Data Time Duration..... | 04/25 |
| Solterra Vehicle Control History (RoB) Information..... | 07/25 |
| Dual Voltage Charging Cable Operation..... | 07/25 |
| Solterra Key Programming Process..... | 09/25 |