



## **SSM 54403 2021-2024 Bronco Sport, 2022-2024 Mustang Mach-E, 2022-2025 Escape, 2024 Maverick - Illuminated Powertrain Malfunction (Wrench) Indicator With DTC P0929 Stored In The GSM**

- \* 2021-2024 Bronco Sport built on or before 15-Dec-2024
- \* 2022-2024 Mustang Mach-E
- \* 2022-2025 Escape built on or before 22-May-2025
- \* 2024 Maverick vehicles built on or after 17-Jan-2024

Some of the above vehicles may exhibit an illuminated powertrain malfunction (wrench) indicator with diagnostic trouble code (DTC) P0929 stored in the gear shift module (GSM). This may be due to the software in the GSM. To correct the condition, reprogram the GSM module using the latest software level of the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 7P155 and labor operation numbers 7001D and 7001D4.