

Technical Information

FROM: Maserati TSO

TO: Maserati Network



Maserati

PERSONAL SERVICE LAB

MASTERS OF CARE

Coolant leakage from “Intercooler outlet sleeve” - Grecale MHEV

DATE: November 25, 2025

Coolant leakage from component “Intercooler outlet sleeve” (name of the PN in Technical Documentation)/ MIL light ON due to BSG failure (due to coolant contamination).

MODELS: M182 Grecale MHEV (All MY).

ACTIONS:

- New tightening and installation procedure for service now available on Technical Documentation (TechDocs) starting from 11/11/2025.
- Availability of new family of components (more resistant) expected for the first quarter of 2026.

Verify that the issue is confirmed and, if necessary, proceed with part replacement following the new procedure 1.71.304 on Technical Documentation.

Until the new family of components is available the only recommendation is to use the new assembly procedure.

We remain at your disposal for clarifications.

Best regards,

TECHNICAL SERVICE OPERATIONS