

# Driveline & Mid-Ship Bearing Vibration

## Topic Background:

- M2 midship shaft vibration and bearing failures at low mileage
- 47X/49X and Cascadia driveline vibration and midship bearing failures
- Repeat failures when shafts/bearing are replaced and installation is not changed from factory

## Topic Resolution Info:

- Dealers encouraged to submit DPRs to drive plant corrections caused by any assembly-related issues
- If there is a new issue, please work with your DSM to submit an FSR.

## Progress Updates:

- Will continue to monitor

## VISUALIZATION:

