

ECP (Electronic Control Pneumatic) Modules, possible water ingress

Topic Background:

- Affected models: Freightliner M2+ and Western Star 47X, 49X
- ECP devices can experience water/contaminant ingress into the core tube of the solenoids through the exhaust port

Topic Resolution Info:

- New O-ring piston solenoid assembly was released for service and production

Progress Updates:

- Fix as fail

