

X-Series HD Front Suspension Threaded

Topic Background:

- Affected models: 47X/49X Flat Leaf Front Suspension
- WST threaded bushings can bind/seize and move laterally within front spring eye/shackle bracket
- Audible popping noise during turning events
- Progressive damage to shackle bars, shackle brackets, front engine crossmember

Topic Resolution Info:

- 47X/49X Front Taperleaf Suspensions must be ordered with HD rubber bushings
- Flat Leaf suspension bushings alternatives are being tested/validated

Progress Updates:

- SS 734 published 12/20/2022

