


SUBJECT: TRUNK LID AND C-PILLAR GARNISH INSPECTION & REPLACEMENT (SA552)

	GROUP	MODEL
	BOD	2023-2024MY K5 (DL3a)
	NUMBER	DATE
	322 (Rev 2, 8/26/2024)	November 2023

**SERVICE ACTION: TRUNK LID AND C-PILLAR GARNISH INSPECTION & REPLACEMENT (SA552)**

**NOTICE**

**This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black margin area.**

This bulletin provides information to inspect the rear trunk lid chrome trim and C-Pillar(s) chrome garnish trim on certain 2023-2024MY K5 (DL3a) vehicles. The issue was first reported on September 29, 2023, which may be loose due to an insufficient curing delay. Follow the procedure outlined in this publication to inspect the rear trunk lid chrome trim and C-Pillar(s) chrome trims, and replace the affected trim on the left and/or right side C-Pillar(s) chrome trim on affected vehicles. Verify that the vehicle is included in the list of affected

**SA552**  
**SUPERSEDED TO**  
**SC346**



**NOTICE**

**A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.**

Repair status for a VIN is provided on KDealer+ (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on KDealer+ (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA552.

