



Service Bulletin

Bulletin No.: PIT6461

Date: November, 2025

PRELIMINARY INFORMATION

Subject: Assist Steps Lighting Inoperative or Flickers

Attention:

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500/3500	2026		All	All	All	All
GMC	Sierra 2500/350	2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	B3L BRS
Condition	Some customers may comment that the assist step lighting is not turning on when entering vehicle or unlocking vehicle using fob. They may also notice the lights flicker on for a second, then go off.
Cause	The cause of the condition may be software issue with running board lighting.

Correction

A software update for the K4 Assist Step Control modules will be released to correct this issue. Once this software is released, bulletin 25-NA-286 will be updated to include the 2026 model year and this PI will be removed.

Version	1
Modified	11/26/2025 — Created.

