

SOC Imbalance SMS

Your vehicle's range estimate is inaccurate. If you go below 20% state of charge, you'll notice a very fast range estimate drop that may impact your ability to get to your destination. There's

nothing wrong with your battery - this is a software calibration issue. Please install the 2025.38.30 software update. Installing it and charging your vehicle to 100% as often as possible for the next few weeks will recalibrate the system. To avoid the biggest range estimate drop, please stay above 20% SOC until the issue is resolved. We'll send you a confirmation once the calibration is complete. We apologize for any inconvenience. Call Rivian 24/7 at 855-748-4265