

Bluetooth Connection to Mobile Phone is Cancelled or Error Message "Emergency Call Faulty" in Instrument Cluster (90/25)

Model Line: **911 (992)**

Model Year: **As of 2022 up to 2025**

Equipment: **ECALL & BCALL (M-no. IW1 / IW3)**

Concerns: **External communication control unit**

Cause: **The customer complains that the Bluetooth connection with the mobile phone is interrupted and/or the message "Emergency call faulty, service necessary" is displayed on the instrument cluster.**

Action: Currently, a software solution is only available for the model lines in ongoing production. As soon as a software solution is also available for the vehicles listed in this technical information, this technical information will be updated accordingly.

Until the software solution is available, customer complaints must be resolved using **guided troubleshooting**.



Information

Component replacement will **not** work or provide a remedy in the case of this fault pattern.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.