

**This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.**

## Document Information

**Location:** Body Exterior / Electrical

**Topic:** Intermittent adaptive cruise control operation

**Condition:** N/A

### Diagnostic Trouble Codes:

B250097-28 : DTC\_SENSOR\_EXTERNAL\_DISTURBANCE\_BLINDNESS

B250A00-68 : DTC\_SENSOR\_EXTERNAL\_DISTURBANCE

## Measure

If you are experiencing intermittent operation for the Adaptive Cruise Control (ACC) please ensure the radar cover is free from obstruction.

You may have DTCs set for sensor external disturbance or blindness.

This could be obstructed by Paint Protection Film (PPF), dust, tape, glue, number plates or bumper protection.

Please remove any obstruction from the radar cover then retest operation to confirm usual functionality has resumed.

If there is no obstructions found on the radar cover please ensure the windscreen is also free from obstructions or films.

## Parts Information

N/A

## Attachments

N/A

## KA Update Information

05/11/2025 – Initial release

**This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.**