

WSR3 workshop campaign - check rear right side trim panel and replace if necessary

WSR3 workshop campaign - check rear right side trim panel and replace if necessary

ID Number	WSR3
Model(s)	911 (992)
Model Year(s)	2025 - 2026
Number of Affected VINs	59
VIN List	Attached
Issue Overview	On the affected vehicles, there is a possibility that the rear right side trim panel was not fully laminated. This does not meet specifications and might be considered a visual detriment by the customer. The rear right side trim panel must therefore be checked and replaced depending on the test result.
What Porsche Centers Should Do	During the next workshop visit, please arrange for this action to be carried out on the affected vehicles (At the time of posting 11/25/2025, remedy is immediately available)
TI	WSR3
Part Status	Status 1 - Order as needed

Warranty processing

Validity:

This workshop campaign will be carried out up to 04.12.2030 and will be closed by the specified date.

Please note that warranty claims can only be processed up to this date.

Scope 1: Checking rear right rear side trim panel

Damage Code	WRS3 66 000
Repair Code	1
Labor time	11 TU

WSR3 workshop campaign - check rear right side trim panel and replace if necessary

Scope 2 to 5: Check rear right side trim panel and replace if necessary

Damage Code	WRS3 66 000
Repair Code	2
Labor time	76 - 253 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.


Customer mobility

Not valid for Scope 1.

Mobility

If requested, mobility for the affected customer is to be ensured by offering a suitable replacement vehicle*.

- **Applies** to the period of the workshop visit
- **Invoicing** via the Customer Mobility programme, primarily Porsche models



Attachments

1. [WSR3 Workshop Campaign VIN List to Field Managers 11.25.2025 V3 HT.xlsx](#)