

WSJ0 Workshop Campaign – Update to software network VR28.13

WSJ0 Workshop Campaign - Update to software network VR28.13

Repair immediately available!

Please see dealer notice attached below!

ID Number	WSJ0
Model(s)	Macan (XAB)
Model Year(s)	2024 - 2025
Number of Affected VINs	11,140
VIN List	Attached
Issue Overview	Software optimizations are available for various control units for the Macan Electric. For this purpose, the control units must be reprogrammed using the Porsche Tester to the current VR28.13 software network.
What Porsche Centers Should Do	Please arrange for this measure to be performed immediately on the affected vehicles. As of the time of this posting (11/4/25) the repair is immediately available.
TI	WSJ0
Part Status	Status 0 - No parts needed
Customer Notification	To be posted later
FAQs	Attached below.

Campaign Exception for Punch Time Requirements: WSJ0

PCNA will make an exception to warranty policy regarding the necessary time keeping procedures when performing the following campaigns: WSJ0. Though warranty policy guidelines state that no technician may be punched on more than one R.O. at the same time, an exception will be made for the WSJ0 campaign.

Due to the extensive programming time necessary a technician may perform multiple WSJ0 campaigns at one time, **as long as there is a separate identifiable punch for each on the respective repair order and the total number of campaigns being performed at one time does not exceed 3.** The exception will be made so that full "active participation time" does not need to be documented for this campaign.

Important information on the baseline software hardware network and the integration test as part of a workshop campaign

Basis of the integration test:

- The test is carried out using the Porsche Tester based on the current baseline in the back end
- There is only one valid baseline per vehicle

What happens at a new baseline?

- Activation of new software/hardware releases
- Previous baseline becomes invalid
- New Porsche Tester release is provided at the same time

Test procedure:

- Vehicles are checked against the current baseline
- Porsche Tester displays affected control units in red when updating is required
- It is always necessary to update the control units

Important information on the workshop campaign:

- Campaign is only considered completed when all control units are displayed in green in the integration test

Attachments

1. [VIN_List_Report_WSJ0_2025-11-04_V3.xlsx](#)
2. [WSJ0_Dealer Note Campaign Execution V2.pdf](#)
3. [WSJ0_FAQs.pdf](#)