

GENERAL MOTORS
DCS7392
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 9, 2025

Subject: A252528630 - Service Update
Fuel Injector Flow Rate

Models: 2026 Buick Envista
2026 Chevrolet Trax

General Motors is releasing Service Update A252528630 today. The total number of U.S. vehicles involved is 799.

What Should Dealers Do: Dealers should review IVH, or the Dealer Maxis reports for open VINs in their inventory. Dealers can view the attached bulletin, and it will also be displayed in Service Information tomorrow.

The Stock VIN list of vehicles in dealer inventory or in-transit is attached to this message. Note: this list is only accurate at the time of report creation and all VINs should be validated in IVH prior to repair.

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

END OF MESSAGE

Service Update

A252528630 Fuel Injector Flow Rate



Release Date: December 2025

Revision: 00

Attention: This service update involves vehicles in dealer inventory only and will expire December 31, 2026.

Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Make	Model	Model Year	
		From	To
Buick	Envista	2026	2026
Chevrolet	Trax	2026	2026

This service update should be performed on vehicles in dealer inventory only. Investigate Vehicle History (IVH) in the GM Global Warranty Management system MUST always be checked to confirm vehicle involvement and MUST be in OPEN status prior to beginning any required inspections and/or repairs. DO NOT use Service Information with VIN search, as it will not verify the VIN eligibility for field actions.

Condition	On certain vehicles listed above, under certain driving conditions and due to differences in flow rate characteristics, the fuel injectors may not be able to properly optimize engine fueling.
Correction	Dealers will replace the engine's three fuel injectors.

Parts

Quantity	Part Name	Part No.
3	INJECTOR ASM-DIR FUEL	25207703
1	GASKET-CM/SHF CVR	55487546
1	PIPE ASM-FUEL FEED INTER	55490170
3	RETAINER-F/INJR	55492928
As Required	COOLANT	12346290 (US) 10953464 (CA) Obtain locally in compliance with GM spec GMW3420 for Dexcool concentrate and GM Spec GMW18270 for premix 50/50 Dexcool

If you have one of the involved vehicles, you must place a CSO order and add a SPAC case with the appropriate VIN. Due to limited inventory, VIN Verification will be conducted on the vehicle identification number you input and if it isn't an OPEN Recall in IVH then the order will be cancelled daily.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9108231	Fuel Injector Replacement (3)	2.5	ZFAT	N/A

Service Procedure

Replace the fuel injectors. Refer to *Direct Fuel Injector Replacement* in SI.

Service Update

A252528630 Fuel Injector Flow Rate



Dealer Responsibility

Dealers must take the steps necessary to ensure that the service update correction has been made to all involved vehicles in dealer inventory before selling or dealer-trading the vehicle, but no later than the end date as noted in the Attention box.

All new, used, GM Certified Pre-Owned (CPO), courtesy transportation vehicles, dealer shuttle vehicles, CarBravo, etc. in dealers' possession and subject to this field action must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Pre-Owned (CPO) vehicles currently in the dealers' inventory within the SHIFT Digital system will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the SHIFT Digital system, or once again be used in the Courtesy Transportation Program.

Dealer Reports – For USA and Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

