



# Service Bulletin

Bulletin No.: PIT6466

Date: December, 2025

## PRELIMINARY INFORMATION

**Subject:** Shimmy, Shake or Wobble When Leaving A Stop

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2025-2026		All	All	All	All
GMC	Terrain	2025-2026		All	All	All	All

<b>Involved Region or Country</b>	United States, Canada, Mexico, Middle East, Brazil (Mercosur)
<b>Condition</b>	A customer may have a complaint of a shimmy, shake or wobble during moderate acceleration in regular drive mode and sometimes in Low 2nd gear. This could be reported as a shake felt in the seat, floor, or steering wheel.
<b>Cause</b>	Engineering is currently working to root cause the issue.

### Correction

Once you confirm the issue is the same as what is described, advise the customer that engineering is currently investigating the issue and in the meantime please continue to drive your vehicle. Once a determination has been made, this PI will be updated or replaced with TSB.

**Note:** There are no long term durability concern with continuing to drive the car.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3080398*	Verify customer concern and advise it is being reviewed	0.3 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

<b>Version</b>	1
<b>Modified</b>	12/12/2025 Created on

