



STAR ONLINE PUBLICATION



Case Number: S2505000003

Release Date: December 2025

Symptom/Vehicle Issue: Diagnostic Trouble Code (DTC) C0050-00-Brake System Hydraulic Leak Set After Recent Repair.

Discussion: Prior to performing any further repairs, check the torque on all hydraulic components- lines, fittings, hoses. Refer to Service library 05 - Brakes / Technical Specifications TORQUE SPECIFICATIONS. Then follow pressure bleeding standard procedure; 05 – Brakes > 05-brakes, ABS > Standard procedure > STANDARD PROCEDURE – ANTILOCK BRAKE SYSTEM BLEEDING.

<<<**Note**>>>The pressure bleeder tank pressure when bleeding the antilock brake system on truck platforms is recommended to be between 40 - 50psi.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.