

Technical Service Bulletin (TSB)
Right Headlamp Not Properly Aimed

REFERENCE:	TSB: 23-044-25 GROUP: 23 - Body	Date:	December 12, 2025	REVISION:	—
VEHICLES AFFECTED:	2026 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or after October 24, 2025 (MDH 1024XX) and on or before October 26, 2025 (MDH 1026XX).			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to the North America markets.	
CUSTOMER SYMPTOM:	Customers may comment on the following: <ul style="list-style-type: none"> Right headlamp aimed too high. 				
CAUSE:	Calibration issue				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-248, date of issue December 12, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly adjusting the right front headlamp aim.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-34-9D	Right Front Headlamp - Inspect Alignment (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.
08-50-34-9E	Right Front Headlamp - Inspect and Aim / Adjust (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZY	Service Action	

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Is the right front headlamp aimed incorrectly?
 - YES >>> Proceed to [Step 2](#).
 - NO >>> Use Inspect LOP (08-50-34-9D) to close the active RSU.
2. Adjust the headlamp aim. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 08 - Electrical / 8L - Lamps and Lighting / Lamps/Lighting - Exterior / Standard Procedure.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.