



Service Bulletin

Bulletin No.: PIC6634

Date: December, 2025

PRELIMINARY INFORMATION

Subject: Incorrect Badging on Liftgate

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2026		All	All	All	All

Involved Region or Country	North America
Condition	Customer may comment that the rear badging around the tailgate is incorrect.
Cause	Incorrect rear badging was used when the vehicle was built.

Correction

Engineering is aware of the issue, and no repair attempts should be made at this time.

This PI will be updated or replaced with TSB once a determination has been made.

In the meantime, please advise customers that they may continue to drive their vehicle while waiting for the fix to become available.

Technicians are asked to verify the concern based on the photos below.

Correct badging: 700 E4



7036614

Incorrect badging: 500 E4



7036615

Version	1
Modified	12/15/2025 Created On.

