

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Interior Light Turns Off		Ref. No. TJ 37364.2.0	
Issuer (Dept.) Technical Service		Issue Date 11/13/25	Status Date 11/19/25
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 8500	
Function Description Interior furnishings		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*Added vehicle types

When the engine is turned off, the lights in overhead console, reading lamps, footwell, and luggage compartment may not turn on. This issue occurs intermittently, and during such instances, the ON/OFF button for the overhead console becomes unresponsive, follow advice under service.

CSC Customer Symptom Codes

Code	Description
JA	Passenger compartment lighting/Does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2024-2026		-	202317-202652
225							2024-2026		-	202317-202652
227							2024-2026		-	202317-202652
235							2024-2026		-	202317-202539
236							2024-2026		-	202317-202539
238							2024-2026		-	202317-202652
238							2024-2026		-	202317-202652
246							2024-2026		-	202317-202652
256							2024-2026		-	202317-202652
536							2024-2026		-	202317-202652
539							2024-2026		-	202317-202652

Technical Journal 37364.2.0

SERVICE:

Open the front driver side door, this will restore the interior lights.

*Work is ongoing, with the planned software release scheduled for the first quarter of 2026.

Warranty claim info:

No warranty claim is accepted for this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8500.