

SERVICE BULLETIN 638 – SPEED 400 & SCRAMBLER 400 X (US)

Subject: Measure and Replace Camshaft Drive Chain Tensioner			
Bulletin Number	Models Affected	VIN or Date Range	Markets Affected
638	Speed 400, Scrambler 400 X	Up to VIN A38716, plus list of individual VINs	All Markets

Dealers are requested to measure and replace camshaft drive chain tensioner the above VIN range as described in the procedure outlined in [Service Bulletin 638](#), found in the Technical Information section of TriumphOnline.net.

Reminder: use the "[VIN Enquiry](#)" function within TOL to search for any outstanding bulletins or recalls whenever a new bike arrives, during PDI, or when a Triumph owner visits your dealership.

Note:

- Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory.
- Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.