

 Preview Solution CBR-2535-1

Regeneration Not Possible P0475-72 - PR (4) - VN (4)

Published 9 December 2025

Valid For

Volvo Model - VN (4) with a TC engine

Mack Model - PR (4) with a TC engine

Model Year - 2024 to current

The purpose of this CBR is to address reports of regeneration failure when ambient temperature is below 30F.

Overview

There have been reports that some VN(4) and PR(4) with turbo compound engines failing to regen when the ambient temperature is below 30F and active fault code **P0475-72 Exhaust Pressure Control Valve "A", Actuator stuck open**. Please follow steps below:

Check if unit has latest service pack.

If there is a service pack available please update vehicle.

- A) If fault returns or no service pack available, diagnose using proper tools.
- B) If no fault returns release unit.

Related links and attachments

No links or attachments available



Share

to others that might find it helpful



Feedback

[Give feedback](#)

to help improve the content of this article