



## **SSM 54446 2025-2026 Expedition - Unintended Left Turn Signal Activation**

Some 2025-2026 Expedition vehicles may exhibit a left turn signal that activates after the right turn signal is activated and the steering wheel is turned to the right, then immediately back to the left (past the center position). The left turn signal will deactivate once the steering wheel returns to center. This may be due to the multifunction switch. Replacing components will not resolve this issue. Inform the customer that Ford is aware of the concern and engineering is currently working on a solution for this condition that is expected to be announced by March 2026. This concern does not affect vehicle durability and the customer can continue to drive the vehicle. Monitor Professional Technician System (PTS) for additional information and schedule a service appointment for the customer once the repair becomes available.